AIRCRAFT TECHNICAL LOGS

Section 1. AIRFRAME

AIRCRAFT

1.	Nationality and Registration	U.S.A. NI53TS
2.	Manufacturer's Designation	DA 42 NE
3.	Manufacturer's Serial Number	42.118
4.	Type Approval or Specification Number	ASTCE - U.S.A.
5.	Date of Manufacture	2006.
6.	Aircraft Inspection Cycle	MOOHR.

BROUGHT AND THE SECULATION OF THE SECURATION OF			DAILY														SINCE	ENGINEERING RECORD NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPL	
### 44 600 6 4 3 88 2 3PP : CYPL IGIP . BRR : CYPL 2021 ### 25 800 6 8 7 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 ### 31, 300 6 7 ACY : 36 3 3PP : CYPL IGIP . BRR : CYPL 2021 ### 15 tolowing additional work carried out by Diamond Aircraft Industries Inc. Service control Standard Ground and Country of the Part of the Air of th	DATE	HRS.	MIN.	HRS.	MIN.		_												
MAY 35, 360 8 . 3		-	-	23	.9	TIMES BROUGHT FORWARD AND TRANSCRICT	_												
MAY 35, 360.6 MAY 1, 360.3 Date: May 31, 2006 SIN 42 118 REG: N153TS TSN: 36.3 Hrs. WICO ROB-111 The following additional work carried out by Diamond Aircraft Industries inc. Service centre Dept. For fight feel sight enrous cannied out and IA.W. DAI GmbH work carried out by Diamond Aircraft Industries inc. Service centre Dept. For fight feel sight enrous cannied out and found to be satisfactory are required to the same of the carried out and found to be satisfactory are required to the same of the requirements for the requirements for the requirements of the same of the	MAY 24 2006	4	.3	28	.2	DEP: BGBW 1613. ARR: CYYR 2031													
Date May 31, 2006 St. 42.118 REG : N183TS TSN: 36.3 Hrs. W/O RO-05-111 The following additional work carried out by Diamond Aircraft Industries Inc. Service centre Dept. Ferry light hel lank removal carried out AIV. DAI cmbH work instruction W1 - OSB + 42 - 004 Rev. Odardé July 13, 2005 hence instruction W1 - OSB + 42 - 004 Rev. Odardé July 14, 2005 hence instruction W1 - OSB + 42 - 004 Rev. Odardé July 14, 2005 hence instruction W1 - OSB + 42 - 004 Rev. Odardé July 14, 2005 hence instruction W1 - OSB + 42 - 004 Rev. Odardé July 14, 2005 hence instruction W1 - OSB +		8	./	36	.3	DEP: CYYR 1219. ARR: CYXU ZUZ													
Date May 31, 2006 SN: 42.118 REG: N153TS TSN: 36.3 Hrs Win RO-06-11 The following additional work carried out by Diamond Aircraft Industries inc. Service centre Dept. Farty flight fuel tank ramoval carried out I.A.W., DAI GmbH work industries inc. Service centre Dept. Farty flight fuel tank ramoval carried out I.A.W., DAI GmbH work representation to the control of the contro		TA	4:	36	.3														
The following additional work carried out by Diamond Aircraft Industries inc. Service centre Dept. Ferry flight feel tank removal carried out by Diamond Aircraft Industries inc. Service centre Dept. Ferry flight feel tank removal carried out I A.W. DAI Gnibh work instruction Will - OSB - 42 - 004 Rev. 0 dated July 19, 2005 feen centre of the control of the contr			1 EL			** Diamond													
The following additional work carried out by Diamond Aircraft Industries Inc. Service centre Dept. Industries Inc. Service centre Dept. Fary flight ball tank removal carried out I.A.W. DAI GmbH work instruction Wil. OSB. 42 – 008 Rev. 0 dated July 19, 2005 hence revering the Aircraft inspraction of Good Grant Control (Aircraft inspraction of Good Grant Control (Aircraft inspraction of Good Grant Control (Aircraft inspraction inspection carried out to meet the querements for the issuance of a U.S. Standard Airworthness Certificate in accordance with PAR 2 1183 (C.) AVID Diamond Standard Airworthness Certificate in accordance with the general control of Good Grant Control (C.) AVID Diamond Aircraft meets the requirements for the certification in requested and have issued a (Standard) (Special) Airworthiness Certificate dated: DIAMOND AIRCRAFT HOUSTRIES INC. D. T. APPROVAL STANDARD (AIRWORTH) and Control of Good Grant Control of G						Date: May 31, 2006 S/N: 42.118 REG : N153TS TSN : 36.3 FIS. W/O RO-06-111													
Ferry flight fuel tank removal carried out I.A.W. DAL CmbH work instruction WI. OSB. 42 – 004 Rev. O Saled July 19, 2005 hence instruction WI. OSB. 42 – 004 Rev. O Saled July 19, 2005 hence instruction WI. OSB. 42 – 1004 Rev. O Saled July 19, 2005 hence instruction WI. OSB. 42 – 1004 Rev. O Saled July 19, 2005 hence instruction WI. OSB. 42 – 1004 Rev. O Saled July 19, 2005 hence instruction WI. OSB. 42 – 1004 Rev. O Saled July 19, 2005 hence instruction with substance of the requirements for the source of a U.S. Standard Almorthiness Certificate in accordance with FAR 21.183 (c). AVID Binevelley checked thru 2008-12 The maintenance described above has been performed in accordance with the applicable standards of almorthiness. DIAMOND AIRCRAFT INDUSTRIES No. D. O.T. APPROVAL #15.54 BOARD STANDARD STANDARD ROOM If find that this aircraft meets the requirements for the certification requested and have issued a (Standard) (Speciell) Airworthiness Certificate dated: DARYL I. MIDDLEBROOK Rederal Avaition Administration Designated Airworthiness Representative: DARTOSOOIOEA Plantmend Date June 07, 2005 SIN. 42.118 REG. N153TS TSN: 37.3 Hrs. WO RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy, Replaced with new unit, Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH M.C down lock indication switches rigged for provided the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH M.C down lock indication switches rigged for gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the DAMOND AIRCRAFT INDISTRIES No. D.O.T. APPROVAL #16.150						The following additional work carried out by Diamond Aircraft													
Instruction WI- OSB 42 - 2004 key a furnish and reversing the Aircraft to Standard configuration. Firel leak checked and reversing the Aircraft in Spandard Aircraft mode to establish or production of the establish and the statistic or production of the establish and the statistic or production of the statistic or the statistic or production of the statistic or productio						Form flight fivel tank removal carried out I A W. DAI GmbH work													
ground runup of the engines carried out and room to be requirements for the Aircraft importation inspection carried out to meet the requirements for the issuance of a U.S. Standard Airvorthiness Certificate in accordance with PAR2 1151 St.). AWD Biweetly checked thru 2006-12 The maintenance deached above has been performed in accordance with the applicable standards of airvorthiness. DIAMOND AIRCRAFT INDUSTRIES INTUSTRIES INDUSTRIES INTUSTRIES INDUSTRIES INTUSTRIES I	-	1				instruction WI - OSB - 42 – 004 Rev. 0 dated July 19, 2003 horizontal to Standard configuration. Fuel leak check and													
Issuance of a U.S. Standard Airworthmess Certificate in accordance with the APR 21138 (c). AWD Blweetky checked thru 2006-12 The maintenance described above has been performed in accordance with the applicable standards of airworthmess. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL \$155.93 Signature Bush and a proper standards of airworthmess of the certification requested and have issued a (Standard) (Speciety) Airworthmess Certificate dated: Of The next annual inspection is due: JARY I. L. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Representative: DARTOS0010EA Part I. MIDDLEBROOK Federal Aviation Administration Designated Airworthmess Part Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy, Replaced with new unit Installation of the switch carried out I.A.W. chapter 3c of the current DA 4. M. M. Both LH And RH MLG down lock indication micro switch assy including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthmess. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93	8	1				ground runup of the engines carried out and round to be satisfactory. Alease the importation importation carried out to meet the requirements for the													
AWD Biweekly checked thru 2006-12 The maintenance described above has been performed in accordance with the gapticable standards of ainvorthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL \$154.93 Signature Library Libra	-		1			issuance of a U.S. Standard Airworthiness Certificate in accordance with													
policial standards of airvortharPROVAL #151-93 DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #151-93			1	1	-	AWD Biweekly checked thru 2006-12													
policial standards of airvortharPROVAL #151-93 DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #151-93					1 2	The maintenance described above has been performed in accordance with the													
If find that this aircraft meets the requirements for the certification requested and have issued a (Standard) (Special) Airworthiness Certificate dated: The next annual inspection is due: DARYL L. MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down look indication micro switch assy, Replaced with new unit Installation of the switch carried out I.A. W. chapter 32 of the current DA 42 MM. Both LH And RH MLG down look indication switches rigged for groper contact on the rollers. Swear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDIVISES INC. D. T. APPROVAL #151-93 DAMOND AIRCRAFT INDIVISES INC. D. O.T. APPROVAL #151-93 DAMOND AIRCRAFT INDIVISES INC. D. O.T. APPROVAL #151-93				1		applicable standards of airworthiness.													
I find that this aircraft meets the requirements for the certification requested and have issued a (Standard) (Special) Airworthiness Certificate dated: O G The next annual inspection is due: DARYL L: MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. L H MLG down lock indication micro switch assy. Replaced with new unit. Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDIRES INC. D. O. T. APPROVAL #161-93 DIAMOND AIRCRAFT INDIRES INC. D. O. T. APPROVAL #161-93 DAADOND AIRCRAFT INDIRES INC. D. O. T. APPROVAL #161-93				1	1	Agend Revel . (ROB)	_(6)												
requested and have issued a (Standard) (Special) Airworthiness Certificate dated: 0 6 The next annual inspection is due: 7/107 Signed: 0ny Middle Arrowch DARYLL MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93 DIAMOND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93 DAROND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93			-			Signature Lic or Stamp	6												
requested and have issued a (Standard) (Special) Airworthiness Certificate dated: 0 6 The next annual inspection is due: 7/107 Signed: 0ny Middle Arrowch DARYLL MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93 DIAMOND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93 DAROND AIRCRAFT INDUSTRIES INC. D. O.T. APPROVAL #161-93																			
Certificate dated:																			
The next annual inspection is due: 7/ 0.77 Signed DARYL L. MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit. Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indications switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DASSIBLATION OF THE STANDARD OF				1															
Signed Dary L. MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches figged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D. O. T. APPROVAL #161-93 DARGOND AIRCRAFT INDUSTRIES INC. D. O. T. APPROVAL #161-93 DARGOND AIRCRAFT INDUSTRIES INC. D. O. T. APPROVAL #161-93				. "	100	7 7													
DARYL L. MIDDLEBROOK Federal Aviation Administration Designated Airworthiness Representative: DART950010EA Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit. Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA Signature August 2006 DA	The state of the s																		
Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DASSIBLE ADMAGNAGE ASSISTANCE OF A POSSIBLE ADMAGNAGE OF A POSSIBLE ADMAG	_				-														
Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit. Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. But H.M.G down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93		-	-			Federal Aviation Administration													
Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit . Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DAG DAG DAG DAG DAG DAG DAG DA	-					DART950010EA													
Date June 07, 2006 S/N: 42.118 REG: N153TS TSN: 37.3 Hrs. W/O RO-06-118 The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit . Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DAG DAG DAG DAG DAG DAG DAG DA				2															
The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept. LH MLG down lock indication micro switch assy. Replaced with new unit Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93	June 07, 2006	TA	2CH:	37	1.3.	**Diamond													
LH MLG down lock indication micro switch assy. Replaced with new unit . Installation of the switch carried out I.A.W. chapter 32 of the current DA 42 M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA DA DOB DOB DOB DOB DOB DOB						Date June 07 , 2006 S/N: 42.118 REG : N153TS TSN : 37.3 Hrs. W/O RO-06-118													
M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA DA DO DO DO DO DO DO DO DO						The following additional work carried out by Diamond Aircraft Industries Inc. Service Centre Dept.													
M.M. Both LH And RH MLG down lock indication switches rigged for proper contact on the rollers. Several Gear swings including Emergency Gear extension carried out and the system determined to function normal. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA DA DA DA DA DA DA DA DA D		1				LH MLG down lock indication micro switch assy. Replaced with new unit													
The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA DA DA DA DA DA DA DA DA D						M.M. Both LH And RH MLG down lock indication switches give a 42													
DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93						Droper contact on the follers. Several Gear swings including Face	The												
DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93	-		-			The maintenance described above has been performed in accordance with the													
Signature (POB)	-			37	.3	DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93													
						Cignature (PO6)													

NISSTS HOUSE 495,6

FAA Approved repair station QCCR389K Altimeter Scale Error Correction Card

TEST PY(FT)	Indicator Reading at +25c	TEST	Indicator Reading at +25c
-1,000	-980	30,000	
0	05	35,000	
500	520	40,000	
1,000	1020	45,000	
1,500	1520	50,000	
2,000	2020	55,000	
3,000	3020	50,000	
4,000	4020	70,000	
6,000	6020	80,000	
8,000	8020		
10,000	10000	a iraka	Altimeter
12,000	12000		Position
14,000	14000		Pilot .
16,000	15980	4	Copilot L
18,000	17980	1 4	
20,000	19980	ALT. S/N	1 42323

TEST	Reading at +25c
30,000	
35,000	
10,000	
15,000	
50,000	
55,000	
60,000	
70,000	
80.000	

Altime	tor
Positio	n
Pilot	
Copilot	1

578 457353 DATE 4-24-20

DOC# ECC123

22,000

25,000

FAA Approved repair station QCCR389K Altimeter Scale Error Correction Card

TEST PT(FT)	Indicator Reading at +25c	TEST	Indicator Reading at +25c
-1,000	-1980	30,000	
0	6	35,000	
500	500	40,000	
1,000	1000	45,000	
1,500	1500	50,000	
2,000	2000	55,000	
3,000	3000	60,000	
4,000	4000	70,000	
6,000	6000	80,000	
8,000	8020		
10,000	10020		Altimeter
12,000	12020		Position
14,000	14040	37 - 37	Pilot L
16,000	16020		Copilot
18,000	18020		
20,000	2002	ALT. S/N	478059
THE RESERVE OF THE PARTY OF THE	THE RESIDENCE AND ADDRESS OF THE PARTY OF TH		

DOC# ECC123

22,000


25,000

ALT. S/N 47805973 DATE 2-24-20

INSPECTION, REPAIRS & REPLACEMENT TRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.	SIGNATURE	LICENCE
	mylut pleans	RO6
GOOD FERRY FLIGHT LOGS.	Dent Heart	BO6 DA RO6
THES TRANSCRIBED FROM FERRY FLIGHT LOGS.	Ogleal Heard	HO6

						-
	CA		TION CARD METER			
P/N: 5934 F	0-3	C/N:	A 250	S/N	1: 4513	53
Standard Alt (Ft)	Alt Reading @ Room T		Standard Alt (Ft)		Alt Read	ding (Ft) n Temp
-1,000	- 10	8	14,000		-75)
0	- 5		16,000		- 60	
500	. 0	1	18,000		- 21	5
1,000	-5	C	20,000		-2	.0
1,500	0:		22,000			
2,000	7050		25,000			
3,000	1305		30,000			
4,000	7-10		35,000	-		
6,000	-35		40,000			
8,000	-60		45,000			
10,000	-70		50,000			
12,000	- 80	-				(8)
Date: \-5-6	Tested 1	By: 4	1	nspect	ed By:	U
FORM QA-A5 (B)				I	INITED INST	RUMENTS. IN

5 .. 0



lock indicatic he switch car And RH MLC on the roller carried out

pus

appli AIRCRAF ince describe

Installer must cross-check eligibility with approved data

	AIR TIME AND	
	AVIONICS OF MODERN AERO, INC	
***	14901 PIONEED ITALE	
	EDEN PRAIRIE, MN 55347	UIRED FOR COMPLE
DATE	952-941-2595	DIRED FOR SOME EL
DATE	FAA APPROVED REPAIR STATION 05VR353Y TOTAL: 126.4	
	DATE: 07/31/2000	Mark Charles
BROUGHT	Radio data IIIK	The second second
	Installed Garmin GDL69A and GASS XXIII of the Version 0370.14 per	
	receiver system. Upgraded of the straight A Welding and	The second of the second
	Garmin Software Service Bulletin in Sold See FAA Form 337 dated	
	balance and equipment list to the same	
	this date for further details.	Marine Laboration
	Avionics of Modern Acro, mo	
	CRS 05VR 353Y Frank Nook	
	AVIONICS OF MODERN AERO, INC	
	14801 PIONEER TRAIL	
	EDEN PRAIRIE, MN 55347 952-941-2595	
	THE STATE OF	
and the same	5 A T.C. 00/12/2006 10/18L. 10011	
	1410010	
	Removed defective Garmin GDL69A s/n 47755871 and replaced with	
	Removed defective Garmin GDL69A s/11 47755071 data representation in the second	
	tested satisfactory.	
	Avionics of Modern Aero, Ind	
	CRS 05VR 353Y Chad Morley	
	Ollad Wolley	
	MODERN AERO, INC.	
	14801 PIONEER TRAIL EDEN PRAIRIE, MN 55347	
	952-941-2595	
	FAA APPROVED REPAIR STATION MZER198L	De La Company
	N153TS DATE: 604-06 ACTT: 186.6	
	AIRFRAME MODEL: DA-42 S/N: 42.118	
		11 11 11 11 11 11 11 11
	INSTALLED NEW P/N D60-1127-10-52-1 R/H WING WALK.	
	INSTALLED NEW P/N D60-7806-10-00 EXHAUST TAIL PIPE ON L/H	
	ENGINE. SERVICED AND CHARGED AIRCRAFT BATTERY.	
	CAPACITY TEST ON BATTERY FOUND SATISFACTORY. COMPLIED	
	WITH MSB 42-021 BY REPOSITIONING EXHAUST TAIL PIPES FOR	
	PROPER CLEARANCE, REFERENCE MODERN, AERO W/O # 34482	
	KENFISCHBACH Kon Freshill	
	RENTIDENBACK Non REMINING	
		The second secon
		N. C.
	CARRIED FORWARD	
	J. T.	

TRIES.		MODERN AERO, INC. 14801 PIONEER TRAIL EDEN PRAIRIE, MN 55347		SIGNATURE	LICENCE
TRIES		952-941-2595 PAIR STATION MZER198L			NAT TO SERVICE
			ACTT: 195.0		
	NI53TS AIRFRAME	DATE: 10/13/06 MODEL: DA-42	S/N: 42.118		
			DE DESCRIPTION OF THE PARTY OF		
	COMPLIED WI	TH MSB 12-02-13 AND SI 42-03 TH NEW STEEL FITTINGS A	29 BY INSTALLING KIT		
	16022R2 HOSES	ACCORDING TO MSB 43-024/	3 AND SB TAE 125-0013.		
_	INSTALLED NE	W P/N RB-0700 INDUCTION ANGINES, INSTALLED NEW P/N	AIR FILTERS ON BOTH		
	TUBE MOUNT	NG PLATE ON R/H ENGINE.	INSTALLED NEW P/N		
	D41-5211-60-00. MODERN AERO	2 LATCH ASSEMBLY ON	CANOPY. REFERENCE		
			/		
	KEN FISCHBAG	H Ken Frechles	1		
				The View	
11. 2					
	N153TS AIRFRAME	DATE: 02/21/07 MODEL: DA-42	ACTT: 306.3 S/N: 42.118		ELT REPL
	TIPE D/N 156E 61-3 C/W N	R3 PU. REPLACED BOTH L/H AND R/I MSB 42-028 BY SEALING ENGINE ELE	CTRICAL HARNESS WITH SILIC	ON. C/W MSB 42-031 BY	Ħ
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 9 FOR FUEL RAIL, I CERTII	I-031, NO DISCREPANCIES FOUND WI NECK PER WI MSB 42-032/1. C/W MSB CH 506.3. C/W MSB 42-019/4 BY INSTA C/W MSB 42-030/2 BY INSTALLING ST FY THAT THIS AIRCRAFT HAS BEEN O TO BE IN AIRWORTHY CONDITION	TH THE LANDING GEAR: C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND GS ON THE RETURN LINE	N
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 9 FOR FUEL RAIL, I CERTII	I-031, NO DISCREPANCIES FOUND WI NECK PER WI MSB 42-032/1. C/W MSE CH 506.3. C/W MSB 42-019/4 BY INSTA C/W MSB 42-030/2 BY INSTALLING ST FY THAT THIS AIRCRAFT HAS BEEN	TH THE LANDING GEAR: C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND GS ON THE RETURN LINE	W N
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY	1-031, NO DISCREPANCIES FOUND WINECK PER WI MSB 42-032/1. C/W MSB CH 506.3. C/W MSB 42-019/4 BY INSTACTION OF THE THIRD STATE OF THAT THIS AIRCRAFT HAS BEEN OF TO BE IN AIRWORTHY CONDITION	TH THE LANDING GEAR. C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE.	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND GS ON THE RETURN LINE	W N
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY	I-031, NO DISCREPANCIES FOUND WI NECK PER WI MSB 42-032/1. C/W MSE CH 506.3. C/W MSB 42-019/4 BY INSTA C/W MSB 42-030/2 BY INSTALLING ST FY THAT THIS AIRCRAFT HAS BEEN	TH THE LANDING GEAR. C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE.	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND S ON THE RETURN LINE //TH AN ANNUAL	W N
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY	1-031, NO DISCREPANCIES FOUND WINECK PER WI MSB 42-032/1. C/W MSB CH 506.3. C/W MSB 42-019/4 BY INSTACTION OF THE THIRD STATE OF THAT THIS AIRCRAFT HAS BEEN OF TO BE IN AIRWORTHY CONDITION	TH THE LANDING GEAR. C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE.	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND S ON THE RETURN LINE //TH AN ANNUAL	W
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode	1-031, NO DISCREPANCIES FOUND WINECK PER WI MSB 42-032/1. C/W MSB CH 506.3. C/W MSB 42-019/4 BY INSTACTION OF THE THIRD STATE OF THAT THIS AIRCRAFT HAS BEEN OF TO BE IN AIRWORTHY CONDITION	TH THE LANDING GEAR. C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND S ON THE RETURN LINE //TH AN ANNUAL	2/11
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode	L-031, NO DISCREPANCIES FOUND WINECK PER WI MSB 42-032/1. C/W MSB CH 506.3. C/W MSB 42-019/4 BY INSTACK MSB 42-030/2 BY INSTALLING STORY THAT THIS AIRCRAFT HAS BEEN O TO BE IN AIRWORTHY CONDITION	TH THE LANDING GEAR. C/W M 8 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND SS ON THE RETURN LINE //ITH AN ANNUAL	2/11
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode NI53TS AIRFRAME REMOVED L/H AND R 7310-0473201 O DINGS	DATE: 6/28/07 MODEL: DA-42 WH FUEL FILTERS. INSTALLED 2 NEV	TH THE LANDING GEAR. C/W M 3 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F ACTT: 383.7 S/N: 42.118 V P/N 02-7310-04740R1 FUEL FILT PERFORMING WI-MSB-42-032 SE	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND SS ON THE RETURN LINE VITH AN ANNUAL TTT: 306.3 Ger #: 35224 GERS USING 2 NEW P/N OF THE MODERN AERO W/O #	2007
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. 0 FOR FUEL RAIL. I CERTII INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode NI53TS AIRFRAME REMOVED L/H AND R 7310-0473201 O DINGS	DATE: 6/28/07 MODEL: DA-42 WHE FILTERS. INSTALLED 2 NEV ATIONAL, AND LEAK CHECKS FOUND.	TH THE LANDING GEAR. C/W M 3 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F ACTT: 383.7 S/N: 42.118 V P/N 02-7310-04740R1 FUEL FILT PERFORMING WI-MSB-42-032 SE	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND SS ON THE RETURN LINE VITH AN ANNUAL TTT: 306.3 Ger #: 35224 GERS USING 2 NEW P/N OF THE MODERN AERO W/O #	2007
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. OF FOR FUEL RAIL. I CERTIL INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode NI53TS AIRFRAME REMOVED L/H AND R 7310-04732R1 O-RINGS 34898. RUN-UP, OPERA	DATE: 6/28/07 MODEL: DA-42 WHE FILTERS. INSTALLED 2 NEV ATIONAL, AND LEAK CHECKS FOUND.	TH THE LANDING GEAR. C/W M 3 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F ACTT: 383.7 S/N: 42.118 V P/N 02-7310-04740R1 FUEL FILT PERFORMING WI-MSB-42-032 SE	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND SS ON THE RETURN LINE VITH AN ANNUAL TTT: 306.3 Ger #: 35224 GERS USING 2 NEW P/N OF THE MODERN AERO W/O #	2007
	COMPLETING WI MSB 42 VENT HOLES IN FILLER 42-035, NEXT DUE AT TA T-FITTINGS P/N 6R6MX. OF FOR FUEL RAIL. I CERTIL INSPECTION AND FOUNI AARON MURPHY 2/21/2007 Mode NI53TS AIRFRAME REMOVED L/H AND R 7310-04732R1 O-RINGS 34898. RUN-UP, OPERA	DATE: 6/28/07 MODEL: DA-42 WHE FILTERS. INSTALLED 2 NEV ATIONAL, AND LEAK CHECKS FOUND.	TH THE LANDING GEAR. C/W M 3 42-035 BY PERFORMING PRESS ALLING NEW CHECK VALVES P/ 'AINLESS STEEL BANJO FITTING INSPECTED IN ACCORDANCE W 1 THIS DATE. Work Order #: 34898 A/F ACTT: 383.7 S/N: 42.118 V P/N 02-7310-04740R1 FUEL FILT PERFORMING WI-MSB-42-032 SE	SB 42-032/1 BY DRILLING URE TEST PER WI MSB N X11-0012-00-00.00 AND SS ON THE RETURN LINE VITH AN ANNUAL TTT: 306.3 Ger #: 35224 GERS USING 2 NEW P/N OF THE MODERN AERO W/O #	2007

DATE	7	DAI		TIME	L AIR SINCE	ENGINEERING RECORD NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLE	(
DATE		HRS.	MIN.	HRS.	MIN.	NOTE: SOL	-
BR	т					Samilees Inc - 1C5	
FO			6	A&MN	Aaintena	Ance Services, Inc. – 1C5 Airport, Bolingbrook, IL.	
					national	TACH TIME: 518.0 Hrs.	+
	TYPE:		OND DA	42		AIRFRAME T.T: 518.0 Hrs.	+
	"N" #: DATE:	N 153				Andreas	
						P/N I-6662019K03.	
	At this	time the	cabin heat	cable, fro	m control	arm to bellcrank, was replaced, P/N I-6662019K03. 127-10-52_1, wing walks were replaced. The left-hand 1 ASV, one check ok. The RH outboard fuel tank	+
	The LH	, D60-11	127-10-51	_1, and R	H, DOU-1.	12 14 SV and sheek ok. The RH outboard fuel tank	+
	was rer	laced, P	N D60-28	817-00-00	S4, ops c	0 1.AST, ops check of the New Houtboard main spar locking heck ok. The RH and LH outboard main spar locking he 0.0 71 Rev F. The LH and RH induction filters were	
	device	ubes we	re replace	d, 2ea P/N	DA4-570	0-00-71 Rev F. The LH and RH induction filters were	T
	replace	d, 2EA P	N RB-07	700, next r	placemer	at due in 200hrs at a total time of 718.0 Hrs. A seal was H cowl fins were repaired as needed. The RH main	+
	tire wa	o the can	d using a	Michelin 1	5x6.0-6/1	20, P/N 072-449-0.	-
	1		make the same of t	CAD	M	was of love voltage dear reliaction, was compared	
-						3-42-050-KIT, in accordance with Diamond OSB-42- OSB-42-050 Rev 2, dated Sept 10 2007. The backup	
	1		a for man a	compant in	1 3 / 3 / / 71 14	IN The Welding Mild Dalance was revised to the	+
	additio						-
						END	
		1	111	//			
	for	Cuff	Stall	1			-
	John :	Blaha	Jr. AP	2238954			
	0						
				1			
_							-
				A 8.	M Moint	enance Services, Inc. – 1C5	
				Clow I	nternatio	nal Airport, Bolingbrook, IL	
	TYPE	: DIA	MOND D				
-	"N" #	: N1:	53TS			TACH TIME: 569.1 Hrs. AIRFRAME T.T: 569.1 Hrs.	1
	DAT		1/2008				-
	At thi	s time, th	ne aircraft	was inspe	cted and h	abed in accordance with an Annual Inspection per	1
	Diami	JIIU SCIV	ice ivianua	us. The L	H and KH	Sien oring were replaced. The DII	
						072-449-0. The wheel bearings were cleaned and 111-0006-00-000/2, S/N: 0279 was removed and a new	1
							L
-	perfor	med. Th	e gear was	s cleaned a	s needed	The page goesters will be refrection and emergency extension test was	-
-							
	nacky	vas renla	/N: LCR	12-V 1.3P	and next	due in 12 months. The emergency lithium battery	1
	battery	was ser	viced and	charged 7	he FI T	model ME40 Cal coace	1
	accord	ance with	FAR 91.	207(d)(1-	4). The ba	interior is due for replacement Feb 2011. The TKS	
	reservo	ir screen	was remo	oved, inspe	cted, clea	ned, and installed. The co-pilot window seal was	1
-	replace	d P/N: 5	12AF,			ned, and installed. The co-pilot window seal wasCONTINUED	1
							1
			1		1		M
					1		1
							1
						CARRIED FORWARD	-

		MIA JATOT	Malak	LICENCE
TRIE	INSPECTION, REPAIRS & REPLACE ES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LIT		SIGNATURE	NUMBER
-				
				1 1 1 1 1 1
				7.1
-				
-				
-				
	A & M Maintena	nce Services, Inc. – 1C5 Airport, Bolingbrook, IL		
	TYPE: DIAMOND DA42	TACH TIME: 569.1		
	"N" #: N 153TS DATE: 03/11/2008	AIRFRAME T.T: 569.1	Hrs.	
	Diamond MSB-42-043, on replacement of ailer aileron bellcranks and rod ends in accordance we and checked for proper rigging - found within literated by the best of the best o	with WI-MSB-42-043 with P/N: MSB-4 mits. estallation, does not apply by aircraft se	erial number.	
	I certify that this aircraft has been inspected in a determined to be in an airworthy condition.	NDaccordance with an Annual Inspection	and was	
	Alley Blekel			
	John J. Blaha Jr. AP 2238954 IA			
	AF 2238934 IA			
1				

TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 04/24/2008 At this time, the RH and LH fuel filters were replaced. The nose strut was serviced with nitrogen to the proper extension. The Co-Pilot firesh air window latch was installed as needed. The cabin heat cable was adjusted for ease of travel. END Tokin J. Blydra Jr. AP 223/9534 I certify that the Altimeter/s and Static system tests required by FAR 91.411 have been performed in accordance with FAR 43. Appendix E. Static System Test Date Mork Order 2008-040 Signed Alt Reporting System Tested to 20,000 ft. Date 05.01/2008 Work Order 2008-040 Signed Alt Reporting System Tested to 20,000 ft. Date 05.01/2008 Work Order 2008-040 CRS#UOHR009X HELICOPTER SPECIALTIES, INC. 4746 S. Columbia Drive Janesville, WI 53546 Emery Air, Inc. Emery Air, Inc. Emery Air, Inc. 12 May, 2008 HRS: 617.7 FAA Approved Repair Station No. E81R759XIEASA.145.4811	Z mare	A & M Maintenance Clow International Ai	rport, Bolingbrook, 112	EQUIRED FO	R COMPLE
At this time, the RH and LH fuel filters were replaced. The nose strut was serviced with nitrogen to the proper extension. The Co-Pilot fresh air window latch was installed as needed. The cabin heat cable was adjusted for ease of travel. END Certify that the Altimeter's and Static system tests required by far 31, 11 have been performed in accordance with FAR 43, pependix F. I certify that the ATC Transponder Tests and Inspection required by FAR 91, 411 have been performed in accordance with FAR 43, pependix F. Initiation of the Company	"N" #: N	AMOND DA42 153TS	TACH TIME: 598.9 Hrs. AIRFRAME T.T: 598.9 Hrs.		
Certify that the Altimeter/s and Static system tests required by AR 91.411 have been performed in accordance with FAR 43, ppendix E. tatic System Test Date 05/01/2008 It Reporting System Tested to 20,000 ft. Date 05/01/2008 It Reporting System Tested to 20,000 ft. Date 05/01/2008 Signed CRS#UOHR009X HELICOPTER SPECIALTIES, INC. 74746 S. Columbia Drive Janesville, WI 53546 Signed System System System Tested to 20,000 ft. Date 05/01/2008 It Reporting System Tested to 20,000 ft. Date 05/01/2008 Signed CRS#UOHR009X HELICOPTER SPECIALTIES, INC. 74746 S. Columbia Drive Janesville, WI 53546 Signed System Sy	_ At this time,	the RH and LH fuel filters were replace sion. The Co-Pilot fresh air window lat for ease of travel.	CII Was about the	the	
AR 91.411 have been performed in accordance with FAR 43, opendix E. Static System Test Date	- John J. Bland AP 223895	Blaling a Jr.			
AR 91.411 have been performed in accordance with FAR 43, opendix E. attic System Test Date					
Appendix E. Static System Test Date 05/01/2008 O5/01/2008 O5/01/2008 O5/01/2008 Oscale Osca			by I certify that the ATC Transponder 3, by FAR 91.413 have been performe	Tests and Inspection requ d in accordance with FAI	ired
CRS#UOHR009X 4746 S. Columbia Drive Janesville, WI 53546 DA 42 N153TS Hawker Beechcraft Authorized Service Center WO: PT 22022 S/n: 42.118 Greater Rockford Airport-Rockford, IL 61109 HRS: 617.7	atic System Test Date_ timeter/s Tested to2 t Reporting System Test	0,000 ft. Date 05/01/2008	Appendix F. Unit S/N 89101869 Date 05/01/2 Signed Low M.	2008_Work Order <u>2008-0</u> CRS#UOHR009	040
DA 42 Emery Air, Inc. 12 May, 2008 N153TS Hawker Beechcraft Authorized Service Center W0: PT 22022 S/n: 42.118 Greater Rockford Airport-Rockford, IL 61109 HRS: 617.7	gned Ja Mo ELICOPTER SPECIAL		4746 S. Columbia Drive		1
N153TS Hawker Beechcraft Authorized Service Center WO: PT 22022 S/n: 42.118 Greater Rockford Airport-Rockford, IL 61109 HRS: 617.7	nesville, WI 53546				
N153TS Hawker Beechcraft Authorized Service Center WO: PT 22022 S/n: 42.118 Greater Rockford Airport-Rockford, IL 61109 HRS: 617.7	DA 42			12 May, 2008	
TATAPPIOTOL ROPAL STATES TO LEGIT STATES TO THE	N153TS	Greater Rockford	Airport-Rockford, IL 61109		
Aircraft weighed in closed hangar using Roadrunner scales, 30057 s/n: 483. New Basic Empty Weight 2925 Lb (1328 Kg) C.G. 94.64 ln (2.404 M)		Aircraft weighed in closed hang	ar using Roadrunner scales, 30057 s/n: 483.		

Approved for Return to Service With Respect to the Work Performed EMERY AIR INC.

Greater Rockford Airport, Rockford, IL 61109

F.A.A. Approved Repair Station No. E81R759X/EASA.145.4811

TRIES. DRAW	A & M Mainte Clow Internation	al Airport, Bolingbrook, IL.		MBE
The state of the s	TYPE: DIAMOND DA42 "N" #: N 153TS	TACH TIME: AIRFRAME T.T:	711.3 Hrs. 711.3 Hrs.	1
	DATE: 10/03/2008	And remain		
	At this time the LH aux fuel pump trans	fer switch was replaced, P/N 19	98-8507. The LH	
	and RH wing walks were replaced, LH	P/N D60-1127-10-51 I and KI	H P/N D00-1127-	
	10-52_1. All brake linings were replaced were replaced, 2ea P/N RB-0700, next to	replacement due in 200hrs. The	nose gear torque	
	link hardware was tightened as needed.	The nose strut was serviced wi	th nitrogen.	
	1. 1. 1.			
	Saluf Bleling			
	John J. Blaha Jr. AP 2238954			
	JAI 22,0554			
				173
-				
	A & M Mainte	nance Services Inc - 1C5		
		nance Services, Inc. – 1C5 al Airport, Bolingbrook, IL.		
			711.3 Hrs. 711.3 Hrs.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008	al Airport, Bolingbrook, IL. TACH TIME: AIRFRAME T.T:	711.3 Hrs.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0	TACH TIME: AIRFRAME T.T: ce protection was accomplished 054a. The airplane flight manual	711.3 Hrs.	
	TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was pro-	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual c. No. 7.01-05E. A copy of crovided for insertion into DA42	711.3 Hrs. In accordance with I was updated with maintenance	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was premanual. Aircraft placards were verified a	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of the rovided for insertion into DA42 and found to be correct. Aircra	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be	
	TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was pro-	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the id Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was proportion of the identity	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was pr manual. Aircraft placards were verified a operated per Diamond Aircraft DA42 ai	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the id Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was proportion of the identity	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was presented by the company of the comp	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was presented by the company of the comp	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	
	Clow Internation TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 10/03/2008 At this time, an operational test of the ic Diamond AMM-TR-OAM-42-053a & 0 Diamond Aircraft Supplement S03, Doc AMM-TR-OAM-42-53a & 054a was presented by the company of the comp	TACH TIME: AIRFRAME T.T: the protection was accomplished 054a. The airplane flight manual 2. No. 7.01-05E. A copy of covided for insertion into DA42 and found to be correct. Aircrairplane flight manual, supplement.	711.3 Hrs. I in accordance with I was updated with maintenance ft can now be nt S03.	

A & M Maintenance Services, Inc. - 1C5 DATE OR COMPLET Clow International Airport, Bolingbrook, IL. 761.8 Hrs. TACH TIME: **DIAMOND DA42** TYPE: BROUG AIRFRAME T.T: 761.8 Hrs. "N" #: N 153TS DATE: 01/21/2009 At this time, the ECU backup batteries were replaced using Panasonic 12V 7.2Ah/20hr, 4ea P/N LC-R127R2P1. A functional test of the electrical system was conducted in accordance with WI-OSB-42-050 line 42. John J. Blaha, Jr. AP 2238954 A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42 TACH TIME: 787.8 Hrs. N 153TS AIRFRAME T.T: 787.8 Hrs. DATE: 04/14/2009 At this time, the aircraft was inspected and lubed in accordance with an Annual Inspection per Diamond Service Manuals. The wheel bearings were cleaned, inspected, and greased. One bearing, P/N 08125-2629, and race, P/N 08231-2629, were replaced on the nose wheel assembly. The LH main tire was replaced using a Goodyear FSII 15x6.0-6/120, P/N: 156-E61-3. The nose wheel was replaced using a Goodyear FSII 5.00-5 10ply, P/N 505C01-2. A gear retraction and emergency extension test was performed, no defects noted. The landing gear and wells were cleaned and lubed. The nose gear torque link hardware was inspected and tightened. The landing gear power pack and the brake reservoirs were serviced. The brakes were checked and found within limits. The rudder "S"-slides were lubed. The LH jack point base was replaced, P/N DV2-1200-00-02. The flap wells were cleaned. The TKS reservoir screen was cleaned and inspected. The cabin heat control arm inner cable was replaced. The excitation batteries were replaced 2ea, P/N: LCR 12-V 1.3P and is next due in 12 months. The emergency lithium battery pack is due for replacement March 2010. The aircraft battery was serviced and charged. The ELT model ME40, S/N: 00460, was inspected and tested in accordance with FAR 91.207(d)(1-4). The ELT battery is due for replacement Feb 2011. AD2008-23-08, effective 12-22-08, on engine mount bolts, was complied with by replacement of bolts with wire secured bolts, referencing WI-MSB-42-058, as terminating action using MSB-42-058-KIT. No further action required. Diamond MSB-42-070, on nose gear pivot assembly, was complied with by inspection, no gap noted, next inspection due in 100hrs at a tach time of 887.8hrs. -----CONTINUED CARRIED FORWARD

A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL

DIAMOND DA42 787.8 Hrs. TACH TIME: "N" #: N 153TS -ICENCE AIRFRAME T.T: 787.8 Hrs. NUMBER DATE: 04/14/2009 RIES. DRA Diamond MSB-42-062/2, on downlock pin replacement, complied with action 2 of this bulletin by installation of improved pins using MSB-42-062-KIT. No further action required. Diamond RSB-42-066, on aux tank check valve replacement, was complied with by installation of solenoid check valves in the RH and LH nacelles using RSB-42-066-KIT, referencing WI-RSB-42-066. Ops check ok. All AD's checked thru Bi-Weekly 2009-07. -----END--I certify that this aircraft has been inspected in accordance with a 100HR Inspection and was determined to be in an airworthy condition. Volam Adam J. Cote AP 3035886 I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition. John J. Blaba Jr. AP 2238954 IA A & M Maintenance Services, Inc. - 1C5 Clow International Airport, Bolingbrook, IL. 848.8 Hrs. TACH TIME: TYPE: DIAMOND DA42 AIRFRAME T.T: 848.8 Hrs. "N" #: N 153TS DATE: 09/15/2009 Diamond MSB-42-070, on nose gear pivot assembly, was complied with by inspection, measured .020 in. gap, next inspection due in 100hrs at a tach time of 948.8hrs. Coloun Adam J. Cote AP 3035886 A & M Maintenance Services, Inc. - 1C5 Clow International Airport, Bolingbrook, IL TACH TIME: 905.5 Hrs. **DIAMOND DA42** AIRFRAME T.T: 905.5 Hrs. N 153TS "N" #: 03/05/2010 DATE: At this time, the RH and LH fuel filters were replaced. The cabin heat cable was replaced from the control arm to the center bellcrank. The right-hand main tire, Michelin P/N 072-449-0, and inner tube, P/N 097-500-0, were replaced. The LH and RH wing walks were replaced, LH P/N D60-1127-10-51 1 RH P/N D60-1127-10-52 1. All four ECU backup batteries were replaced, 4ea P/N LC-R127R2P. The aft cabin door was removed and reinstalled after repair from Diamond Aircraft Industries Inc. W/O# RO-10-017 dated 02/23/2010. The cabin defrost heat exchanger was replaced, P/N D60-2140-10-00-MOD MSB 42-070/1, on replacement of nose gear pivot tube, was complied with in accordance with WI-MSB-42-070/1 by replacement of tube, P/N D60-3233-82-00_01, and bearings, P/N GE10UK. MSB 42-074/3, to prevent nose gear structure failure, was complied with in accordance with WI-MSB-42-074/3 by installation of reinforcement plate P/N D60-5340-61-00-SB. -END----

John J. Blaha Jr.

A & M Maintenance Services, Inc. - 1C5 Clow International Airport, Bolingbrook, IL ED FOR COMPLE 917.6 Hrs. TACH TIME: **DIAMOND DA42** AIRFRAME T.T: 917.6 Hrs. "N" #: BF N 153TS FC DATE: 04/22/2010 At this time, the aircraft was inspected and lubed in accordance with an Annual Inspection per Diamond Service Manuals. The wheel bearings were cleaned, inspected, and greased. A gear retraction and emergency extension test was performed, no defects noted. The landing gear and wells were cleaned and lubed. The nose gear torque link hardware was inspected and tightened. The landing gear power pack and the brake reservoirs were serviced. The brakes were checked and found within limits. The rudder "S"-slides were lubed. The main and nose gear dampeners were serviced with nitrogen. The TKS reservoir screen was cleaned and inspected. Both induction filters were replaced 2ea P/N RB-0700, RH replaced with serviceable unit with 165.2hrs of service remaining, and the LH was replaced with new. The excitation batteries were replaced 2ea. P/N: LC-R121R3P, and are next due for replacement 04/2011. The emergency lithium battery pack was replaced, P/N D60-2560-91-00, and is next due for replacement 04/2012. The aircraft battery was removed and a new Gill G243 S/N G02456113, was serviced, charged, and installed. The ELT model ME40, S/N: 00460, was inspected and tested in accordance with FAR 91.207(d)(1-4). The ELT battery is due for replacement Feb 2011. All AD's checked thru Bi-Weekly 2010-08. ----END----A & M Maintenance Services, Inc. - 1C5 Clow International Airport, Bolingbrook, IL TACH TIME: 917.6 Hrs. TYPE: DIAMOND DA42 AIRFRAME T.T: 917.6 Hrs. "N" #: N 153TS DATE: 04/22/2010 I certify that this aircraft has been inspected in accordance with a 100HR Inspection and was determined to be in an airworthy condition. Molan Adam J. Cote AP 3035886 I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition. John J. Blaha Jr. AP 2238954 IA I certify that the Altimeter/s and Static system tests required by FAR 91.411 have been performed in accordance with FAR 43, Appendix E. Static System Test Date 05/21/2010 Altimeter/s Tested to 20,000 ft. Date 05/21/2010 Alt Reporting System Tested to 20,000 ft. Date 05/21/2010 Work Order 2010-044 Signed CRS#UOHR009X HELICOPTER SPECIALTIES, INC. 4746 S. Columbia Drive Janesville, WI 53546 I certify that the ATC Transponder Tests and Inspection required by FAR 91.413 have been performed in accordance with FAR 43. Appendix F. Unit S/N 89101869 Date <u>05/21/2010</u> Work Order <u>2010-044</u> Signed CRS#UOHR009X HELICOPTER SPECIALTIES, INC.

4746 S. Columbia Drive Janesville, WI 53546

A & M Maint	enance Services, Inc. – 1C5		
	nal Airport, Bolingbrook, IL.		
TYPE: DIAMOND DA42 "N" #: N 153TS DATE: 07/19/2010		81.6 Hrs. 81.6 Hrs.	
MSB42-088, on MLG trailing arm block, v MLG blocks, no defects noted. The next ins service thereafter.	was complied with by visual inspection of spection is due at the next 100hr service	and every 100hr	
	END		
John J. Blaha Jr. AP 2238954			
TACH OBSERNED AUGO	24, 2010 1014.3.		
TO THE RESIDENCE			
	A STATE OF THE STA		
		ASSESSED FOR THE PARTY OF THE P	1000



Date: November 24, 2010

FOR COMPLE

WO # RO-10-125 A/C DA 42NG S/N: 42.118 Reg: N153TS TSN: 1015.0

LHE Austro E4-B S/N: E4-B-00135 TSN: 0.00 Hrs. RHE Austro E4-B S/N: E4-B-00136 TSN: 0.00 Hrs.

LH Prop. Mt-propeller MTV-6-R-C-F/187-129 S/N: 06094 TSN: 1015.0 Hrs. RH Prop. Mt-Propeller MTV-6-R-C-F/187-129 S/N: 06095 TSN: 1015.0 Hrs.

The Following work has been carried out:

Diamond Aircraft Industries GmbH issued Optional Service Bulletin 42-068/1, complied with using Materials kit Appendix A Rev. 5 and Appendix B Rev. 2.

LH propeller MTV-6-A-C-F/187-129, S/N 06094, TSN 1015.0 removed for model change from "A" to "R" flange I.A.W. MT

Propeller SI No. 48C and reinstalled I.A.W. chapter 61 of DA 42 NG AMM Doc. # 7.02.15 Rev.

RH propeller MTV-6-A-C-F/187-129, S/N 06095, TSN 1015.0 removed for model change from "A" to "R" flange I.A.W. MT Propeller SI No. 48 C and reinstalled I.A.W. chapter 61 of DA 42 NG AMM Doc. #7.02.15 Rev. 1. Dynamic balance of LH & RH propellers carried out.

LH Thielert Engine TAE 125-01, S/N 02-01-0664 TSN:1015.0 removed and replaced with new "0" time Austro Engine model E4-B, S/N E4-B-00135 I.A.W. WI-OSB42-068 Rev. 6 Appendix 2 Rev. 1. RH Thielert Engine TAE 125-01, S/N 02-01-0665, TSN 1015.0 removed and replaced with new "0" time Austro Engine model E4-B, S/N E4-B-00136 I.A.W. WI-OSB42-068 Rev. 6 Appendix 2 Rev. 1. Ground run up of the Engines and fluid leak check performed and found satisfactory. Honeywell KAP140 autopilot system mechanical check and the system function check complied with. Landing gear installation carried out I.A.W. WI-OSB42-068 Rev. 6 Appendix 4. Landing Gear retraction check carried out I.A.W. DA 42NG current issue of AMM chapter 32. Electrical bonding check carried out. Pitot static & Transponder correlation check carried out. Airspeed indicator model code B864 removed and replaced with new unit model code B884 S/N 205337. Altimeter S/N 451353 removed & reinstalled after calibration check performed by Kitchener Aero Avionics. Compass swing carried out.

Radio's on: Liquid Compass FOR N 30 60 E 120 150 STEER 359 031 061 092 121 154 210 240 W 300 330 S

Aircraft reweighed:

New Empty weight = 1427. kg or 3146.0 lbs New E.W. C of G = 2.371 m or 93.35 in.

New E. W. Moments = 3383.7 kg-m or 293691.6 in-lbs

183 214 240 268 299 329

Max all up Weight =1900 kg or 4189 lbs New useful Load = 473.0 kg or 1043.0 lbs

New weight and balance report and equipment list added to section 6 of the Current AFM Doc. # 7.01.15-E Rev. 2 dated November 2009. All Placards checked for conformance. All flight control surfaces checked for balance & travels. This DA42 is converted to a DA42NG as per OSB42-068/1 and is eligible for TCDS A57CE Rev. 11 as per note 10. New Data Plate installed.

All snags notated during the above described tasks have been rectified and all pertinent details of the work carried out are on file with this work order.

The following DAI service bulletins C/W during OSB42-068/1:

Austro Engine MSB-E4-006 - N/A due to eng. S/N affectivity Austro Engine MSB-E4-007 - N/A due to eng. S/N affectivity

Austro Engine MSB-E4-008 - LH and RH eng. Oil separator hoses replaced with new C/W.

Austro Engine MSB-E4-009 /AD 2010-23-09 – High pressure fuel inspection/replacement to be C/W @ 50 hrs. engine time. MSB42NG002/4 - Software E4-B (AE300) engine Software version VC33_0_5_11 verified.

MSB42NG-003/4 - G1000 software version update C/W.

MSB 42NG-005/1 - Charged Air tube between Turbo charger & Intercooler C/W.

MSB42NG-007 - Emergency Exit lever Insp. & map light sealant C/W.

OSB42NG-008 - Installation of coated safety walk C/W.

MSB42NG-010 - Installation of a protective mesh on coolant and charged air radiator C/W.

OSB42NG-013 - Cowling with improved cooling performance C/W.

MSB42NG-014 - Replacement of Passenger door retaining bracket C/W

MSB42NG-016 – Rudder control System & NLG steering reinforcement C/W. NOTE: Repetitive inspections terminated.

MSB42NG-018 - Replacement of turbo connector Assy. C/W

OSB42-020 - Modification to heating system improvement N/A due to A/C S/N

MSB42-074/3 - NLG box reinforcement C/W I.A.W OSB42-068/1

MSB42-076 - Sealing of the LH and RH engine firewall holes N/A. No holes through FRP

MSB42NG-007 - Inspection of the Emergency exit lever C/W

MSB42-031/1 - LH and RH MLG brace rib reinforcement CW

MSB42-032/1 - Aux fuel tank vent hole insp. C/W

MSB42-043/1 - Replacement of aileron bellcrank rod ends PCW

MSB42-062/1 - Replacement of landing gear down lock pins PCW

MSB42-063/1 – Insp. & modification of the NLG N/A due to S/N affectivity. MSB42-070/1 – NLG pivot tubular Assy. N/A on DA42NG NLG Assy.

RSB42-025 - Improved fuel probes installation C/W

RSB42-029 - Additional position pins for canopy C/W

RSB42-066 - LH & RH aux tanks check valve and solenoid C/W.

MT Propeller SI48C - LH and RH propeller modification from "A" flange to "R" flange C/W.

Garmin MSB 0823 Rev.C - GDU CRS/BARO knob interference check C/W AD 2010-11-09 - Proportional Pressure reducing Valve N/A to Austro Engines

AD 2010-14-21 - Oil blow by separator N/A to Austro Engines

AD 2010-23-09 - High pressure fuel pump fuel oscillation check. NOTE: Due at 50 Hrs. Engine time. AWDS checked through Bi-Weekly Supplement 2010-25

CONTINUED NEXT PAGE: >

The mai	aft is released subject to the	has been performed in a	ccordance with the IDUSTRIES AMO ctory test flight for nce.	applicab 161-93 the evalu	le standards of A			
	orginator		Autonics 6 KITCHEN AER	ER	AMO 1-77		#1:	9
			Work Order #: Altimeter S/N:	Altim K41902 451353	eter Calibration T	est Record		
			Altitude (Feet)1000 0 500 1000 1500 2000 2500 3000 4000 6000 8000 10000 Hysteresis Case Leak	Tol (+/- Ft) 20 20 20 25 30 30 30 40 60	Altimeter Reads -15 -6 +1 -2 +4 +4 +6 -1 -26 -41 -57	Altitude (Feet) 12000 14000 16000 20000 22000 25000 30000 45000 Friction After Effect Completed	230 280	-50 12



Date: November 24, 2010

FOR COMPLET

WO # RO-10-125 A/C DA 42NG S/N: 42118 Reg: N153TS TSN: 1015.0

LHE Austro E4-B S/N: E4-B-00135 TSN: 0.00 Hrs. RHE Austro E4-B S/N: E4-B-00136 TSN: 0.00 Hrs.

LH Prop. Mt-propeller MTV-6-R-C-F/187-129 S/N: 06094 TSN: 1015.0 Hrs. RH Prop. Mt-Propeller MTV-6-R-C-F/187-129 S/N: 06095 TSN: 1015.0 Hrs.

1000 hr inspection carried out I.A.W. DA42NG AMM Doc. 7.02.15 Rev. 7 chapter 04-00-00. ELT annual performance check carried out. Next check due. Nov. 2011, ELT batteries expire Dec. 2013. Emergency battery package replaced with new. Next replacement due Nov. 2012. New ECU backup batteries installed. Next replacement due Nov. 2011. Autopilot mechanical check carried out. Next due at TTAF 1515.0 Hrs. Altimeter S/N 451353 removed and reinstalled after calibration check carried out by Kitchener Aero Avignica. Next tells in the carried out to the carried Kitchener Aero Avionics. Next calibration check due Oct. 2012 or TTAF 2015.0 hrs. Pitot static and transponder correlation checks carried out. Next check due Nov. 2012 or TTAF 2015.0 Hrs.

Magnetic compass swing carried out.

Radio	's on	i: Liq	uid (Com	pass	
FOR	N	30	60	E	120	150
STEER	359	031	061	092	121	154
FOR	S	210	240	W	300	330
STEER	183	214	240	268	299	329

Electrical bonding system and static discharging system check carried out. Next check due TTAF 2015 Hrs. or Nov. 2014. LH and RH fuel filter elements replaced with new. Brake fluid drained and replenished with new fluid 4 brakes bleeding carried out. Next fluid replacement due Nov. 2013. Hydraulic fluid in landing gear chambers replaced with new. Next fluid change due Nov. 2012. Hydraulic fluid in hydraulic system replaced with new. Next fluid change due Nov. 2012. LH & RH MLG brake discs and brake pads replaced with new. NLG LH bearing replaced with new. Gear retraction check carried out, found satisfactory TKS system FIKI test carried out. Wind shield de-ice system pump #1 replaced with a new unit S/N AST06K1952. New airspeed indicator S/N 205337 code B884 with limitation markings in conformance with OSB42-068/1 and AFM limitations section 2.3 Installed. Fuel hoses interconnecting the individual fuel tank chambers and fuel hoses connecting the fuel tank chambers to filler assemblies replaced with new. Next replacement due Nov. 2018. Both LH and RH newly installed engines serviced with 7 liters each Shell Helix 5W30 oil. LH and RH gearbox serviced with 2 liters each Shell Spirax GSX 75W80 oil. Wings removed and fuel tanks reworked I.A.W. OSB42-068/1. Wings inspected as per AMM chapter 05 inspection sheets and wings reinstalled. Control surfaces travel checks carried out. Rudder and stab removed inspected and reinstalled. Landing gear retraction check carried out and all audible warnings checked for operation.

All snags notated during the above described tasks have been rectified and all pertinent details of the work carried out are on file with this work order.

Following AWD's and SB's checked and complied with as applicable:

Austro Engine MSB-E4-006 - N/A due to eng. S/N affectivity Austro Engine MSB-E4-007 - N/A due to eng S/N affectivity

Austro Engine MSB-E4-008 – LH and RH eng. Oil separator hoses replaced with new C/W.

Austro Engine MSB-E4-009 – LH & RH High Pressure Fuel Pumps fuel oscillation check, NOTE: Due at 50 hrs. Engine time

MSB42NG002/5 - Software E4-B (AE300) engine verified Software version VC33_0_5_11

MSB42NG-003/4 - G1000 software version update C/W.

MSB 42NG-005/1 - Charged Air tube between Turbo charger & Intercooler C/W.

MSB42NG-007 - Emergency Exit lever Insp. & map light sealant C/W.

OSB42NG-008 - Installation of coated safety walk C/W.

MSB42NG-010 - Installation of a protective mesh on coolant and charged air radiator C/W.

OSB42NG-013 - Cowling with improved cooling performance C/W.

MSB42NG-014 - Replacement of Passenger door retaining bracket C/W.

MSB42NG-016 – Rudder control System & NLG steering reinforcement C/W. NOTE: Repetitive inspections terminated.

MSB42NG-018 - Replacement of turbo connector Assy. C/W

OSB42-020 - Modification to heating system improvement N/A due to A/C S/N

MSB42-074/3 - NLG box reinforcement C/W I.A.W. OSB42-068/1

MSB42-076 - Sealing of the LH and RH engine firewall holes N/A no holes through FRP.

OSB42-015/4 - Flight into known icing test of the TKS system C/W

MSB42-031/1 - LH and RH MLG brace rib reinforcement PCW.

MSB42-032/1 – Aux fuel tank vent hole insp. C/W.
MSB42-043/1 – Replacement of aileron bellcrank rod ends PCW.

MSB42-062/1 - Replacement of landing gear down lock pins PCW.

MSB42-063/1 - Insp. & modification of the NLG N/A due to S/N affectivity.

MSB42-070/1 – NLG pivot tubular Assy. N/A on DA42NG NLG Assy. RSB42-025 – Improved fuel probes installation C/W.

RSB42-029 - Additional position pins for canopy C/W.

RSB42-066 – LH & RH aux tanks check valve and solenoid C/W

MT Propeller SI48C - LH and RH propeller modification from "A" flange to "R" flange C/W. Garmin MSB 0823 Rev.C - GDU CRS/BARO knob interference check C/W.

AD 2008-16-20 - Replacement of Aileron bellcrank rod ends. PCW

AD 2010-11-09 - Proportional Pressure reducing valve N/A to Austro Engines.

AD 2010-11-09 - Proportional Pressure reducing valve N/A to Austro Engines.

AD 2010-14-21 - Oil blow by separator N/A to Austro Engines.

AD 2010-23-09 - High pressure fuel pump fuel oscillations check, NOTE: Due at 50 hrs. Engine time

AWDS checked through Bi-Weekly Supplement 2010-25

The maintenance described above has been performed in accordance with the applicable standards of

CONTINUED NEXT PAGE:

	I have carried out an independent inspection of the Flight controls/Power	rplant con	trols affected by the	work
		/		
	Signature: Barbbersle_Lic or Stamp:	_	012)	
	This aircraft is released subject to the completion of a satisfactory test flight for avionics performance.		OA OA	e and
	Signature Lic or Stamp:			
		-		
	Diamond			
	W Diament		Date: November	29, 2010
	WO # RO-10-125 A/C DA 42NG S/N: 42.118 Reg: N153TS TSN: 1015.0			
	LHE Austro E4-B S/N: E4-B-00135 TSN: 0.00 Hrs.			
	RHE Austro E4-B S/N: E4-B-00136 TSN: 0.00 Hrs.			
	The following work carried out			
	Propeller governors replaced with new units LHE propeller governor P/N P-877-16 S/N 10G160FD removed P/N P-877-16 S/N 10G406	CED install	ed	
	RHE propeller governor P/N P-877-16 S/N 10G161FD removed P/N P-877-16 S/N 10G409 Engines ground run and propeller governors self test function tested satisfactory.	5FD install	ed	
		5FD install	ed	
0		5FD install		thiness.
0	Engines ground run and propeller governors self test function tested satisfactory.	5FD install		thiness.
	The maintenance described above has been performed in accordance with the appropriate DIAMOND AIRCRAFT INDUSTRIES AMO	5FD install pplicable :		thiness.
	Engines ground run and propeller governors self test function tested satisfactory. The maintenance described above has been performed in accordance with the appropriate testing the properties of the properties	5FD install		thiness.
	The maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed above hin acco	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed in accordance with the appropriate the maintenance described above has been performed above hin acco	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed abov	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed above has been	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed above has been	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance with the application of the mainte	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed above has been	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance with the application of the mainte	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance with the application of the mainte	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.
	The maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application of the maintenance described above has been performed in accordance with the application. DIAMOND AIRCRAFT INDUSTRIES AMO DIAMOND Lic or Stamp: Lic or Stamp: Date: November 29, 2010 Aircraft Total Time: 1015.0 hours I certify that this aircraft DA 42 NG Serial Number 42.118 has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.	5FD install pplicable :		thiness.

	Edward Fill	DAI		TOTAL TIME S	SINCE	ENGINEERING RECORD NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLET	+
	DATE	HRS.	MIN.	HRS.	MIN.	NOTE: USE SO	1
	BROUGHT FORWARD			1015	.0		1
	NOV 2 9 2010	1	.5	1016	.5		1
2.4.	MOV 2 9 2010	-	-	1016	.5	** Diamond	+
	NOV 3 0 2010					Date: November 30, 2010 S/N: 42.118 REG: N153TS TSN: 1016.5 Hrs. W/O RO-10-125 The following additional work carried out: LH aileron and flap short rods lengthened by ½ turn at the rod ends. Stall Vane adjusted 1mm down. I have carried out an independent check of the flight controls affected by the work accomplished. Signature Lic. or Stamp This aircraft is released subject to the completion of a satisfactory test flight for the evaluation of Flight, Engine, & Avionics performance	
				1016	.5	The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #161-93 DA RO6 Signature Lic or Stamp	
	DEC 1 6 2010	0	.6	1017	.1		
				1017	7./	Date: December 16, 2010 S/N: 42.118 REG: N153TS TSN: 1017.1 Engine E4-B Ser. No. E4-B-00136 Engine TSN: 2.1 Hrs. The following additional work carried out by Diamond Aircraft Industries Inc. Service centre Dept. Glow Plug Control box unit P/N E4A-94-200-000-020 S/N. 000200 removed & replaced with anew unit S/N. 000050. Ground run up of the engine performed found to be satisfactory. The maintenance described above has been performed in accordance with the applicable standards of airworthiness. DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVAL #154-93 Signature Lic or Stamp	
							-
							/
9							7
						CARRIED FORWARD	/

3-11	teny was removed and a new Give 1243 S/N (2\$25352\$2, was seeviced,	1+/10	COM.
Bat	tery was some are	of B	273382
10 XL	1-243 SAI GAZESES LE	0	
0/	1 1 1 1 was serviced,		
Char	sed, and installed.		
	A & M Maintenance Services, Inc. – 1C5		
	Clow International Airport, Bolingbrook, IL. TYPE: DIAMOND DA42 TACH TIME: 1	-	
	"N" # N 152TC	076.5 Hrs	
	At the time, the RH fuel filter was replaced, P/N WK-724_3. The cabin defrost cal control arm to the bellcrank was replaced, P/N T22700034. Ops check normal, no	leaks noted.	
	School Bluf		
	John J. Blana Jr. AP 2238954		
	A & M Maintenance Services, Inc. – 1C5		
-00	Clow International Airport, Bolingbrook, IL. TYPE: DIAMOND DA42		
	"N" #. N 152TC	100.6 Hrs	
	At the time, the left-hand fuel temp probe was replaced, P/N S102511PFY24S, us Leak and ops checked. The trim wheel control chain was reinstalled and the tension needed.	ing new gasket. n adjusted as	
	END-		
	Celem 1 Cox		
	Adam J Cote AP3035886		
	A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL.		
	TYPE: DIAMOND DA42 TACH TIME: "N" #: N 153TS AIRFRAME T.T: DATE: 05/16/2011	1107.5 Hrs. 1107.5 Hrs.	
	At this time, both fuel filters were changed using 100hr service kit, P/N DA ECU connectors were removed, inspected, and reinstalled.		
	Celeum / Con S		
	AP3035886		
-			

DATE	TOT		TIME	SINCE FG.	ENGINEERING RECORD NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLET	
DATE	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTH PAGES AND	
BROUGHT	M	1	450	375 -4	7-11-2011 touch 11.25013 H12222 Al	
		1			Take Mark 105	1
			A & M	I Mainte	enance Services, Inc. – 1C5 nal Airport, Bolingbrook, IL.	+
T	YPE: DIA	MOND E		Cinatio	TACH TIME: 1201.8 Hrs.	+
		53TS)A42		AIRFRAME T.T: 1201.8 Hrs.	-
		10/2011				-
W	heel bearings	s were rem	noved, clear o-rings, P/N	ned, inspend NMS287	0, and tubes, P/N 097-500-0 were replaced. The main ected, greased and reinstalled. The both brake calipers 75-222. The brakes were serviced and bled.	
	//	/	/ //	<u>-</u>	END	
P	In J. Blaha.	BLL	The			
A	P 2238954	1.				
		0				
			1			+
		-				-
			A &	M Maint	tenance Services, Inc. – 1C5	
7	TYPE: DL	AMOND	DA42-NG		onal Airport, Bolingbrook, IL	
		153TS	DA42-NO	ī	TACH TIME: 1223.1 Hrs. AIRFRAME TT: 1223.1 Hrs.	
	DATE: 12				Table 1 III	
n v	n accordance wheel bearing	gs were cle	oohr/AN eaned, inst	NUAL IN pected, and	cleaned for inspection. All components were inspected NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and	
lo l	n accordance wheel bearing wheel bearing wheel the pear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1.207 replacements aft (white ere reposition commont of the pear reposition of the pear retrained to the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 11–4). The Ent at 1323 yy (lithium te) nav ligloned and coalele and coalele were o bellerant and observe and and and coalele were o bellerant and	power pack emergence ceplaced, P/ere checked cleaned and as inspects ME406, S/LT battery B. Ihrs. Bot blockup to the bulbs wages were exposition to the bulbs was repicted and cable were considered and cable a	NUAL IN sected, and and brake y extension N RU-16: do The rue d lubed. The ded and cle N: 00460 y is due 12 h main fu battery vol ere replace inspected inspected fuel do The laced. The laced and cle page 16- h main fu battery vol ere replace inspected fuel do The laced and and and and and and and and and an	d greased. The landing gear legs were cleaned and creservoir fluid level was checked, no service needed. on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. O, was inspected and tested in accordance with FAR 2/2013. Both fuel filters were replaced and are next due tel filler cap water seals were replaced, 2ea P/N BS534. Istage was checked and replacement is due at 10-2012. Deed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and eathernate air cable, from bellcrank to air box, was	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellcraninousing an attrol to be	pour pack emergence eplaced, P/ ere checked cleaned and as inspects ME406, S/ LT battery B. Ihrs. Bot b) backup b th bulbs we ages were exposition k, was repided and cable was	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellcraninousing an attrol to be	pour pack emergence eplaced, P/ ere checked cleaned and as inspects ME406, S/ LT battery B. Ihrs. Bot b) backup b th bulbs we ages were exposition k, was repided and cable was	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	d greased. The landing gear legs were cleaned and creservoir fluid level was checked, no service needed. 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. 20, was inspected and tested in accordance with FAR 2/2013. Both fuel filters were replaced and are next due tel filler cap water seals were replaced, 2ea P/N BS534. 2/2014 and 1-2012 and 1-2012 and 1-2012 and 1-2012 and 1-2012 and 1-2012 and 1-2013 and 1-2014 and 1-2015 and 1-20	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence eplaced, P/ ere checked cleaned and as inspects ME406, S/ LT battery B. Ihrs. Bot b) backup b th bulbs we ages were exposition k, was repided and cable was	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence eplaced, P/ ere checked cleaned and as inspects ME406, S/ LT battery B. Ihrs. Bot b) backup b th bulbs we ages were exposition k, was repided and cable was	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the the the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the the the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the the the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the the the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	
lu vi	n accordance wheel bearing ubed. The hy The gear retranduction filte udder cable the edal assembliks reservoing the Artex EL 1.207 (d) (1-1) or replacement the emergence of the the emergence of the emergence of the emergence of the the the emergence of the	e with a 10gs were clevidraulic popular action and ers were retensions wellies were or screen w.T., M/N: 1 -4). The Ent at 1323 yy (lithium te) nav lighoned and cables were on bellerant nousing an attrol to be	pour pack emergence pelaced, Prere checked cleaned and as inspects (ME406, S/LT battery) backup to the bulbs wages were reposition k, was repided and cable was located and cable was located and cable was reposition was repided and cable was located and cable was repided and cable was reposition was repided and cable was repided and cable was repided and cable was reposition was repided and cable was reposition was repided and cable was reposition was repided and cable was repided and cable was reposition and cable was reposition was reposition was repided and cable was reposition and cable was reposition.	NUAL IN pected, and and brake y extension. When I have a second of the I have a second of t	NSPECTION per Diamond Service Manual. The nose d greased. The landing gear legs were cleaned and e reservoir fluid level was checked, no service needed. The needed on tests were performed, no defects noted. Both 20, the next replacement is due at 1423.1 hrs. The dder hinge, torque plate, return springs, s-slides, and The elevator and rudder trim friction was checked. The caned. The aircraft battery was charged and serviced. When we was charged and serviced. When the filters were replaced and are next due the filler cap water seals were replaced, 2ea P/N BS534. Seed, 2ea P/N 34-0428070-64. All engine safety ropes and cleaned. The induction hoses, pressure side, and event chaffing on both engines. The cabin defrost cable, the cable was reinstalled, and the	

			-
	A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL		LICENCE
ENTRIES.	TYPE: DIAMOND DA42-NG "N" # N 153TS PATE: 12/09/2011	1223.1 Hrs. 1223.1 Hrs.	
	The engine mount to firewall bolt torque was checked. A known ice functional test and all system components operate normal. The ECU backup batteries, 4ea P/N LC were replaced and are next due 12/2012. All AD's checked thru BI-weekly 2011-2 AD2011-10-13, effective 06/17/2011, on pax door retaining bracket, was previous by Diamond Aircraft, at 1015.1hrs 11-24-2010, in accordance with MSB42NG-01 MSB42NG-024, engine safety ropes, was complied with in accordance with WI-M by removal of safety ropes and inspection of engine cages, no defects noted.	sly complied with 14. ASB42NG-024	
	I certify this AIRCRAFT has been inspected in accordance with a 100HR INSPECTION and was determined to be in an airworthy condition.		-
	Adam J. Cote AP 3035886 I certify this AIRCRAFT has been inspected in accordance with an ANNUAL INSPECTION and was determined to be in an airworthy condition.		,
	John J. Blaha Jr. AP 2238964 IA		
	A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL.		
	TYPE: DIAMOND DA42 TACH TIME: "N" #: N 153TS AIRFRAME T.T: DATE: 04/04/2012	1328.4 Hrs. 1328.4 Hrs.	
	SILD42NG-001, correction of data plate, was complied with by removal of dat installation of original data plate and revision data plate P/N DS_STP-1.		
	John J. Blahaf John J. Dhaha Jr. AP 2238954		

A & M Maintenance Services, Inc. – 1C5 COMPLETE Clow International Airport, Bolingbrook, IL. DATE 1328.4 Hrs. TACH TIME: TYPE: DIAMOND DA42 1328.4 Hrs. AIRFRAME T.T: BROUGHT "N" #: N 153TS 42.118 FORWARD AIRFRAME S/N: FAF DATE: 05/17/2012 At this time, the LH cowling oil access door latch seal was replaced and the latch was adjusted. The App RH cowling oil access door latch assembly was replaced with new, P/N D64-7116-60-00. The cabin Stat defrost control system was disassembled, all bellcranks and cables were lubricated, and the system Altir was reassembled, ops check normal. The LH wing was disassembled and removed. The fuel tank Alt assembly was disconnected and removed, the outboard fuel sender, P/N D60-2817-14-00_1, and the Wor inboard fuel sender, P/N D60-2817-13-00_1, were replaced with new, and installed using a new o-rings. The tank anti-chafe tape was replaced as needed. The fuel tank assembly was installed in the Sigr wing and the wing was installed onto the aircraft. All connections were assembled and the fuel tank HEL was filled and checked for leaks, none noted. The top two ice protection panels on the LH forward 474 fuselage were replaced, 2ea P/N D60-1123-20-24. The LH and RH Alternators were removed and replaced with new as per 300hr inspection, LH installed P/N E4A-91-000-000 Iss:010 S/N 00773, Jan and RH installed P/N E4A-91-000-000 Iss:010 S/N 00770. The next 300hr inspection is due at 1628.4hrs. The next 100hr service is due at 1428.4hrs. RSB42NG-017/1, on improved MLG dampener seals, was complied with by replacement of seals in both MLG dampeners in accordance with WI-RSB42NG-017. The dampeners were serviced with hydraulic fluid and nitrogen to the proper pressure. Both dampeners were painted with a red dot for identification of compliance with this bulletin. MSB42NG-026, on replacement of the MLG dampener nut, was complied with at this time by complying with MSB42NG-017/1. -END-----A & M Maintenance Services, Inc. - 1C5 Clow International Airport, Bolingbrook, IL. TYPE: **DIAMOND DA42** TACH TIME: 1328.4 Hrs. N 153TS AIRFRAME T.T: 1328.4 Hrs. DATE: 05/17/2012 AIRFRAME S/N: 42.118 alleun Adam J Cote AP3035886 Federal Aviation Administration Flight Standards District Office **4915 South Howell Avenue** Milwaukee, Wisconsin 53207 Aircraft Make: Diamond Aircraft Ind. GmbH Model: DA 42 NG. S/N: 42.118. Registration: N153TA. I find that this Aircraft meets the requirements of the certificate requested and have issued an Amended Standard Airworthiness Certificate dated 04/16/2012 due to aircraft model change. Timothy H. Anderson Aviation Safety Inspector AGL-FSDO-13 CARRIED FORWARD

Certify that the Alimeter's and Static system tests required by Certify that the Alimeter's tested and coordance with FAR 43, Appendix E.		INSPECTION, REPAIRS & REPLACEME	NT N DATE AND TIME COLUMNS.	SIGNATURE	LICENCE NUMBER
A & M Maintenance Services, Inc. – 1CS Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG TACH TIME: 1434.0 Hrs. N 153TS AIRFRAME TT: 1434.0 Hrs. DATE: 11/09/2012 At this time, both fuel filters were changed using 100hr kit, P/N DA42-AE-100KIT. The alternate air cable, from control to bellerank, was replaced. The emergency (lithium) battery pack was replaced, Pen NBU-1620, next replacement is due 11/2014. Both induction filters were replaced, Pen NBU-1620, next replacement is due 11/2014. Both induction filters were replaced, Pen NBU-1620, next due in 200hrs at 1634 ohns. Adam J Cote AP 3035886 A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG TACH TIME: 1474.8 Hrs. AIRFRAME S/N: 42.118 DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. AIRFRAME S/N: 42.118 DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. AIRFRAME S/N: 42.118 gaar legs were cleaned, inspected, and greased. Both main tires were replaced, 2ea P/N 072-460. The landing were cleaned, inspected, and greased. Both main tires were replaced. 2ea P/N 072-40. The landing gear legs were cleaned, and both. All brake limings were replaced Ale P/N aPS66-10500. The hydraulic gear legs were cleaned and lubed. All brake limings were replaced between the source of the control of the properties of the proper	I certify that the FAR 91.411 h. Appendix E. Static System Altimeter/s To Alt Reporting Work Order_ Signed	the Altimeter/s and Static system tests required by have been performed in accordance with FAR 43, Test Date 10/05/2012 ested to 20,000 ft. Date 10/05/2012 system Tested to 20,000 ft. Date 10/05/2012 2012-115 CR SPECIALTIES, INC. embia Drive	by FAR 91.413 have been per Appendix F. Unit S/N 89101869 Date Signed HELICOPTER SPECIALTIES 4746 S. Columbia Drive	formed in accordance 10/05/2012_Work	ce with FAR 43, COrder 2012-115
TYPE: DIAMOND DA42-NG N"# N 153TS DATE: 11/09/2012 At this time, both fuel filters were changed using 100br kit, PN DA42-AE-100KIT. The alternate air cable, from control to bellerank, was replaced. The emergency (dithium) battery pack was replaced, PN De0-256-091-00, next due in 200brs at 1634 0brs. PN 200-256-091-00, next due in 200brs at 1634 0brs. Adam J Cote AP 3035886 A& M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG N"# N 153TS DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. All components were inspected in accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings were cleaned, inspected, and greased. Both main tires were replaced, 2ea PN N27-449-0. The landing gear legs were cleaned and lubed. All brake limings were replaced Sea P/N APS66-10500. The hydraulic gear legs were cleaned and lubed. All brake limings were replaced sea P/N APS66-10500. The hydraulic gear legs were cleaned and nubed. All brake limings were replaced with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects noted. The rudder hinge, torque plate, return springs, s-slides, noted. The rudder table tensions were checked. The rudder hinge, torque plate, return springs, s-slides, noted truth friends was checked. The KT reservoir screen was inspected and cleaned. The aircraft battery was charged and serviced. The KT reservoir screen was inspected and cleaned. The aircraft battery was charged and serviced. The KT reservoir screen was inspected and lebed in accordance with FAR 91.207 (d) (1) 41. The ELT battery is due 12/2013. All engines asfety ropes were reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was rigged. A k		A & M Maintenance Ser	rvices, Inc. – 1C5		
A & M Maintenance Services, Inc. – IC5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG "N" # N 153TS DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. All components were inspected in accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings were cleaned, inspected, and greased. Both main tires were replaced, 2ea P/N 072-449-0. The landing gear legs were cleaned and lubed. All brake linings were replaced Sea P/N APS66-10500. The hydraulic gear legs were cleaned and lubed. All brake linings were replaced doed. The nose strive and dust cable was replaced, with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects noted. The nudder cable tensions were checked. The rudder hinge, torque plate, return springs, s-slides, and pedal assemblies were cleaned and lubed. The pilot side rudder peda dust cable was replaced, P/N and pedal assemblies were cleaned and lubed. The pilot side rudder pedal dust cable was replaced, P/N and pedal assemblies were cleaned and lubed. The pilot side rudder peda lust cable was replaced, P/N and pedal assemblies were cleaned and lubed. The pilot side rudder peda lense and the control level was characted and serviced. The Artex ELT, M/N. ME406, S/N. 00460, was inspected and tested in accordance with FAR 91.207 (d) (1-4). The ELT battery is due 12/2013. All engine safety ropes were repositioned and cages were inspected and cleaned. The alternate air inner cable, from bellcrank to RH induction box, was removed, the housing and cable were cleaned and lubricated, and the entire system was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the		TYPE: DIAMOND DA42-NG "N" # N 153TS DATE: 11/09/2012 At this time, both fuel filters were changed using 100hr	TACH TIME: 1434.0 I AIRFRAME TT: 1434.0 I r kit, P/N DA42-AE-100KIT. The a	Hrs. Iternate as	3
A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG TACH TIME: 1474.8 Hrs. AIRFRAME TT: 1474.8 Hrs. AIRFRAME TT: 1474.8 Hrs. AIRFRAME TT: 1474.8 Hrs. AIRFRAME TT: 1474.8 Hrs. AIRFRAME TS: 1474.8 Hrs. AIRFRAME SN: 42.118 At this time, the airframe was opened and cleaned for inspection. All components were inspected in accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings were cleaned, inspected, and greased. Both main tires were replaced, 2ea P/N 072-449-0. The landing gear legs were cleaned and lubed. All brake linings were replaced 8ea P/N APS66-10500. The hydraulic gear legs were cleaned and lubed. All brake linings were replaced 8ea P/N APS66-10500. The hydraulic power pack and brake reservoir fluid level was checked, no service needed. The nose strut was serviced with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects noted. The rudder cable tensions were checked. The rudder hinge, torque plate, return springs, s-slides, and pedal assemblies were cleaned and lubed. The pilot side rudder pedal adjust cable was replaced, P/N 20-2700-21-00. The flap up position indicator lamp was replaced, P/N 74.6 c42-Q. The elevator and rudder trim friction was checked. The TKS reservoir screen was inspected and cleaned. The aircraft battery was charged and serviced. The Artex ELT, M/N: ME406, S/N: 00460, was inspected and tested in accordance with FAR 91.207 (d) (1-4). The ELT battery is due 12/2013. All engine safety ropes were repositioned and cages were inspected and cleaned. The aitcrnate air inner cable, from bellcrank to RH induction box, was removed, the housing and cable were cleaned and lubricated, and the entire system was rigged. A known ice functional test was performed and all system components operate normal. The cowing fireproof paint was touched un as		replaced 2ea P/N RU-1620, next due in 200hrs at 103	4.0105.		
Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG "N" # N 153TS DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. All components were inspected in accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings were cleaned, inspected, and greased. Both main tires were replaced, 2ea P/N 072-449-0. The landing gear legs were cleaned and lubed. All brake linings were replaced. 2ea P/N APS66-10500. The hydraulic gear legs were cleaned and lubed. All brake linings were replaced. The nose strut was serviced with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects noted. The rudder cable tensions were checked. The rudder injee, torque plate, return springs, s-slides, and pedal assemblies were cleaned and lubed. The pilot side rudder pedal adjust cable was replaced, P/N 20-2700-21-00. The flap up position indicator lamp was replaced, P/N T4.6 24-20. The elevator and rudder trim friction was checked. The TKS reservoir screen was inspected and cleaned. The aircraft battery was charged and serviced. The Artex ELT, M/N; ME406, S/N; 00460, was inspected and tested in accordance with FAR 91.207 (d) (1-4). The ELT battery is due 12/2013. All engine safety ropes were repositioned and cages were inspected and cleaned. The alternate air miner cable, from bellcrank to RH induction box, was removed, the housing and cable were cleaned and lubricated, and the cable was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was reinstalled. The a		Adam J Cote			
TYPE: DIAMOND DA42-NG "N" # N 153TS DATE: 01/10/2013 At this time, the airframe was opened and cleaned for inspection. All components were inspected in accordance with a 100HR/ANNUAL INSPECTION per Diamond Service Manual. The wheel bearings were cleaned, inspected, and greased. Both main tires were replaced, 2ea P/N 072-449-0. The landing gear legs were cleaned and lubed. All brake linings were replaced 8ea P/N APS66-10500. The hydraulic gear legs were cleaned and lubed. All brake linings were replaced 8ea P/N APS66-0500. The hydraulic power pack and brake reservoir fluid level was checked, no service needed. The nose strut was serviced with nitrogen to 232psi. A gear retraction and emergency extension tests were performed, no defects noted. The rudder cable tensions were checked. The rudder hinge, torque plate, return springs, s-slides, noted. The rudder cable tensions were checked. The rudder pedal adjust cable was replaced, P/N 20-2700-21-00. The flap up position indicator lamp was replaced. P/N T4.6 24-20. The elevator and rudder trim friction was checked. The TKS reservoir screen was inspected and cleaned. The aircraft battery was charged and serviced. The Artex ELT, M/N: ME406, S/N: 00460, was inspected and tested in accordance with FAR 91.207 (d) (1-4). The ELT battery is due 12/2013. All engine safety ropes were repositioned and cages were inspected and cleaned. The aitcrnate air inner cable, from bellerank to RH induction box, was removed, the housing and cable were cleaned and lubricated, and the cable was reinstalled. The alternate air cable from control lever to bellcrank was replaced, and the entire system was rigged. A known ice functional test was performed and all system components operate normal. The cowling fireproof paint was touched un as needed. The emergency (lithium) backup battery voltage was checked and replacement is due at 11/2014. The ECU backup batteries, 4ea P/N LC-R127R2P1, were		A & M Maintenance Clow International Air	Services, Inc. – 1C5 port, Bolingbrook, IL		
		"N" # N 153TS DATE: 01/10/2013 At this time, the airframe was opened and cleaned for accordance with a 100HR/ANNUAL INSPECTION were cleaned, inspected, and greased. Both main tires gear legs were cleaned and lubed. All brake linings we power pack and brake reservoir fluid level was checked with nitrogen to 232psi. A gear retraction and emerge noted. The rudder cable tensions were checked. The ru and pedal assemblies were cleaned and lubed. The pill 20-2700-21-00. The flap up position indicator lamp to rudder trim friction was checked. The TKS reservoir subattery was charged and serviced. The Artex ELT, M. accordance with FAR 91.207 (d) (1-4). The ELT batter repositioned and cages were inspected and cleaned. The induction box, was removed, the housing and cable were installed. The alternate air cable from control lever rigged. A known ice functional test was performed and cowling fireproof paint was touched up as needed. The checked and replacement is due at 11/2014. The ECU	AIRFRAME TT: AIRFRAME S/N: r inspection. All components were in per Diamond Service Manual. The were replaced, 2ea P/N 072-449-0. The replaced 8ea P/N APS66-10500 The replaced 8ea P/N T4.6 24-20. The service replaced, P/N T4.6 24-20. The service was inspected and cleaned. The replaced and service in the service of the alternate air inner cable, from be service cleaned and lubricated, and the service cleaned and lubricated, and the service dealer and service replaced, and the service of the servic	1474.8 Hrs. 42.118 aspected in wheel bearings The landing The hydraulic t was serviced no defects ings, s-slides, as replaced, P/N elevator and the aircraft acted and tested in try ropes were ellcrank to RH cable was entire system was ormal. The ery voltage was 27R2P1, were	

Carl St	TOTAL AIR			
	A & M Clow Int	ternational Airport, Bolingbrook, IL		DMPLETE
"N" # N 153TS		AIRFRAM	E TT: 1474.8 Hrs.	
AD2012-17-07, eff mapping in accorda	fective 10-11-2012, ance with MSB42N	on excessive adhesive voids, was complied G-022, results sent to Diamond Aircraft for	with by tap test and review, normal flight	
permitted at this tin	ne.	END		
I certify this AIRC	RAFT has been ins	pected in accordance with a		
100HR INSPECT	ION and was determ	mined to be in an airworthy condition.		
AP 3035886	DAFT besterning	aceted in accordance with an		
ANNUAL INSPE	CTION and was de	termined to be in an airworthy condition.		
Joluf B	Chaf			
John J. Blaha Jr. AP 2238954 IA				
	1			
	D DA42-NG	TACH TIME	: 1512.9 Hrs.	
	2			
at this time, the airf	rame was opened a	nd cleaned for inspection. All components we	ere inspected in	
eference with a 100]	HR/ANNUAL INS	PECTION per Diamond Service Manual. Tl	he wheel bearings	
ere cleaned, inspect ack and brake reser	ted, and greased. The	e landing gear legs were cleaned and lubed. The pose struct	The hydraulic power	
itrogen to 232psi. A	gear retraction and	emergency extension tests were performed	no defects noted	
he rudder cable tens	sions were checked,	no adjustment needed. The rudder hinge tore	que plate return	
ere checked. The T	KS reservoir screen	was inspected and cleaned. The L.H. fuel term	nerature concer wire	
onnection terminals	were replaced with	new, ops check good. Both alternate air door	re were adjusted for	
III travei. The aircra	III battery was charg	ted and serviced. The Artex FLT M/N-MEA	106 CAT. 00160	
ngine safety ropes w	vere repositioned and	cages were inspected and cleaned A known	n ion franti- 14-4	
as periorified and a	ii system componen	Is operate normal The emergency (lithium) 1	haalam batta	
offage was checked	and is due for replace	cement at 10-2012 The FCII backup better.	t months to	
D2013-0/-01, enec	ctive 05/20/2013 of	Overeytension of the main landing		
112013-00-02, ellec	cuve 04/08/2013, or	1 engine induction filter icing was proviously	y complied with by	
		CONTINUED		
		CARRIED FORWARD		
	TYPE: DIAMON Adam J. Cote AP 3035886 I certify this AIRC ANNUAL INSPECT ANNUAL IN	Clow Interpretation of the rudder cable tensions were checked, and brake reservoir screen connection terminals were replaced with all travel. The aircraft battery was charge spected and tested in accordance with Inspected and all system componen of the proposed and as performed and all system componen of the proposed and september 2013–07-01, effective 05/20/2013, or evolved-092, effective 05/08/2013, or evol	Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG N" # N 153TS ARFRAM AD2012-17-07, effective 10-11-2012, on excessive adhesive voids, was complied mapping in accordance with MSB42NG-022, results sent to Diamond Aircraft for permitted at this time. END I certify this AIRCRAFT has been inspected in accordance with a 100HR.INSPECTION and was determined to be in an airworthy condition. Adam J. Cote AP 3035886 I certify this AIRCRAFT has been inspected in accordance with an ANNUAL INSPECTION and was determined to be in an airworthy condition. A & M Maintenance Services, Inc. – 1C5 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG N" # N 153TS AIRFRAME AIR	A & M Maintenance Services, Inc. – 1C3 Clow International Airport, Bolingbrook, IL TYPE: DIAMOND DA42-NG

-	A & M Maintenance Servi Clow International Airport,		BRUTAHUE	LICENCE
ENTRIES.	TYPE: DIAMOND DA42-NG	AIRFRAME TT:	1512.9 Hrs. 1512.9 Hrs.	
	"N" # N 153TS DATE: 05/24/2013	AIRFRAME S/N:	42.118	
	MSB42NG-035/1, nose gear actuator bearing and safety wa			
	housing, no damage noted.			
		with a		
	100HR INSPECTION and was determined to 50 at an	yorthy condition.		
	Cleleun / Cox			
	AD 2025996			
	I certify this AIRCRAFT has been inspected in accordance ANNUAL INSPECTION and was determined to be in an	with an airworthy condition.		
	Lokel Bletch			
	John J. Blaha Jr. AP 2238954 IA			
		2 4 77 00100		
	American Avionics 7023 Perimeter Rd.		1541 5	
	Date: 31October2013_Diamond_DA42NG_N	153TS_SN: 42.118_1118:	1541.5	
	MFD Replacement: Replaced existing GDU1040 p/n 011-00972-03 s/n 8890076 03 s/n 88901283 in accordance with Garmin G1000 System	6 with newly overhauled GDU10- Maintenance Manual p/n 190-009	40 p/n 011-00972- 007-00 Rev E.	
	Garmin G1000 System software update: Complied with Diamond Mandatory Service Bulletin NO. M software v0670.10 in accordance with Garmin G1000 Syste	1SB 42NG-003/13 by installing G m Maintenance Manual p/n 190-0	1000 System 0907-00 Rev E.	
	This aircraft was inspected in accordance with applicable m regard to the work performed, this aircraft is approved for re-	aintenance rules and current FAA eturn to service.	Regulations. With	
	Details on file under WO# A14393.	14 n. 2	ARS A	
	Steven M. Latti	in JHM JH		1
	Inspector CRS# 1AMR9	80Y		
1				-
	American Avionics 7023 Perimeter Rd. Se			
	Date: _19September2013_Diamond_DA42NG_N			
	Removed defective GEA 71 p/n 011-00831-00 s/n 46703729 at 011-00831-00 s/n 46708243 in accordance with Garmin G1000	nd replaced with newly overhaule O System Maintenance Manual p/1	a GEA /1 p/n n 190-00907-00	
	Rev E. This aircraft was inspected in accordance with applicable main regard to the work performed, this aircraft is approved for return.	tenance rules and current FAA R rn to service.	egulations. With	
	Details on file under WO# 93876. Rick Wiseman	Reldelley	(AMA)	
	Inspector CRS# 1AMR980	Y		

Removed defective			craft: Diamond DA42-NG	S/N-42.118	TACH: 1541.5	
Kit-N05-801-432	ve TKS level sending u I/A/W Diamond DA42 A42-NG M/M. Operat	NG M/M. Remove	new sending unit P/N-D60-3013-2 ed and replaced burned out position	5-00 using new gaskets n light P/N-34-0428020	and hardware supplied in 0-65 (1ea.) in Starboard	
0	1		2775150			
Signature /	The same of the same of	A&P_		the same resource or		СОМР
AMERICAN		1				
AVIONICS	11/14/2013	N153TS	Aircraft: Diamond DA42	S/N-42.118	TACH: 1549.4	
Removed worn L/H gear Goodyear Fligh M/M.	main gear tire Cond at Special 2 15X6.00	-6 6ply P/N156E	oly P/N-072-449-0 S/N-2189S00 61-3 S/N-31412121. Maintena	453 and installed a n nce and servicing per	ew tire on L/H main formed I/A/W DA42	
Signature		A&P_	2775150		_	-
					_	
AMERICAN						
AVIONICS	12/5/2013	N153TS	Aircraft: Diamond DA42	S/N-42.118	TACH: 1550.8	
Removed main bat	tery Gill P/N-G-243	S/N-G02535202	and installed a new main batte	ry Gill P/N-G243 S/N	-G02801697	-
Maintenance perfo	rmed I/A/W Gill bat	tery servicing in:	structions and DA42 M/M.	1, 0 1, 11 02 10 0, 11		
N					<u> </u>	
Signature /		A&P_27	15150		No.	
The same and						
OMEDICO.	001011001					
AMERICAN	02/04/2014	N153TS	D42 S/N 42.118	1550 8 Tach &	B TTAE -	
AVIONICS			D42 S/N 42.118	1550.8 Tach &		
AVIONICS Removed stall wa after overhaul by	rning lift detector P	N C-99701-1, S	/N 241. Installed same lift dete	ctor, P/N C-99701-1	, S/N 241,	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st	rning lift detector Page Safe Flight Instrume	N C-99701-1, S	/N 241. Installed same lift dete	ctor, P/N C-99701-1	, S/N 241,	
AVIONICS Removed stall wa after overhaul by 3 Diamond DA42 st Aircraft is OK for	rning lift detector Page Safe Flight Instrume	N C-99701-1, S	/N 241. Installed same lift dete QA1R419K, work order #3854 /N D60-2737-11-00. Ground f	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241,	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st	rning lift detector Page Safe Flight Instrume	N C-99701-1, S	/N 241. Installed same lift dete	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241,	
AVIONICS Removed stall wa after overhaul by 3 Diamond DA42 st Aircraft is OK for	rning lift detector Page Safe Flight Instrume	N C-99701-1, S	/N 241. Installed same lift dete QA1R419K, work order #3854 /N D60-2737-11-00. Ground f	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241,	
AVIONICS Removed stall wa after overhaul by 3 Diamond DA42 st Aircraft is OK for	rning lift detector Page Safe Flight Instrume	N C-99701-1, S	/N 241. Installed same lift dete QA1R419K, work order #3854 /N D60-2737-11-00. Ground f	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241,	
AVIONICS Removed stall wa after overhaul by 3 Diamond DA42 st Aircraft is OK for	rning lift detector P/Safe Flight Instrume tall warning installat test flight.	N C-99701-1, S ent Corp, CRS# of ion gauge tool F	N 241. Installed same lift dete QA1R419K, work order #3854 N D60-2737-11-00. Ground f Certificate AP34079	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241, position with a good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS	rning lift detector PASafe Flight Instrume tall warning installat test flight.	N C-99701-1, S ent Corp, CRS# of ion gauge tool F	O/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A-P340-79 Diamond DA42 S/N-	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241,	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	O/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A-P340-79 Diamond DA42 S/N-	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	, S/N 241, position with a good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS	rning lift detector PASafe Flight Instrume tall warning installate test flight. 02/04/2014 g gear accumulato	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning punctional check was	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning princtional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	
AVIONICS Removed stall wa after overhaul by Diamond DA42 st Aircraft is OK for Signature AMERICAN AVIONICS Serviced landin	rning lift detector P/Safe Flight Instrume tall warning installat test flight. Development of the control of t	N C-99701-1, S ent Corp, CRS# o ion gauge tool F N153TS r with nitroger	P/N 241. Installed same lift dete QA1R419K, work order #3854 P/N D60-2737-11-00. Ground f Certificate A+P34079 Diamond DA42 S/N-n IAW DA42 AMM chapter	ctor, P/N C-99701-1. 3. Set stall warning punctional check was 55 42.118 TAC 29-00-00.	y, S/N 241, position with good.	

ENTRIES.	INSPECTION, REPAIRS & REPLACEMENT DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS. SIGNATURE	LICENCE
		1
	Date: 01/31/14 DIAMOND DA 42 NG N153TS SN: 42.118	
	Land Avidence TAS615 Traffic option in accordance with FAA Form 337 of this date.	
	Processor p/n: 70-2420-8TAS615 s/n: M135009528 Transponder Coupler p/n: 70-2040 s/n: M135009653 Antenna p/n: S72-1750-31L s/n: 11059 (upper)	
	Antenna p/n: S72-1750-32L s/n: 11085 (lower)	
	Regulations. With regard to the work performed, this followard is appearance.	
	Details on file under WO# 125158.	
	Inspector	
Real Line	CRS# 1AMR980Y	
0		
	American Avionics 7023 Perimeter Rd. Seattle, Wa 98108	
	American Avionics 7023 Perimeter Rd. Seattle, Wa 98108 Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	June
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under work order number: 94211	Viae
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	June
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	Viae
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	June
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under work order number: 94211 Signed DANA GERRY CRS# 1AMR980Y	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under work order number: 94211 Signed DANA GERRY CRS# 1AMR980Y	
	Date: 4/14/2014 Tail# N153TS A/C Type: DA42-NG Acft Time: 1562.7 Ldg: Work Performed: REPLACED FPS CONNECTOR AND HARNESS ON LEFT AND RIGHT ENGINES WITH NEW PARTS FROM KIT E4A-90-R18-000 IAW: AUSTRO MM E4.08.04 REV 19 This aircraft was inspected and repaired in accordance with applicable maintenance rules and current FAA Regulations and in regards to the work performed is approved for return to service. Details are on file under parts order number: 94211	


DATE	тот	AL.	TIME	L AIR SINCE G.	NOTE: USE BOTH PAGE	ENGINEERINGS AND AS MANY	LINES AS REQUIRED FOR C	OMPLETE
	HRS.	MIN.	HRS.	MIN.	NOTE: OSE SO			-
BROUGHT								
	1 1	-						_
AMERICA	07/10	2014	N153	BTS	DA42NG S/N 42.11	18	1562.7 Tach & TTAC	
AVIONICS				an mith I	FAR 91.409(a) and FAR	43 appendix D.	Referencing Diamond	
DA42NG ma	inual inspe	ction in	accordan	ce with r	AR 91.409(a) and 1711	45 appendix 2.		
Installed a 2 i	new engine	fuel fil	ters. P/N	WK724	3.			_
Installed 4 ne	w FCII ha	ck un b	atteries P	/N LC-R	127R2P. Next replacement	ent due July 201	5.	
Installed a ne	w ELT bat	tery, P/	N 455-00	12. Inspe	ected and functionally che	ecked ELT per I	FAR 91.207(d), and found	
to be airworth	hy.	emoved	and clear	ned inhos	ard fuel quantity probe. I	Reinstalled prob	e with a new o-ring seal.	
Installed righ	t wing and	secured	all hardy	vare, TK	S lines, and electrical con	nections. Opera	ational check of right fuel	_
quantity indic	cation was	good.						
Serviced bral	ke reservoir	s. Serv	iced all w	heel bear	rings. All gear retraction	and extension	checks good.	
					NG-035/1 not applicable		tuator serial number. 13 by American Avionics,	
					check of both "ALTN FA			_
instructions v			то оро		ment of oom Thomas In	mareurons	pro outroum	_
					ring reinforcement was co	omplied with by	Diamond Aircraft Nov.	
24, 2010, 101 MSP42NG 0							14'03104	
2010, 1015.0	TT per MS	DAONIC	2.018	onnector	assembly was complied	with by Diamor	id Aircraft Nov. 24,	
		H4/NU						
				2014 by	compliance with Austro	RSB-E4-003/13	. Updated both engines	_
MSB42NG-0 EECU softwa	02/12 compare to version	plied wi	th July 1, 3_0_05_1	2014 by 7.	compliance with Austro	RSB-E4-003/13	. Updated both engines	
MSB42NG-0	02/12 compare to version	plied wi	th July 1, 3_0_05_1	2014 by 7.	compliance with Austro	RSB-E4-003/13	. Updated both engines	-0
MSB42NG-0 EECU softwa AD's checked	02/12 compare to version through is	plied wi on VC33 ssue 201	th July 1, 3_0_05_1 14-13.	7.				
MSB42NG-0 EECU softwa AD's checked	02/12 compare to version of through is this aircraft	plied wi on VC33 ssue 201	th July 1, 3_0_05_1 14-13.	7.			. Updated both engines	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con	02/12 compare to version of through is this aircraft addition.	plied wi on VC33 ssue 201 has bee	th July 1, 3_0_05_1 14-13.	7. ed in acc	ordance with an annual i	nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature	02/12 compare to version of through is this aircraft addition.	plied wi on VC33 ssue 201 has bee	th July 1, 3_0_05_1 14-13.	7. ed in acc		nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature	ne to version of through is through is this aircraft addition.	plied wi on VC33 ssue 201 has bee	th July 1, 3_0_05_1 14-13.	7. ed in acc	ordance with an annual i	nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature	02/12 compare to version of through is through is this aircraft dition.	plied wi on VC33 ssue 201 has bee	th July 1, 3_0_05_1 14-13.	7. ed in acc	ordance with an annual i	nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that the airworthy consideration of the second s	02/12 compare to versical through is this aircraft addition.	plied wi on VC33 ssue 201 has bee	th July 1, 3_0_05_1 14-13. en inspect	7. ed in acc	ordance with an annual i Certificate A73407 Registration:	nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature	02/12 compare to version of through is through is this aircraft dition.	plied wipplied wippli	th July 1, 3_0_05_1 14-13. en inspect	7. ed in acc	Certificate An 3407 Registration: Aircraft S/N:	nspection and w 9 <i>SS TA</i> N153TS 42.118		
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature	02/12 compare to version of through is through is this aircraft dition. ALL Date Traft Make	plied wipplied wippli	th July 1, 3_0_05_1 14-13. en inspect	7. ed in acc	ordance with an annual i Certificate A73407 Registration:	nspection and w		
MSB42NG-0 EECU softwa AD's checked I certify that the airworthy considered airworthy consider	ne to versical through is this aircraft dition. ALLI Date traft Make raft Mode	has bee	th July 1, 3_0_05_1 14-13. en inspect	7. ed in acc	Certificate An 3407 Registration: Aircraft S/N: ACTT:	N153TS 42.118 1566.5	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that tairworthy con Signature Airca Removed	ne to versical through is this aircraft dition. ALLI Date raft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Certificate An 3407 Registration: Aircraft S/N:	N153TS 42.118 1566.5	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Airc Removed battery fu	ne to versical through is this aircraft dition. ALLI Date or aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Certificate An 3407 Registration: Aircraft S/N: ACTT:	N153TS 42.118 1566.5	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that tairworthy con Signature Airca Removed	ne to versical through is this aircraft dition. ALLI Date or aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Certificate An 3407 Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Airc Removed battery fu	ne to versical through is this aircraft dition. ALLI Date or aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Airc Removed battery fu	ne to versical through is this aircraft dition. ALLI Date or aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Aircr Removed battery fu	ne to versical through is this aircraft dition. ALLI Date or aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Aircr Removed battery fu	o2/12 commerce to versical through is this aircraft addition. ALLI Dates aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Aircr Removed battery fu	o2/12 commerce to versical through is this aircraft addition. ALLI Dates aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Aircr Removed battery fu	o2/12 commerce to versical through is this aircraft addition. ALLI Dates aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	
MSB42NG-0 EECU softwa AD's checked I certify that t airworthy con Signature Airc Aircr Removed battery fu	o2/12 commerce to versical through is this aircraft addition. ALLI Dates aft Make aft Mode	has bee	th July 1, 3 0 05 1 14-13. en inspect	7. ed in acc	Registration: Aircraft S/N: ACTT:	nspection and w 9 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	vas determined to be in an	

ENTRE	INSPEC	TION, REPAIRS & REPLE THROUGH ANY UNUSED	LACEMENT LINES IN DATE AND TIME	COLUMNS.	SIGNATURE	LICENCE
1 -0.1	Americ	206 763 N/_5_	37S	08		MA FOR
		Performed in accordance with FAI	R Part 43 appendices "E" and "F".			
		. 102	IAW part 43 Appendix "E", paragra IAW Part 43 Appendix "E", paragra			
	/Static S		IAW Part 43 Appendix "F", paragra	nph "a"		
		15588	Date 01/16/2	015		
	Signed L	Hali May	robbonspector CRS#1A	+		
	Signed_#			1		
	ARMERICA	an 5		NATOTO		
	Date:	3/27/2015	Registration: Aircraft S/N:	N153TS 42.118		
	Aircraft Make: Aircraft Model:	Diamond DA42-NG	ACTT:	1566.5		
	Complied with Austro M VC33_0_05_18 using in checks were satisfactory	structions in MSB-E4-0	mond MSB-42NG-002/13 003/16. L/H and R/H EEC	U's were upd	ated. Engine operat	ional
	Signature his Go	acher_A&P	2775150			
	Signature / Signature	A&P	2775150			
				SEATTLE, W	98108	
	AMER Make/Mode Serial Num Registratio	CAN AVIONICS, 70 bl: Diamond DA 42NG ber: 42.118 n Number: N153TS tware and manifest per DIA N	23 PERIMETER RD. S Hobbs: N/A Tach: 1566.5 Date: 31 March 2015	Work/Orde	r: A15751	
	AMERI Make/Mode Serial Num Registratio Verified sof 0 steps 92 – This aircra	EAN AVIONICS. 70 bl: Diamond DA 42NG ber: 42.118 n Number: N153TS tware and manifest per DIA N 99.	Hobbs: N/A Tach: 1566.5 Date: 31 March 2015	Work/Orde	r: A15751 MSB 42NG-003 rev.	

DATE		TAL	TIME	SINCE FG.		E BOTH BA		GINEERING RECO		R COMP
	HRS.	MIN.	HRS.	MIN.	NOTE: U	SE BOTH PA	GES AIT			COMPLETE
BROUGHT FORWARD										
May 12, 2015					vor chec	к, 591.	171,	ABFI, VOT 10	8.6, 0° bea	ring error
-										
						10	ARL	IN'S AIRCRA ERVICE, INC.	FT	
						1	S	ERVICE, INC.		
							36 GALLA (406)-388-1351, FA	X (406)-388-7417, www.arline.com, arline@arlin	s.com	
				27	DATE 7 AUG 2015	REGISTRA N153TS		SERIAL # 42.118	TAC & TOTA 1582.3	AL TIME
			V Viation	ro re 10 EI Rì va Rc Ro Pa	ds. Checked ELT traction check. Cl 1000HR), Replaced ECU batteries P/N U-1620. Replaced two hose P/N A2- eplaced left and ri int system per ins DATE AUG 2015 certify that this air be in an airworth August IA	per 91-207(d). hecked wing, gea i standby attitude N LC-R127-R2P. d L/H Aux fuel p isfo2-04. Cleane ight tail pipe rubl structions. Repla P 1340061 REGISTRA N153TS reraft has been in ry condition	ELT Batte ar and tail ar and tail ar gyro eme. Replaced pump to so did deice fil ber mount: aced left el	es, pulleys, lights, brakes, tery due Aug 2021. Draines bolts. Checked bonding argency battery package P/I fuel filters elements P/N W blenoid valve hose P/N A 24 ind strainer. Replaced nose s P/N 140SCE64010. Spot levator static wick. Reinstate with a secondance with an annual	d sumps. Cleaned gased discharge system (di N D6O-2560-91-00, FWK 724/3. Replaced a 4562-05 and fuel coolectire and wheel bearing repaired inside of cowalled inspection panels TAC & TOTA 1582.3	colator. Ran gear Replaced four ir filters P/N er to solenoid gs and races. lings with fire s and cowl.
	01/21/20	016	N153T		DIAMOND	DA4			TACH:1605.5	
	Service Perform gear sw CLAY L/ 8285 PE SEATTL	ned ring che ACY AV RIMETE	cked go	ood.	llator with	nitrogen	IAW	Emmett Esmond AP3155315	- d	00.
	-	MAI	SOLU NTENAN Skywest Di	NCE	ERO	510 782-6591		AIRFRAM	E ENTRY	
WORK	K ORDER: 95° EL: Diamond I	1 AIRCRA	AFT: N153	TS TAC	H: 1609.4			DATE: 0	03/24/2016	
Replain placar and L	ced the followings (2EA P/N: 1/H engine defra	ing parts w D4D-1127	vith new: L	/H rear se & D60-112		(P/N: DA4-2 th wingwalk s aled interior d ce Manual. –	rephing	30-1), four exterior "Je surfaces (P/N: DA4-1 gs. Leak and ops che	et-A" fuel	


This airframe is approved for return to service, for only the work performed.

Jesse Case A&P 3772878




DATE	SERVICES SERVICES	3 RECORD LINES AS REQUIRED FOR COMPL	ETE
	IFR CERT. TESTS - The Altimeter / Static and Transponder Systems have been tested and inspected per 14 CFR 91.411 & 91.413. The systems were been tested and inspected per 14 CFR 91.411 & 91.413. The systems were		
FORWARD	N Number 153T\$ Tact/Hobbs 0017-7 ACTT 1643-1	and who so there are	
The same of the sa	Date <u>O2-O1- 2017</u> Authorized Signature. P.O. Box 2872 Fullerton CA 92833 Office (714) 525-7545		
MX saero	Date: 4/26/2017 N153TS S/N: 42.118 Total Time: 1698.7 Tach: 1698.7 Hobbs: 91.6	MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.366.4806 Cell: 562.881.534!	5
1. Installed new battery P/N	R624-15M S/N: 40860833 IAW DA42 AMM 24-31-00. Authorized Signature Abel Navarrete AP3773318		
(MX	Date: 5/17/2017 N153TS S/N: 42.118 Total Time: 1719.3 Tach: 1719.3 Hobbs: 116.5	MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.366.4806 Cell: 562.881.5345	-
1. Replaced LH tire P/N: 06-0	7340 and tube P/N : 06-00770 IAW DA42 AMM 32-40-00. Authorized Signature Abel Navarrete AP3773318		
MX	Date: 5/24/17 N153TS S/N: 42.118 Total Time: 1727.6 Tach: 1727.6 Hobbs: 126.1	MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.366.4806 Cell: 562.881.5345	
2. Inspected ELT-system IAI 3. Inspected emergency ba 4. Replaced fuel filters IAIW 5. Compiled with 100 hour 6. Replaced set screw for al 7. ADs current to biweekly 8. Performed ground run of	lubrication IAW DA42NG AMM 12-10-00. ternate air P/n: DA19071-03-01 IAW DA42NG AMM 71-60-00. evision 2017-10		
F-27	Authorized Signature Abel Navarrete AP3773318		
1. Replace	I RH tire P/N 05-07340 and tube P/N 05-0770 IAW DAYS NG AAMA 23-40-00	MX Aero Global LLC 01A E. Spring St. Long Beach, CA 90806 Main: 562.366.4806 Cell: 562.881.5345	
2. Replaced	Authorized Signature Stanley Jijawi AP3704706		
Replaced by brahe and a Dr. a see	Date: 7/18/2017 N153TS S/N: 42.118 Total Time: 1776.3 Tach: 1776.3 Hobbs: 197.7	MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.366.4806	
1. Replaced LH brake pads P/N: RAG6	Authorized Signature Abel Navarrete AP3773318	Cell: 562.881.5345	
	CARRIED FORWARD		

ENGINEERING RECORD



AIR TIME AND

413



THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. ALTIMETERS, ALTITUDE REPORTING EQUIPMENT AND STATIC PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43 TRANSPONDER MAKE: TRANSPONDER MAKE: RIGHT MODEL: S/N: 20,000 20,000 DATE: WO: INSPECTOR: 47805973 451353 9310 Richard 7310 KICACO ELLO
CAROLINA AVIONICS GROUP, LLC CAROLINA AVIONICS GROUP, LLC

STS FAA APPROVED REPAIR STATION # QCCR-389K FAA APPROVED REPAIR STATION # QCCR-389K

CARRIED FORWARD



3330 AIRPORT LOOP SALISBURY NC 28147 OFFICE: 704-431-6862 INFO@SOUTHTECAVIATION.COM

DATE: MARCH 10, 2020 | DIAMOND DA42NG | S/N: 42.118 | REG: N153TS

TACH: 1969.4 HRS. TTAF: 1969.4 HRS.

ANNUAL/200 HOUR INSPECTION COMPLETED THIS DATE IN ACCORDANCE WITH DIAMOND AIRCRAFT DA42NG AMM. DIAMOND AIRCRAFT MANDATORY SERVICE BULLETIN MSB 42-137/1 INSPECTION OF T-YOKE AXLE NUT FOR LOOSENESS, DATED DECEMBER 11, 2019 COMPLIED WITH IN ACCORDANCE WITH DIAMOND AIRCRAFT WORK INSTRUCTION WI-MSB 42-137, DATED OCTOBER 21, 2019. NO FAULTS NOTED. NEXT DUE IN INTERVALS NOT TO EXCEED 200 HOURS

(2169.4 TACH) OR 12 MONTHS (MAR 2021). ELT TESTED IN ACCORDANCE WITH CFR 91.207(D). ELT BATTERY EXP: AUG 2021. REPLACED EMERGENCY BACKUP BATTERY, P/N:(D60-2560-91-00). EXP: MAR 2022.

INSTALLED NEW WITNESS WIRE ON EMERGENCY SWITCH.

REPLACED FADEC BACKUP BATTERIES, P/N:(LC-R127R2P). EXP: MAR 2021.

REMOVED TOP COM ANTENNA AND MOUNTED CI-2580-200 COMANT VHF GPS ANTENNA, S/N:(623460).

REMOVED AND REPLACED STRIPES AND N-NUMBERS. REPLACED CANOPY AND FUEL PLACARDS WITH NEW.

SERVICED MLG AND NLG STRUTS WITH NITROGEN.

REPLACED NLG TIRE WITH GOODYEAR FLT SPEC 500-5 10 PLY.

REPLACED RIGHT MLG TIRE WITH G/Y FLIGHT SPECIAL II 15-6.00X6 6PLY AND TUBE, P/N:(GL-1520B).

REPLACED STALL HORN SPEAKER, P/N:(SC628NDR).

REPLACED AVIONICS SWITCH WITH NEW, P/N:(KIACAAAAAA).

REPLACED FRONT AND REAR CANOPY LOCKS, P/N:(DA4-5210-20-53).

REPLACED FIRE PAINT IN LEFT AND RIGHT COWLINGS.

REMOVED FIRE PAINT ON LEFT AND RIGHT NACELLES BEHIND TURBOS AND REPLACED WITH NEW FIRE SHIELDS, LEFT P/N:(D64-5711-24-00) AND RIGHT P/N:(D64-5711-24-00).

REPLACED LEFT AND RIGHT PROPELLER ICE SHIELDS.

REMOVED ALL QUICK-DRAINS, CLEANED, REPLACED O-RINGS, P/N:(MS29513-006) AND P/N:(MS29513-011); REINSTALLED.

LUBRICATED CABIN/DEFROST CABLES.

REPLACED MISSING RIGHT MLG WHEEL CAP SCREW, P/N:(102-00600).

COMPLIED WITH ATA CHAPTER 51 BONDING INSPECTION, NEXT DUE IN 1000 HOURS TIS (2969.4 TTAF) OR FOUR YEARS

(MAR 2024), WHICHEVER OCCURS FIRST.

REPLACED LEFT INBOARD FUEL PROBE, P/N:(D60-2817-13-000_1) AND LEFT OUTBOUND FUEL PROBE,

P/N:(D60-2817-14-00_1) USING NEW O-RINGS, P/N:(DIN-3771-23.4X3.53). OPS CHECK GOOD.

REPLACED TWO LEFT ENGINE ELECTRIC FUEL PUMPS IN LEFT NACELLE, P/N:(0_580_054_001) USING CUSH WASHERS,

P/N:(DIN7603-A14X20X1.5AL), AND TWO FUEL PRE-FILTERS, P/N:(D64-2810-00-03_1). OPS CHECK GOOD.

REPAINTED BOTH GLARE SHIELDS.

REPAINTED LEFT AND RIGHT PROPELLER SPINNERS.

REPLACED LEFT AND RIGHT FUEL FILTERS, P/N:(WK724_3).

RESEALED REAR DOME LIGHT REFERENCING MSB 42NG-007.

REPLACED LEFT AND RIGHT ANTI-SKID PADS, P/N:(D60-1127-10-53) AND P/N:(D60-1127-10-54).

GEA 71 PUTTING OUT INTERMITTENT INFORMATION. CLEANED TERMINALS AND RESEATED UNIT.

LEFT MLG LEG BONDING WIRE BROKEN, CRIMPED ON NEW TERMINAL END AND REINSTALLED.

LUBRICATED ALL LANDING GEAR SYSTEM.

REPLACED LEFT AND RIGHT AIR FILTERS, P/N:(RU1620).

REPLACED LEFT AND RIGHT BRAKE ROTORS, P/N:(RA164-01501)

REPLACED ALL LEFT AND RIGHT BRAKE LININGS, P/N:(066-10500).

REPLACED LEFT AND RIGHT BRAKE CALIPER PUCK O-RINGS, P/N:(MS28775-222).

BLED LEFT AND RIGHT BRAKE SYSTEMS.

REMOVED PROPELLERS FOR PAINTING AND REINSTALLED.

REPLACED LEFT AND RIGHT WING TIP OUTER STATIC WICKS, P/N:(16630).

REPLACED RIGHT MLG JOINT WITH OVERSIZE JOINT 2: 36MM, P/N:(D64-3217-23-02).

PERFORMED GEAR SWING TO CHECK TIRE CLEARANCE IN WHEEL WELL.

REPLACED RUDDER UPPER ATTACH BEARING, P/N:(SCP8).

REPLACED LEFT FUEL FILTER CRUSH WASHER, P/N:(DIN7603-A8X11.5-AL).

INSTALLED USB POWER SUPPLY, P/N:(200-101A) S/N:(4463) REFERENCING GUARDIAN AVIONIC INSTALL DOCUMENT NO. 250-M AND DRAWING USB 250 REV. A. NO CHANGE TO WEIGHT AND BALANCE.

REPLACED ELEVATOR TRIM BELLOWS, P/N:(K050201001).

REPLACED LEFT AND RIGHT WING T-SEAL, P/N:(DAI-9057-00-01).

INSPECTED AND REPACKED WHEEL BEARINGS.

I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

CHRISTIAN HEDRICK (Muley

A&P 3740465 IA



3330 AIRPORT LOOP SALISBURY NC 28147 OFFICE: 704-431-6862 INFO@SOUTHTECAVIATION.COM


DATE: JULY 9, 2020 | DIAMOND DA42NG | S/N: 42.118 | REG: N153TS TACH: 1970.0 HRS. TTAF: 1970.0 HRS.

REPLACED AHRS WITH GARMIN GRS77, P/N:(011-00868-10) S/N:(42031929).
REPLACED MAGNETOMETER WITH GARMIN GMU44, P/N:(011-00870-000) S/N:(47510495).
REPLACED PFD WITH GARMIN GDU1040 HTR, P/N:(011-00972-03) S/N:(88904254).
RECONFIGURED AND LOADED SOFTWARE.
NO CHANGED TO WEIGHT AND BALANCE.
OPERATIONAL CHECKS OK.

ALL WORK PERFORMED IN ACCORDANCE WITH DIAMOND AIRCRAFT DA42NG AMM.

CHRISTIAN HEDRICK

A&P 3740465 IA



ENGINEERING RECORD

WO: WO_645



Take Flight Aviation LLC - 49 Hangar Road - Montgomery, NY 12549 - 8454574188

DIAMOND AIRCRAFT IND GMBH, DA 42 NG, S/N: 42.118

December 3, 2020

Airframe - page 1 of 1

N153TS TACH: 1984.7

- Completed a 12yr structural inspection as required. Removed wings, Inspected fuel tanks and re-installed as required. Installed (2) LN9037-M6X26 Bolt, Hex, Socket Button Head, Installed (4) LN9037-M6X28 Bolt, D60-9030-00-01 Sealing ring 3/16, Installed (4) LN9037-M6X26 Bolt, Hexagon, Installed (6) 65151 Vent hose, Installed (4) Installed (4) NAS1149F0763P Washer, Installed (48) DIN985-M6-A2 Nut Hexagon, Installed (6) 65151 Vent hose, Installed (4) DA1-2817-10-70 Fuel tank hoses, Installed (16) 15400032 1/4" Hose Crimp Clamp, Installed (4) OR80X3 O-ring, Installed (2) D60-D41-2817-10-70 Fuel tank hoses, Installed (2) D60-9030-00-10 Sealing ring 5/16, Installed (24) DAI-9057-00-01 Fuse wing gap gasket. 2. Removed and replaced LH strobe bulb with new as required. Installed (1) 02-0250276-00 - Whelen A610 Flashtube.

- 4. Removed and replaced alternate air control cable with new. Cleaned and lubricated alternate air valves on both engines as required. Installed (1) D607167-11-00 - Cable LH alternate air.
- 5. Removed and replaced nose wheel bearings and races with new. Installed (2) 08213-20629 Bearing cup, Installed (2) 08125-20629 -
- 6. Removed and replaced nose landing gear centering mount casting with new. Installed (1) D60-3223-10-55 Centering bracket, Installed (1) D60-3223-64-00 - Casting, Installed (1) LFR50-8,NPP.VA - Guide wheel, Installed (1) BU1-08-06-0140-C - Bushing, Installed (1) LN9037-M6X34 - Bolt, Hex...
- 7. Cleaned corrosion from LH main gear spring as required.
- 8. Cleaned corrosion from RH main gear spring as required.
- 9. Removed and replaced LH main gear tire with owner supplied unit as required.
- 10. Removed and replaced corroded hardware on LH main gear with new as required. Installed (2) DIN472-30 Retaining ring, Installed (4) DIN471-10-ZP - Retaining ring.
- 11. Removed and replaced corroded hardware on RH main gear with new as required. Installed (6) DIN471-20-ZP Retaining ring.
- 12. Cleaned connections on Variable stop motor for elevator as required. Functional check satisfactory.
- 13. Inspected aircraft logbooks and found engine replacement on RH engine in logs as required.
- 14. Removed and replaced corroded stabilator hardware with new as required. Installed (8) DIN931-M10X45-YZP Bolt, Installed (8) DIN985-M10-A2 - Nut self locking.
- 15. Removed and replaced corroded vertical stabilizer bolts with new as required. Installed (1) Z-144DI Spring, Installed (1) Z-124AI -Spring, Installed (1) LN9037-M6X84 - Bolt, Installed (1) LN9037-M6X58 - Bolt, Installed (2) DA4-2738-00-70 - Bolt drilled shank, Installed (2) DIN935-M5-A2 - Nut castellated.
- 16. Removed and replaced corroded trim tab bolt with new as required. Installed (4) DIN985-m5-a2 Nut 8mm.
- 17. Cleaned all fuel tanks as required to remove microbial growth.
- 18. Removed corrosion on vertical stabilizer control rod as required. Treated, primed and painted to match aircraft as required.
- 19. Removed horizontal stabilizer static wick, cleaned corrosion and re-installed.
- 20. Adjusted rudder trim friction and lubricated as required.
- 21. Removed and replaced broken bonding straps on RH flap push rod with new as required. Installed (4) stock bonding strap material.
- 22. Serviced hydraulic accumulator to proper pressure as required.
- 23. Re-bonded center fuselage to wing fairing as required.
- 24. Removed and replaced RH main wheel bearings and races with new. Installed (2) 13836 Race, Installed (2) 13889 Wheel bearing.
- 25. Removed and replace LH main wheel bearings and races with new. Installed (2) 13836 Race, Installed (2) 13889 Wheel bearing.
- 26. Removed and replaced LH aileron bonding strap with new.
- 27. Removed and replaced LH rudder pedal mounting bolt with new. Installed (2) LN9037-05020 Bolt, Hex, Socket Button Head.
- 28. Removed and replaced fuel filler cap o-rings with new. Installed (2) BS534 Fuel cap seal, Installed (2) BS338 Fuel Cap, Installed (1) DIN965A-M5X30-A2 - Screw countersunk.
- 29. Installed missing LH auxiliary inline filter as required. Installed (1) QA03152 Inline fuel filter.
- 30. Removed and replaced fuel filter drain valves with new. Installed (4) DA4-9028-17-1 Fuel drain valve.
- 31. Removed RH and LH wing ground plates on top and bottom inboard edges, bonded in new plates, repaired composite laters and ground plane IAW Diamond maintenance manual section 51. Body worked, primed and painted as required.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Take Flight Aviation LLC under work order: WO 645.

James T. Markey IA AP3166872IA

Take Flight Aviation LLC - 49 Hangar Road - Montgomery, NY 12549 - 8454574188

N153TS TACH: 1984.7

DIAMOND AIRCRAFT IND GMBH, DA 42 NG, S/N: 42.118

- 1. Performed Annual inspection I/A/W AC43-13 Appendix D.using Diamond DA42 Aircraft Maintenance Manual as a reference. 2. All interior removed for inspection. Inspected all lines, wires, electrical connections, switches, levers and breakers. No defects noted.
- 3. Aircraft interior and exterior cleaned. Removed engine cowlings and all access panels for inspection. 4. Aircraft placed on jacks. All wheel assemblies removed. Removed, cleaned, inspected, repacked and reinstalled all wheel bearings. All
- tires inspected for wear and proper air pressures verified. Wheel assemblies reinstalled.
- 5. Main battery removed, tested, charged and reinstalled.
- 6. All gear assemblies inspected. Verified proper nitrogen pressures in all oleo struts. Inspected all gear links, gear doors, gear wells, and
- all other gear related pieces. No defects noted. 7. Completed multiple normal gear swings and emergency gear swings. All operations normal. Aircraft removed from jacks.
- 8. Rudder removed for tail inspection. Rudder, rudder hinges, rudder trim tab, rudder gap seal, elevator, elevator push rod, elevator hinges, elevator trim tab, elevator mounting brackets, and elevator mass balance all inspected. No defects noted. Rudder assembly lubricated and reinstalled.
- 9. Inspected Pitot-static probe and stall warning sensor. No defects noted.
- 10. Fuel tanks and fuel interconnecting hoses inspected. All bonding wires inspected. Checked all fuel vents for blockages and proper operation, no blockages found and vents operate normally.
- 11. Inspected inner and outer flap assemblies, ailerons assemblies, hinges and pushrods. No defects noted.
- 12. Inspected inside of engine nacelles. Inspected all wiring, connectors, fuel lines, TKS lines, TKS junction blocks, EECU's and wing main attach bolts. No defects noted.
- 13. Inspected canopy and rear passenger door. Inspected windows, door hinges, and tested door open warning lights. No defects noted.
- 14. Reinstalled all interior panels and seat assemblies. Verified proper operation of seats belts after interior re-installation.
- 15. Hydraulic system components inspected and verified hydraulic fluid level.
- 16. Inspected all systems in rear compartment.
- 17. All flight control cables, pulleys, rudder pedals, control rods and control sticks inspected and lubricated.
- 18. Nose baggage carpets and rear wall removed. Inspected TKS tank & lines, battery compartment & battery, and all lines & electrical connectors/ wiring. Nose baggage door latches inspected and force tested. No defects noted. Reinstalled all carpets and panels.
- 19. ELT inspected I/A/W FAR 91.207(d).
- 20. EECU backup batteries replaced. Due for replacement 12/2021.
- 21. Emergency backup battery and switch inspected. Backup battery replacement due: 12/2021.
- 22. All access panels reinstalled and reinstalled engine cowlings.
- 23. All systems checked for proper operation, no defects noted.
- 24. All other routine service items performed.
- 25. All AD's complied with bi-weekly thru this date.

With respect to the work performed,	this airframe is approved for return to service.	. Details of work performed are on file with Take Flight Aviation
LLC under work order: WO_723.	1	

Diamond

Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N153TS TACH: 2060.2

wo: WO 804

DIAMOND AIRCRAFT IND GMBH, DA 42 NG, S/N: 42.118

May 17, 2021

Airframe - page 1 of 1

Removed broken key body from ignition, Ran aircraft with spare key and functional checked all systems with no issue noted.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Take Flight Aviation LLC under work order: WO_804.

James T. Markey IA AP3166872IA

CARRIED FORWARD



Take Flight Aviation LLC - 49 Hangar Road - Montgomery, NY 12549 - 8454574188

N153TS TACH: 2079.6

DIAMOND AIRCRAFT IND GMBH, DA 42 NG, S/N: 42.118

July 06, 2021

- 1. Performed Annual inspection I/A/W AC43-13 Appendix D.using Diamond DA42 Aircraft Maintenance Manual as a reference.
- Perioring removed for inspection. Inspected all lines, wires, electrical connections, switches, levers and breakers. No defects noted.

 All interior removed ordered electrical engine conditions and ordered electrical engine conditions.
- Air Illies
 Aircraft interior and exterior cleaned. Removed engine cowlings and all access panels for inspection.
- 3. Aircraft placed on jacks. All wheel assemblies removed. Removed, cleaned, inspected, repacked and reinstalled all wheel bearings. All Aircraft placed on Jack and proper air pressures verified. Wheel assemblies reinstalled.
- Main battery removed, tested, charged and reinstalled.
- 5. Main patter, related proper nitrogen pressures in all oleo struts. Inspected all gear links, gear doors, gear wells, and all other gear related pieces. No defects noted.
- 7. Completed multiple normal gear swings and emergency gear swings. All operations normal. Aircraft removed from jacks.
- 7. Completed many and the control of elevator trim tab, elevator mounting brackets, and elevator mass balance all inspected. No defects noted. Rudder assembly lubricated
- 9. Inspected Pitot-static probe and stall warning sensor. No defects noted.
- 10. Fuel tanks and fuel interconnecting hoses inspected. All bonding wires inspected. Checked all fuel vents for blockages and proper operation, no blockages found and vents operate normally.
- 11. Inspected inner and outer flap assemblies, ailerons assemblies, hinges and pushrods. No defects noted.
- 12. Inspected inside of engine nacelles. Inspected all wiring, connectors, fuel lines, TKS lines, TKS junction blocks, EECU's and wing main attach bolts. No defects noted.
- 13. Inspected canopy and rear passenger door. Inspected windows, door hinges, and tested door open warning lights. No defects noted.
- 14. Reinstalled all interior panels and seat assemblies. Verified proper operation of seats belts after interior re-installation.
- 15. Hydraulic system components inspected and verified hydraulic fluid level.
- 16. Inspected all systems in rear compartment.
- 17. All flight control cables, pulleys, rudder pedals, control rods and control sticks inspected and lubricated.
- 18. Nose baggage carpets and rear wall removed. Inspected TKS tank & lines, battery compartment & battery, and all lines & electrical connectors/ wiring. Nose baggage door latches inspected and force tested. No defects noted. Reinstalled all carpets and panels.
- 10 ELT inspected I/AM FAR 91 207(d) Expires August 2021
- 20. EECU backup batteries replaced. Due for replacement 12/2021.
- 21. Emergency backup battery and switch inspected. Backup battery replacement due: 12/2021.
- 22. All access panels reinstalled and reinstalled engine cowlings.
- 23. All systems checked for proper operation, no defects noted.
- 24. All other routine service items performed.
- 25. All AD's complied with bi-weekly thru this date.
- 26. Replaced missing V.G. and repaired two other defective units. Installed (1) D64-5710-06-01 Vortex generator.
- 27. Removed and replaced INOP unit with new. Installed (1) A50828 Position Light (tail).
- 28. Removed and replaced broken terminal.
- 29. Removed and replaced L/H tire with new serviceable tire. Installed (1) 15X6.00-6 TUBE.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Take Flight Aviation LLC under work order: WO_854.

James T. Markey IA AP3166872IA

Airframe - page 1 of 1

wo: WO 1056



Diamond.

Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N153TS

Hobbs: 709.0

Tach: 2107.4

- January 13, 2022
- 1. Installed new alt air cable as required. Adjusted as required. Ops checked good. Installed (1 ft) P/N DA60-7167-11-00 Bowden cable.
- 2. Adjust heat controls as required. Lubricated controls. Ops checked good.

With respect to the work performed, I certify that this airframe has been determined airworthy and is approved for return to service. Details of work performed are on file with Take Flight Aviation LLC under work order: WO_1056.

James I. Markey IA AP3166872IA

AIR TIME AND

		TAL	TIME	L AIR SINCE G.	ENGINEERING RECORD NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	
DATE	HRS.	MIN.	HRS.	MIN.		E
BROUGHT	M	by Insponder	to com	CRS 23 Hol Parama 973 asponder 13 were paply with	Design, Inc R58R222Y Illybrook Road us,, NJ 07652 3-615-3856 Test and Inspections Required performed this date and found 1 FAR 43, Appendix F. 2 345RS/N 3 EH 422212	
	_ Ma	ake/Mode	Details of	f this insp	pection are on	
	We -	ork Order			Date: 3\5\22	
	The	Altime	ter and S	Static sy	ystem tests required by	
	FAI To Wa Sig D&	R 91.41 comply as tested mature:_cD Avio	with FA to: 20	R 43 A	ed this date and found appendix E. Altimeter feet on 3 5 22	
STATE OF THE PARTY	CR	SKJON				
	CR	S KJON				
	CR	SKJON				
	CR	S KJON				
	CR	SKJON				
	CR	SKJON				
	CR	SKJON				· ·
	CR					
	CR					
	CR					
	CR					
	CR					

	N153TS	Heavy Metal Air LLC	Date: 01/	/16/2023
	Make Diamond Model DA-42NG	Westchester County Airport	Tach:	2151.4
ENTR	Carial Number 42.118	White Plains, NY 10604	Ainfrom Tex Lori	2151
	Log Entry Page 1 of 1	914-461-2336	Airframe Total Time:	2151.4
	Performed a 100 HR Inspection I/A with in reference of DA42 AMM ar Installed new ELT battery P/N: 452 interior and exterior cleaned. All in connections, switches, levers, and be removed. Removed, cleaned, inspectinspected. Verified proper nitrogen and all other gear related pieces. Not gear swings. All operations normal new L/H brake lining P/N: 066-105 RC2207681. Installed 4 new EECU light P/N: 461K022801WS S/N: RCC/W S/B SB42-124 Cabin heat, dealternate air P/N: SB42-124KIT. Onoted. All AD's checked and listed	A/W 14 CFR Part 43.13 Appendix D. All and Austro Engine MM. Performed FAR 2-6499, S/N: 395535-052. ELT battery enterior removed for inspection. Inspected preakers, no defects noted. Aircraft place cted, repacked, and reinstalled all wheels pressures in all oleo struts. Inspected all of defects noted. Completed multiple nor an interaction of the complete multiple nor and alternate air cables. Installed not prevait and alternate air and cabin at thru BW 2023-02. Run-up and operation—END——	expiration date JUL/2029. A all lines, wires, electrical ed on jacks. All wheel asse I bearings. All gear assemb II gear links, gear wells, gearmal gear swings and emer I nose strut as needed. Insta N: DA4-2560-91-00, S/N: 98. Installed new flap up pagear inspection, no defects hew Cable kit for cabin head heat, Defrost heat OK, no onal checks of all systems.	Aircraft emblies blies ear doors, rgency alled 4 cosition noted. nt, defrost, o defects - OK.
	2151.4 Date 01/16/2023	in accordance with a 100 HR Inspection and was de	oc in an worthy conditi	
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	peller has been inspected in accordance with an AN 2151.4 Date 01/16/2023. P# 26779101A.	NUAL INSPECTION and	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2	2151.4 Date 01/16/2023	NUAL INSPECTION and	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and o	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and o	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and o	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and o	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and or	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and v	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and o	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and or	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and or	was
	Andy Batista Lecrtify that this Airframe, Engine, Property determined to be in airworthy condition. Time 2 Signed A&F	2151.4 Date 01/16/2023.	NUAL INSPECTION and or	was

71411

N153TS 04/29/23 Tach - - - Hobb's 0806 3 Type Insp. Thru Service

- Engine Power % unattained incleded with ECU Fail notification. Downloaded Terror log from ECU flagged Prop Governor P. & R. with Overhaulted Prop

NOT MIN.

TI

N153TS 12/23/23, Tach 2.188.9. Type Insp: Thru Service Left Main Tire found flat, Jacked, Removed & replaced tube Assy Reinstalled Left Main Wheel Assy and removed Jack I certify that this aircraft has been serviced IAW Diamond Tech Pubs Determined to be in Airworthy Condition, END A&P Print Thomas Tassopulos A&P 2898005 COMPLETE A&P Sign

HRS. MIN. HRS. BROUGHT FORWARD



Airframe Log Entry

Reg#: N153TS S'N: 42 118 Hrs: 849.9

Make: Diamond Date: 04/08/2024 Lnds. NA

Model: DA42-NG

Performed 2 yr pitot/static ops checks. Tested and inspected the pilot's altimeter and Standby automatic pressure altitude reporting systems IAW Title 14 CFR part 91.411 and ATC Transponder tests and inspections IAW title 14 CFR part 91.413(a) and found to comply with the Title 14 CFR part 43, appendices E and F. All tests pass at this time. A/C tested to 20,000ft.

The above described repair or maintenance is approved for return to service. A detailed record is on file under Work Order # KDKPA

Signed: Pedro Roque Q.I. 2736

Duncan Aviation CRS#JGVR194F

Phone: 203-266-2149



DGM Aircraft Maintenance 9100 Republic Airport Rte 109 SB5 Farmingdale NY 11735 631-270-4144

Make: Diamond (Austria)

Model: DA 42 NG Tail: **N153TS**

S/N: 42,118

Hours: Tach: 2188.9 Hobbs: 853.6 A/CTT: 2188.9

Airframe Logbook

Completed 100 Hour inspection in reference to Diamond service manual and FAR 43 Apdx D. Lubed landing gear the wheel hearings. Serviced brains checks will and wheel bearings. Serviced brake system with 5606. Performed normal and FAR 43 Apdx D. Lubed landing gean no defects noted. ELT inspected I/A/W FAR 91.207(d) and checks good. Battery due date 007/2029. Replaced right brake caliper piston O-ring with new P/N: MS28775-222. Replaced left tire inner tube with new P/N: 302-246-401. MS24665-12(X2), LN9348-M4 (X2), LN9037-M4X18. Replaced right fuel filter drain calve with new P/N: CAV180.

- C/W AD 22-06-08 by inspection OK. Next due Tach: 2388.9 - C/W AD 24-06-13 by replacing T-Bolt P/N: D60-5320-00-32, DIn125A-M6, Dim9021-M6-A2 washer, Din985-M2-A2 Nut. An416-1 Pin.

AD's checked thru 2024-15. Run up, leak checks and system checks satis. Approved for return to service.

ENGINE SERVICE AND

N153TS
Make Austro
Model E4P-B
Serial Number E4-B-00135
Log Entry Page 1 of 1
Left Engine

Heavy Metal Air LLC Westchester County Airport White Plains, NY 10604 914-461-2336
 Date
 01/16/2023

 Tach
 2151.4

 Airframe Total Time
 2151.4

 Engine Total Time
 1136.4

 Time Since New
 1136.4

Performed a 100 HR Inspection I/A/W 14 CFR Part 43.13 Appendix D using Diamond DA42 AMM and Austro Engine MM as references. All standard service items complied with. Air intake and turbo charging system inspected. V-Band clamp on turbo charge inspected for defects, none found. Installed new Engine air filter P/N; RU1620. Visually inspected alternator, engine wiring harness and sensors, rear belt drive system, eylinder head drain, full fuel system, waste gale controller, exhaust system, and engine breather line, no defects noted. Drained engine oil and filled with 7 Liters Aeroshell diesel ultra 5W-30. Removed and cut opened oil filter for inspection – OK – replaced with new P/N; E4A-52-100-802 filter. Drained gearbox oil and replaced with SPIRAX-S6-GXME 75W-80. Gear box oil filters removed and inspected for particles, none found. Reinstalled filters and verified proper gear box oil level. Removed and replaced fuel filter with new filter P/N; WK72-I/3. Inspected engine mounts for cracks, deterioration, or loose hardware. Serviced coolant reservoir with peak European vehicles 50/50 antifreeze coolant. Pressure tested coolant system; no leaks found. C/W 900HR injector replacement Installed 4 new Injector P/N; E4A-35-100-000, S/N; RC2105426. All AD's checked and listed thru BW 2023-02. Run-up and operational checks of all systems – OK.

---END---

correspondence to the inspected in accordance with a 100 HR. Inspection and was determined to be in airworthy condition. Time 2151.4 Date 01/16/2023

Signed (My)

A&P# 4039748

Andy Batista



DGM Aircraft Maintenance 9100 Republic Airport Rte 109 SB5 Farmingdale NY 11735 631-270-4144 Make: Diamond (Austria)

Model: DA 42 NG

Tail: N153TS

S/N: 42.118

Hours: Tach: 2188.9 A/CTT: 2188.9 Left EngTT: 1136.9 EngSMOH: 218.9

Left engine logbook

100 Hr. inspection accomplished in reference to Diamond and Austro service manuals. Drained oil, Removed oil filter and inspected oil filter for contaminants, none found. Replaced oil filter with new E4A-52-100-802. Serviced with 7.5 Liters of 5W30LT. Replaced gear box with serviceable P/N: E4A-70-000-000 Rev. ADI S/N: 3811. Gear box total time 1072.6. Serviced with Shell Spirax S6 GXME 75W-80. Installed kit E4A-52-000. Replaced vibrator dampener with new P/N: 90589. Replaced intake hose with new P/N: D64-8126-00-04_3. Replaced 4 exhaust gasket with new P/N: E4A-04000-001. Replaced waste gate gasket E4A-04-000-003. Replaced turbo gasket P/N: E4A-04-000-002 And 4 nuts P/N: DIN934M101.5. Removed Governor and Accumulator send out to MT-Propeller USA, Inc, Reinstalled governor wiring harness and sensors, rear belt drive system, cylinder head drain, full fuel system. Cooling system inspected. leak checks good. Approved for return to service.

Signed:

Name: Gabriel Acevedo Jr

Cert: AP2827501

Date: 08/01/2024

TOTAL SINCE MEG



ENGINEERING RECORD

Date: 08/01/2024 Hours: Tach: 2188.9 Hobbs: 853.6 A/CTT: 2188.9

Tail#: N153TS

Make: Diamond (Austria) Model: DA 42 NG S/N: 42.118

Airframe Logbook

I certify that this aircraft has been inspected in according with an annual inspection and was determined to be in an airworthy condition

Name: William Mundy

Co: DGM Aircraft Maintenance

Cert: AP 2750364 IA

Sign: W. E.

N153TS 11/08/24 L Tach 2198.4 Hobbs 870.2 Jacked Aircraft Removed & Replaced Right Main New Goodyear 15x6.00 6 Ply tire, Serviced to Re and returned aircraft to Airworthy



AIRCRAFT SQUAWK SHEET Please complete all sections where applicable.

Phone(Day): Phone(Evening): is a safety issue or if you ground an aircraft, make sure you verbally notify the
Phone(Evening):
is a safety issue or if you ground an aircraft make sure you verhally notify the
maintenance staff)
(To be filled in by maintenance staff)
PER PAGE M.M 32-50-00

OPS CHECK OF STREETS GOOD AIRCRAFT OK. FOR STRING

Records Officer Signature: _ Date: __ Page 1 of 1 Make Diamond Model DA-42NG Serial Number 42.118 Log Entry Page 1 of 1

Heavy Metal Air LLC Westchester County Airport

White Plains, NY 10604 914-461-2336

Date:

01/16/2023

Tach:

2151.4

Airframe Total Time:

2151.4

Performed a 100 HR Inspection I/A/W 14 CFR Part 43.13 Appendix D. All standard service items complied with in reference of DA42 AMM and Austro Engine MM. Performed FAR 91.207 (d) ELT inspection. installed new ELT battery P/N: 452-6499, S/N: 395535-052. ELT battery expiration date JUL/2029. Aircraft interior and exterior cleaned. All interior removed for inspection. Inspected all lines, wires, electrical connections, switches, levers, and breakers, no defects noted. Aircraft placed on jacks. All wheel assemblies removed. Removed. cleaned, inspected, repacked, and reinstalled all wheel bearings. All gear assemblies inspected. Verified proper nitrogen pressures in all oleo struts. Inspected all gear links, gear wells, gear doors, and all other gear related pieces. No defects noted. Completed multiple normal gear swings and emergency gear swings. All operations normal. Aircraft removed from jacks. Serviced nose strut as needed. Installed 4 new L/H brake lining P/N: 066-10500. Installed new emergency battery P/N: DA4-2560-91-00, S/N: RC2207681. Installed 4 new EECU batteries P/N: NP7-12, S/N: RC2206698. Installed new flap up position light P/N: 461K022801WS S/N: RC2202071. C/W AD 2021-22-03 nose gear inspection, no defects noted. C/W S/B SB42-124 Cabin heat, defrost and alternate air cables. Installed new Cable kit for cabin heat, defrost, alternate air P/N: SB42-124KIT. Operational test of alternate air and cabin heat, Defrost heat OK, no defects noted. All AD's checked and listed thru BW 2023-02. Run-up and operational checks of all systems - OK. ---END---

Teertify that this aircraft has been inspected in accordance with a 100 IIR Inspection and was determined to be in airworthy condition. Time 2151 4 Date 01/16/2023.

Signed ACHPall

A&P # 4039748

Andy Batista

Learning that this Airframe, Engine, Propeller has been inspected in accordance with an ANNUAL INSPECTION and was determined to be in airworthy condition. Time 2151.4 Date 01/16/2023.

Signed

A&P # 26779101A.

Alexander Duran

ISLIP AVIONICS, INC.
CRS# FJIR141K
LI MAC ARTHUR AIRPORT
RONKONKOMA, NY
631-588-3543

AIRCRAFT MAINTENANCE RECORD

DATE:

24-MAY-2023

A/C REG#

N153TS

A/C S/N:

42-118

Replaced defective VHF / GPS WAAS Antenna CI 2580-200 referencing Comant installation manual II A258005 Rev E. Post-installation ground operational test satisfactory.

Addressed autopilot issue – autopilot would not pass pre-flight test. Determined issue to be autopilot software – configuration files missing. Loaded files and configured autopilot. Pre-flight test satisfactory.

All work performed using guidance from AC 43.13-1B (change 1) and AC 43.13-2B as applicable.

Details are on file with this Repair Station under work order 9661. END

Authorized Signature:

N153TS 12/23/23, Tach 2,188.9, Type Insp: Thru Service Left MainTire found flat, Jacked, Removed & replaced tube Assy Reinstalled Left Main Wheel Assy and removed N153TS 04/29/23, Tach ---- Hobb's 0806 3 Type Insp. Thru Service Jack. I certify that this aircraft has been serviced IAW Diamond Engine Power % unattained incleded with ECU Fail notification. Downloaded Error log from ECU flagged Frop Governor R & R with Overhaulied Prop Gov Tech Pubs Determined to be in Airworthy Condition, END Accomplished Ground Run Up & Leak checks All Run Up & Ops Check Good A&P Print: Thomas Tassopulos A&P 2898005 certify that This Properler's been serviced (AVV Diamond & MT Propeller & Determined to be in Ainvorthy Condition END LINES AS REQUIRED FOR COMPLETE NOT MIN. HRS. MIN. HRS. BROUGHT FORWARD Airframe Log Entry Model: DA42-NG Make: Diamond Reg#: N153TS Date: 04/08/2024 S'N: 42.118 Lnds: NA Hrs: 849.9 Performed 2 yr pitot/static ops checks. Tested and inspected the pilot's altimeter and Standby automatic pressure altitude reporting systems IAW Title 14 CFR part 91.411 and ATC Transponder tests and inspections IAW title 14 CFR part 91.413(a) and found to comply with the Title 14 CFR part 43, appendices E and F. All tests pass at this time. A/C tested to 20,000ft. The above described repair or maintenance is approved for return to service. A detailed record is on file under Work Order # KDKPA Signed: Pedro Roque Q.I. 2736_ Duncan Aviation CRS#JGVR194F Phone: 203-266-2149 **DGM Aircraft Maintenance** Diamond (Austria) Make: 9100 Republic Airport Rte 109 Model: DA 42 NG Tail: **N153TS** Farmingdale, NY 11735 S/N: 42.118 Tach: 2188.9 Hobbs: 853.6 A/CTT: 2188.9 Hours: Airframe Logbook Completed 100 Hour inspection in reference to Diamond service manual and FAR 43 Apdx D. Lubed landing gear and wheel bearings. Serviced brake system with 5606. Performed normal and emergency gear extension checks with no defects noted. ELT inspected I/A/W FAR 91.207(d) and checks good. Battery due date 007/2029. Replaced right brake caliper piston O-ring with new P/N: MS28775-222. Replaced left tire inner tube with new P/N: 302-246-401. Replaced left main fuel tank drain valve with new P/N: CAV180. Replaced Elevator trim hardware with new P/N: MS24665-12(X2), LN9348-M4 (X2), LN9037-M4X18. Replaced right fuel filter drain calve with new P/N:CAV180. Insp/lubed flight controls. - C/W AD 22-06-08 by inspection OK. Next due Tach: 2388.9 - C/W AD 24-06-13 by replacing T-Bolt P/N: D60-5320-00-32, DIn125A-M6, Dim9021-M6-A2 washer, Din985-M2-A2 Nut, AD's checked thru 2024-15. Run up, leak checks and system checks satis. Approved for return to service. Signed: Name: **Emanuel Castano** Cert: A 4556937 Date: 11/01/2024

ENT								
	Date: Tail#:	11/01/2024 H N153TS	lours: Tach: 2188.9	Hobbs: 853.	6 A/CTT: 2188.9			
	Make:	Diamond (Aus	tria) Model: DA 4	2 NG	S/N: 42	118		
		Logbook						
	I certify t	hat this aircraft determined to t	has been inspected be in an airworthy co	in according	with an annual i	nspection		
		William Mundy			ert: AP 27503	64 IA		
	RETICE AR	DGM Aircraft M	aintenance	Si	gn: Wulkam	14		
							T	
Jack New Rem	ed Air Good oved	year 15 Jack ar	emoved a second	Rep Ply tire ed airc	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
Jack New Rem A&P	ed Air Good oved Print:	craft Re year 15 Jack ar Thoma	emoved & 5x6.00 6 Id returns Is Tassor	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
Jack New Rem A&P	ed Air Good oved Print:	craft Re year 15 Jack ar Thoma	emoved 8 5x6.00 6 l id returne	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
Jack New Rem A&P * A&P	ed Air Good oved Print:	year 15 Jack ar Thoma	emoved a x6.00 6 of returned a Tassop	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P N153TS 06/3 Serviced Left both Main Tir bracket Aircr	ed Ail Good Good Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Love	emoved a signal of the state of	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Low to Service END poulos.	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Love	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Low to Service END poulos.	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Low to Service END poulos.	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Low to Service END poulos.	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS
New Rem A&P A&P N153TS 06/3 Serviced Left both Main Tir bracket. Aircr A&P Print: Th	ed Ail Good Oved Oved Print: # 28	year 15 Jack ar Thoma 2201 Hobbs 876 In Gear Strut, Sell Nose Gear Low to Service END poulos.	emoved 8 5x6.00 6 Id returne A&P Sig 6.7 Proced ver Clamp	Rep Plytin d airc soulos	laced Rose, Service raft to A	ght Ma ed to	ain T Requ	uired PS

AIR TIME AND

	DAI		TIME	SINCE	WOTE USE BOTH PAGE	ENGINEERING RECORD
DATE	HRS.	MIN.	HRS.	MIN.	NOTE: USE BOTTO	
ROUGHT						
RWARD	1					
-						Log Book Entry
	N					
TITA	TT	TIT) 1			
VEN						
AVIATION MO	BILE AIRCRAFT S	SERVICES [/	AVIONICS			
8100 Republic	and the second s					
Farmingdale N' United States	Y 11735			Teleph	one: 631-756-5500	Email: Maint@ventura.aero
Registration: N					al Number: 42.118 ch Time: 2220.3 Hrs	Work Order: NY1970 Engine TT 1205.3 Hrs
1anufacturer: I 1odel Number:					bbs Time 906.0 Hrs	September 3 rd 2025
omplied With/P	erformed Th	ne Follov	ving Inspec	ctions/Ma	aintenance:	
		(C+	mer Sunnli	ad) Elast	trical Connector On Last Engi	ne Waste Gate Control Valve.
1. In	istalled Nev	v (Custoi	nei Suppn	iea) Elect	trical Connector On Lett Engl	ne waste date control valve.
R	un Up And	Ops Che	ck OK.			ne waste Gate Control valve.
2. R	un Up And epaired Lef	Ops Che t Engine were rep	ck OK. Turbo Inle	et Duct Tu	ube As Needed.	t Federal Aviation Regulations and the Aviation under Work Order NY1970
2. R The items iden repairs are a	un Up And epaired Lef	Ops Che t Engine were rep	ck OK. Turbo Inle	et Duct Tu	ube As Needed.	t Federal Aviation Regulations and the
2. R	un Up And epaired Lef	Ops Che t Engine were rep	ck OK. Turbo Inle	et Duct Tu	ube As Needed.	t Federal Aviation Regulations and the
2. R The items iden repairs are a	un Up And epaired Lef	Ops Che t Engine were rep	ck OK. Turbo Inle	et Duct Tu	ube As Needed.	t Federal Aviation Regulations and the Aviation under Work Order NY1970
2. R The items iden repairs are a	un Up And epaired Lef	Ops Che t Engine were rep	ck OK. Turbo Inle	et Duct Tu	ube As Needed.	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a	un Up And epaired Left above approved for	Ops Che the Engine were reported to the contract of the contra	aired and/o service. F	or inspector or inspector or inspector of the control of the contr	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a	un Up And epaired Left above approved for	Ops Che the Engine were reported to the contract of the contra	aired and/o service. F	or inspector or inspector or inspector of the control of the contr	ube As Needed.	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a second secon	un Up And epaired Left above approved for	Ops Che tengine were rep return to	aired and/o service. F	or inspector and the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a second secon	un Up And epaired Left lified above approved for the second secon	Ops Che tengine were rep return to	aired and/oservice. F	or inspection of the contract	ted in accordance with current details are on file with Ventural	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a second repairs are a second repair and repairs are a second repair and repair	un Up And epaired Left lified above approved for the proved for th	Ops Che tengine were rep return to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items identer repairs are a second repairs are a second repair and repairs are a second repair and repair	un Up And epaired Left lified above approved for the proved for th	Ops Che tengine were rep return to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced to aircret	un Up And epaired Left tified above approved for the proved for th	Ops Che tengine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced and are a serviced	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced and are a serviced	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced to aircret	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced and are a serviced	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented and repairs are a second s	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced and are a serviced	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970
The items idented are a serviced to the servic	un Up And epaired Left tified above approved for the ML	Ops Chet Engine were repreturn to	aired and/oservice. F	or inspection of the second of	ted in accordance with current details are on file with Ventura	t Federal Aviation Regulations and the Aviation under Work Order NY1970

CARRIED FORWARD