

**ROTAX.**

# ENGINE LOG BOOK

NO.: E79 / ORL/H

109-244

FOR ROTAX 2-STROKE AND 4-STROKE AIRCRAFT ENGINES

EDITION: 2020 07 01 | PART NO.: 898023

A BRP BRAND



2

Engine Log Book No.: 109-244 for piston engine

Type of engine: **912**

Model: **S2-01**

Engine serial no.: **9.139.965**

Manufacturer: **BRP-Rotax GmbH & Co KG  
A-4623 Gunskirchen, Austria**

Year of manufacture: **20.10.2021**

Data sheet: **EASA.E.121**

Take off power: **73,5** kW perm. duration: **5** min. at: **5800** r.p.m

Max. cont. power: **69** kW at: **5500** r.p.m.

*The above mentioned engine is considered to be operationally reliable if operated and maintained in accordance with the Civil Aircraft and Civil Aviation Equipment Order, current issue and the pertinent operational and maintenance instructions.*

*For relevant Airworthiness Directives (AD) see EASA Website and also check with your local aviation authority (e.g. EASA, FAA TC, CAA,....).*

Remarks: **none**

**For Instructions of Continued Airworthiness (ICAs) like e.g. relevant Service Bulletins etc. see the current SL-2ST-013, SL-912-021, SL-914-019 List of Applicable Publications for ROTAX Aircraft Engines and its reference to ROTAX® Aircraft Engines website [www.flyrotax.com](http://www.flyrotax.com)**

Date: **02.12.2021**

Signature:

BRP-Rotax GmbH & Co KG  
AT.21 G.0006  
R. Freinberger 31420



Status of Airworthiness Directives or modifications effective at 0 hours and at the time of production.

Date:

Signature &  
Licence no.:

applicable SB: **912-042r1, 912-057r1.**

optional SB: **912-037r1.**

not applicable:

**912-022, 912-028r1, 912-029r3, 912-030r1, 912-031, 912-033, 912-039, 912-040r1, 912-041r2, 912-043r2, 912-045, 912-046, 912-047, 912-048, 912-049, 912-051, 912-052r4, 912-053, 912-054, 912-055, 912-056r1, 912-058, 912-059, 912-060, 912-061r1, 912-062r2, 912-063r1, 912-064r1, 912-066r1, 912-068r1, 912-070r1, 912-071, 912-073, 912-074, 912-075.**

BRP-Rotax GmbH & Co KG  
AT 21 G.0006  
R. Freinberger 31420

02. 12.  
2021

applicable AD: **none**

not applicable / performed AD:

**2006-0316R1: Engine - Magnetic Plug - Inspections; Note: not applicable (unlisted engine serial number)**

**2007-0025: Engine - Crankcase - Inspections; Note: not applicable; (unlisted engine serial number and crankcase)**

**2007-0060R1-E: Engine Fuel and Control - Fuel Pump - Replacement; Note: not applicable (unlisted fuel pump)**

**2007-0155: Engine Fuel and Control - Coolant Specification - Modification; Note: adjusted manuals**

**2011-0224-E: Engine - Crankshaft - Inspection; Note: not applicable (unlisted crankshaft)**

**2011-0067-E: Ignition - Magneto Flywheel Hub Washer - Replacement; Note: not applicable (unlisted engine serial number)**

**2012-0019-E: Engine Oil - Oil Pump and Attachment Bolts - Inspection; Note: not applicable (unlisted engine serial number)**

**2012-0097R1: Engine Fuel and Control - Fuel Pump Pressure Side Hose - Replacement; not applicable (unlisted fuel pump)**

**2013-0117-E: Engine - Cylinder Head Section - Inspection / Replacement; Note: not applicable (unlisted cylinder head - installed part number not affected)**

**2015-0240: Engine - Engine Cylinder Head - Inspection / Replacement; Note: adjusted manuals**

**2016-0144; ATA 73 - Engine Fuel and Control - Float - Inspection / Replacement; Note: installed part number of floats not affected**

**2017-0208; ATA 72 - Reciprocating Engine - Valve Push Rod Assembly - Inspection / Replacement; Note: installed parts are not affected;**

BRP-Rotax GmbH & Co KG  
AT 21 G.0006  
R. Freinberger 31420

02. 12.  
2021

10/28/25, 9:44 AM

## Flight Schedule Pro



Aviation

4850 Spartan Dr, Denton, TX 76207

Office: (866) 383-2400 - Fax: (940) 3381-3555

WO19647 - N330VA - Tecnam - P-2006T - S/N: 348

LH ENG: - S/N: 9.139.965 - LH PROP: - S/N: 211167.0

RH ENG: - S/N: 10.005.059 - RH PROP: - S/N: 211165.0

ACTT: 836.30 - TACH: 836.30 - HOBBS: 851.70

LH ETT: 836.30 - LH TSMO: 836.30 - LH PTT: 836.30

RH ETT: 844.70 - RH TSMO: 844.70 - RH PTT: 844.70

Aircraft was found to have been delivered with no record of FAA AD compliance on this engine. The manufacturer complied with EASA AD's were cross-referenced against FAA AD's via the FAA Dynamic Regulatory System to ensure FAA airworthiness requirements were met. The following are the results. Complied with AD 2019-10-04. Serial number of engine not affected. No further action required. Complied with AD 2016-23-04. Engine serial number not affected and engine was manufactured with new parts outside of affected date range. No further action required. AD 2016-13-04 complied with at time of manufacture by compliance with EASA 2015-0240, method of compliance was modification and adjustment of cockpit instrumentation and adjustment of manuals. No further action required. Complied with AD 2013-15-19. Serial number of engine not affected by AD. No further action required. AD 2012-16-13 C compliance was performed at time of manufacture by compliance of EASA AD 2012-0097R1, fuel pump not listed. No further action required. Complied with AD 2012-04-03. Serial number of engine not affected. No further action required. AD 2011-25-02 compliance was performed at time of manufacture by compliance with EASA 2011-0224-E, crankshaft not listed. No further action required. Complied with AD 2011-12-04. Serial number of engine not affected by AD. No further action required. A.D. 2010-18-14 complied with at manufacture by compliance with EASA A.D. 2007-0060R1-E, fuel pump not listed. No further action required. Complied with AD 2002-16-07. Serial number of engine not affected. No further action required.

Landon Reeder A&amp;P 4369883 Date: 10/28/25 Signature:



**Maintenance record:**

Date:	Engine hours:		Work performed:	Signature & Licence no.:
	TSN:	TSO:		



**luciano sorlini** epa VIA MARCONI, 33 CARZAGO RIVIERA (BS) C.A. IT.145.0275

ENGINE:	912S23-01 ROTAX	S/N 9139965
WORK:	INST. PROPELLER GOV. DRIVE	DATA: 16.12.2021
WORK REPORT N°:	2691	TOT. HOURS: 00:00

**WORK PERFORMED : INSTALLATION OF PROPELLER GOVERNOR DRIVE WITH GEARBOX MODIFICATION FROM S2 TO S3 (I.A.W. ROTAX SI-912-031R1) I.A.W. H.M.M. 899603 AND WORK REPORT 2691 OF SORLINI.**

**A.D. AND ROTAX S.B. PERFORMED**

- AD 2017-0208 PERF. INSP. OF VALVE PUSH-ROD ASSY AND ROCKER ARMS, NOT AFFECTED (SB-912-070R1)
- AD 2016-0144 PERF. INSP. FLOATS NOT AFFECTED
- AD 2013-0117-E PERF. INSP. CYLINDER HEADS NOT AFFECTED (ASB-912-062)
- AD 2012-0097R1 PERF. INSP. FUEL PUMP NOT AFFECTED (ASB-912-061)
- AD 2011-0224-E PERF. CRANKSHAFT INSP. NOT AFFECTED
- ROTAX SI-912-031R1 PERF. CHANGE OF GEARBOX CONFIGURATION FROM S2 TO S3

**Dichiarazione di riammissione in servizio / release to service**

Certifies that unless otherwise specified, the works was accomplished in accordance with EASA PART 145 and in respect to that works the engines is considered ready for release to service.

certifying staff  
 ing. ~~SORLINI~~ Mancini  
 M. Gomancini  
 C.I.T. N° 10180365

**MAINTENANCE RECORD**

Date:	April 14, 2023	Page 1 of 1 Pages	Reg. No:	N330VA
Aircraft:	TECNAM P2006T	Serial #:	348/US	Total Time / L Tach / R Tach: 101.1 / 101.1 / 100.5
#1 Eng:	<b>BRP-Rotax GmbH 912 S3</b>	Serial #:	<b>9.139.965</b>	<b>Total Time: 101.1</b>

The below listed items were accomplished in accordance with current FAA regulations, manufacturer's technical data, and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [ ], followed, in bold, directly by AD notes and SB's.


Work Order 082304561

- [500] Annual, and TECNAM 50-, and 100-hour Inspections performed, in accordance with the **TECNAM P2006T Aircraft Maintenance Manual, Doc. No. 2006/045, 3<sup>rd</sup> Edition – Rev. 2, July 21<sup>st</sup>, 2022.**
- [500] Performed Rotax 50-hour and 100-hour inspections as required, no defects noted. All work performed I/A/W **BRP – Rotax MM Chapter Date: July 01, 2021, Rev 1.**
- [500] Drained # 1 Engine S/N 9.139.965, engine oil, removed and inspected oil filter, installed new oil filter, P/N 825-01600 and oil tank drain gasket, P/N 250-010, serviced engine with 3 liters of Aeroshell Sport Plus 4 Aviation Oil. All work performed I/A/W **Rotax MML Date: July 01, 2021, Rev 1.**
- [452] **AD 2005-01-14 (02/15/2005) Valve train on all engines: C/W by inspection I/A/W, Rotax SB-912-040, Date: Aug/2003, Rev. 1., AD is N/A by engine serial number, left 9.139.965, right 9.139.966, I/A/W AD 2005-01-14, Paragraph [F].**
- [453] **AD 2010-20-23 (11/08/2010) Engine crankcase: C/W by inspection in accordance with, I/A/W, AD 2010-20-23, Paragraph C. AD is N/A by engine crankcase serial number, left 21 5130, right 21 5131.**
- [454] **AD 2011-25-02 (12/22/2011) Crankshaft: C/W by inspection I/A/W, Rotax SB-912-059, Date: Nov. 2011, AD is N/A by engine serial number, left 9.139.965.**
- [455] **AD 2016-13-04 (07/27/2016) Engine coolant temperature limit: C/W by inspection, I/A/W AD 2016-13-04 Paragraph C. AD is N/A by engine cylinder head part number installed, 6623753.**
- [456] **AD 2016-23-04 (12/07/2016) Carburetor floats: PCW EASA AD 2016-0144, Date: Dec.07, 2016 AD is N/A by affected part number carburetor floats are not installed, no further action required.**
- [458] **AD 2014-11-09 (07/15/2014) Power Plant: AD is not due at this time, due 600 hours TIS not exceeding 625 hours TIS.**
- [459] **AD 2015-02-09 (03/05/2015) Engine Exhaust: C/W by inspection I/A/W, AD2015-02-09 Paragraph [f], [1], & Tecnam SB170-CS Ed. 1 Rev. 2, no defects noted, One time Inspection per paragraph [f].**
- [003] Adjusted LH & RH Alternator belt tension to proper tolerance, I/A/W **BRP-Rotax MML 12-20-00.**

I certify that this engine has been inspected in accordance with a 100-Hour Inspection and was determined to be in airworthy condition.

Signed \_\_\_\_\_

Central Flying Service, LLC.  
2301 Crisp Drive, Little Rock, AR 72202



Thomas Papka  
Phone: (501) 375-3245, (800) 888-5387

CRS No. HBKR587E  
FAX (501) 975-9596

# Maintenance record:

## MAINTENANCE RECORD

Date:	April 14, 2023	Page 1 of 1 Pages	Reg. No:	N330VA
Aircraft:	TECNAM P2006T	Serial #:	348/US	Total Time / L Tach / R Tach: 101.1 / 101.1 / 100.5
#1 Eng:	BRP-Rotax GmbH 912 S3	Serial #:	9.139.965	Total Time: 101.1

The below listed items were accomplished in accordance with current FAA regulations, manufacturer's technical data, and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [ ], followed, in bold, directly by AD notes and SB's.

### Work Order 082304561

- [500] TECNAM 50 and 100 hour Inspections performed, I/A/W the TECNAM P2006T Aircraft Maintenance Manual, Doc. No. 2006/045, 3<sup>rd</sup> Edition – Rev. 2, July 21<sup>st</sup>, 2022.
- [500] Performed Rotax 50-hour and 100-hour inspections as required, no defects noted. All work performed I/A/W BRP – Rotax MM Chapter Date: July 01, 2021, Rev 1.
- [500] Drained # 1 Engine S/N 9.139.965, engine oil, removed and inspected oil filter, installed new oil filter, P/N 825-01600 and oil tank drain gasket, P/N 250-010, serviced engine with 3 liters of Aeroshell Sport Plus 4 Aviation Oil. All work performed I/A/W Rotax MML Date: July 01, 2021, Rev 1.
- [452] AD 2005-01-14 (02/15/2005) *Valve train on all engines: C/W* by inspection I/A/W, Rotax SB-912-040, Date: Aug/2003, Rev. 1., AD is N/A by engine serial number, left 9.139.965, right 9.139.966, I/A/W AD 2005-01-14, Paragraph [F].
- [453] AD 2010-20-23 (11/08/2010) *Engine crankcase: C/W* by inspection in accordance with, I/A/W, AD 2010-20-23, Paragraph C. AD is N/A by engine crankcase serial number, left 21 5130, right 21 5131.
- [454] AD 2011-25-02 (12/22/2011) *Crankshaft: C/W* by inspection I/A/W, Rotax SB-912-059, Date: Nov. 2011, AD is N/A by engine serial number, left 9.139.965.
- [455] AD 2016-13-04 (07/27/2016) *Engine coolant temperature limit: C/W* by inspection, I/A/W AD 2016-13-04 Paragraph C. AD is N/A by engine cylinder head part number installed, 6623753.
- [456] AD 2016-23-04 (12/07/2016) *Carburetor floats: PCW EASA AD 2016-0144, Date: Dec.07, 2016* AD is N/A by affected part number carburetor floats are not installed, no further action required.
- [458] AD 2014-11-09 (07/15/2014) *Power Plant: AD is not due at this time, due 600 hours TIS not exceeding 625 hours TIS.*
- [459] AD 2015-02-09 (03/05/2015) *Engine Exhaust: C/W* by inspection I/A/W, AD2015-02-09 Paragraph [f], [1], & Tecnam SB170-CS Ed. 1 Rev. 2, no defects noted, One time Inspection per paragraph [f].
- [003] Adjusted LH & RH Alternator belt tension to proper tolerance, I/A/W BRP-Rotax MML 12-20-00.

I certify that this engine has been inspected in accordance with a 100-Hour Inspection and was determined to be in airworthy condition.

Signed  
 Central Flying Service, LLC.  
 2301 Crisp Drive, Little Rock, AR 72202

  
 Steve Hoover  
 Phone: (501) 375-3245, (800) 888-5387

CRS No. HBKR587E  
 FAX (501) 975-9596




Created 09/18/2023 S/N 9.139.965 Engine 1 Tach 185.60 TTIS 185.60

TSOH 185.60

Completed a 100 HR inspection IAW FAR 43 app. D with reference to BRP-Rotax maintenance manual 5-20-00 and Tecnam P2006T Maintenance manual 05-20. Researched AD's through Bi-weekly report 2023-19 No applicable AD's due at this time. Compressions #1 79/80 #2 79/80 #3 79/80 #4 79/80. Drained oil sump removed and cut open oil filter. No metal found. Removed and inspected magnetic drain plug. No metal found. Installed oil filter P/N 825016. Serviced oil sump with 3l of Aeroshell sport+4. Replaced all spark plugs with P/N 297658. Completed 200 HR carburetor inspection using overhaul kit 996-846 and completed carburetor synchronization with reference to BRP-Rotax maintenance manual 12-00-00 and 12-20-00.

I certify that this engine has been inspected in accordance with a 100 HR inspection and was determined to be in airworthy condition.


Logan Baker P#4638550 Date 9/18/23 Signature 



Created 11/03/2023 S/N 9.139.965 Engine 1 Tach 227.30 TTIS 227.30

TSOH 227.30

Completed a 50 HR inspection IAW FAR 43 app. D with reference to per Tecnam P2006T MM and Rotax MM. Drained oil sump, removed and cut open oil filter. No metal found. Installed oil filter P/N 825016. Serviced oil sump with 3 Qts of Aeroshell sport plus 4


Josh Kennedy A&P#4653415 Date: 11/3/23 Signature: 



Created 12/05/2023 Model: 912 S2-01 S/N 9.139.965 Engine 1 Tach 282.30 TTIS 282.30 TSOH 282.30

Completed an 100 HR Inspection IAW FAR App. D with reference to BRP-Rotax Maintenance Manual 05-20-00 and TE CNAM P2006T Maintenance Manual 05-20. Researched AD's through Bi-Weekly report 2023-25. No applicable AD's due at this time. Compressions #1 70/80 #2 70/80 #3 70/80 #4 70/80. Drained oil sump, removed and cut open filter. No metal found. Removed and inspected magnetic drain plug. No metal found. Installed new oil filter P/N 06-07276. Serviced oil tank with 3 liters of AeroShell Sport+ 4. Removed, inspected, cleaned and reinstalled spark plugs.

I certify that this engine has been inspected in accordance with 100 HR inspection and was determined to be in airworthy condition.


Dominic Blewett # P 4848287 Date: 12/5/23 Signature: 







Created 12/05/2023 Model: 912 S2-01 S/N 9.139.965 Engine 1 Tach 282.30

TTIS 282.30 TSOH 282.30

Flushed Coolant system with distilled water and serviced it with 50/50 coolant mixture shellzone dexcool per Rotax M.M. CH 12-20.

Josh Kennedy A&P#4653415 Date: 12/5/23 Signature: 

**Maintenance record:**

 <b>Engine hours:</b>		<b>Signature &amp; Licence no.:</b>		
<p>Created <b>12/14/2023</b> Model: <b>912 S2-01</b> S/N <b>9.139.965</b> Engine 1 Tach <b>300.60</b> TTIS <b>300.60</b> TSOH <b>300.60</b></p> <p>Drained oil. Added 3 liters of Aeroshell sport plus 4 BRP-Rotax Maintenance Manual.</p> <p>Josh Kennedy A&amp;P#4653415 Date: 12/14/23 Signature: </p>				
				
<p>Created <b>12/27/2023</b> Model: <b>912 S2-01</b> S/N <b>9.139.965</b></p> <p>Engine 1 Tach <b>333.10</b> TTIS <b>333.10</b> TSOH <b>333.10</b></p> <p>Completed a 50 HR inspection IAW FAR 43 app. D with reference to per Tecnam P2006T MM and Rotax MM. Drained oil sump, removed and cut open oil filter. No metal found. Installed oil filter P/N 825-016. Serviced oil sump with 3 Qts of Aeroshell sport plus 4.</p>				
<p>Josh Kennedy A&amp;P#4653415 Date: 12/27/23 Signature: </p>				



Created 02/13/2024 N330VA Tecnam P2006T S/N 348/US. Engine 1 363.00 TTIS 363.00

Replaced faulty of temp sensor probe on LH engine P/N986-385 using Rotax MM 76-70-00 as reference. Performed ops check and test flight. No defects noted.

Landon Reeder #A&P Pending Date: 2/13/24 Signature:

Signature &  
Licence no.:



Created 03/01/2024 Model: 912 S2-01 S/N 9.139.965 Engine 1 Tach

376.70 TTIS 376.70 TSOH 376.70

Completed a 100, 200, 400 HR inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20-00 and BRP-Rotax maintenance manual 5-20-00. Researched AD's through bi-weekly report 2024-04. No applicable AD's due at this time. Compressions #1 79/80 #2 79/80 #3 79/80 #4 78/80. Drained oil sump, removed and cut open oil filter. no metal found. Inspected magnetic plug no metal found. Installed oil filter P/N AA825706 , cleaned oil sump tank complying with the 50Hr inspection for use of leaded fuel. Serviced oil sump with 2.8L of Aeroshell Sport plus 4. Installed 8 new spark plugs P/N297656. Removed both Carburetors for inspection and cleaning with reference to BRP-Rotax heavy Maintenance manual 73-00-00. Completed check of carburetor float weights, weights as follows Inboard carburetor 6.28G outboard carburetor 6.28G. Installed carburetor gasket and or ring set P/N 996946. Reassembled carburetors, reinstalled carburetors and completed mechanical and pneumatic synchronization. Completed Propeller friction torque in free rotation of gearbox with overload clutch. Actual friction torque 58Nm.

**I certify that this engine has been inspected in accordance with 100 HR inspection and was determined to be in airworthy condition.**

Logan Baker P#4638550 Date: 3/1/24 Signature:



KC

Created 04/26/2024 Model: 912 S2-01 S/N 9.139.965 Engine

1 Tach 461.00 TTIS 461.00 TSOH 461.00

Completed a 100 HR inspection IAW FAR 43 app. D with reference to BRP Rotax maintenance manual line 05-20-00. Researched AD's through bi-weekly report 2024-08. No applicable AD's due at this time. Compressions #1 79/80 #2 79/80 #3 79/80 #4 79/80. Drained oil sump, Removed and cut open oil filter, inspected magnetic plug No metal found. Installed oil filter P/N 825016. Cleaned oil tank for using more than 30% leaded fuel with reference to Rotax Line maintenance manual 12-20-00. Serviced oil sump with 2.8 L of Aeroshell sport 4 plus. Replaced 8 Sparkplugs P/N 297656. Replaced leaking valve cover gasket on #2 cyl P/N 250-285

**I certify that this engine has been inspected in accordance with a 100 HR inspection and was determined to be in airworthy condition.**

Logan Baker P#4638550 Date: 4/26/24 Signature:




Signature & License no.:

Blank lines for signature and license number.

04/29/2024, N330VA, Rotax Model: 912 S2-01, S/N: 9.139.965, #1 Position, Tach: 461.0, TTIS: 461.0. This engine has been inspected for an Annual Inspection IAW Part 43 Appendix D and used BRP Rotax MM PN: 899169, section 05-20-00 for reference. All AD's are current up through FAA Biweekly 2024-08. I certify that this engine has been inspected for an Annual Inspection and has been determined to be in airworthy condition and is approved for return to service. ---END---


William A. Latham, Jr. AP3557002IA.



**Maintenance record:**

Created: Thu, 09/05/24    Model: 912 S2-01    S/N: 9.139.965    TACH: 555.0    TTIS: 554.6  
TSOH: 554.6

Completed a 100 HR inspection IAW FAR 43 app. D with reference to BRP Rotax maintenance manual line 05-20-00. Researched AD's through bi-weekly report 2024-17. No applicable AD's due at this time. Compressions #1 79/80 # 79/80 #3 74/80 #4 76/80. Drained oil sump, Removed and cut open oil filter, inspected magnetic plug No metal found. Installed oil filter P/N 825016. Cleaned oil tank for using more than 30% leaded fuel with reference to Rotax Line maintenance manual 12-20-00. Serviced oil sump with 2.8 L of Aeroshell sport 4 plus. Replaced 8 Sparkplugs P/N 297656. Removed gearbox S/N 82280 per Tecnam P2006T MML 5-50-00 sent to Advanced Powerplant solution for overhaul. Installed overhauled gearbox S/N 82280 per Tecnam P2006T MML. Installed new prop o-ring C-048-A. Installed fuel pump gasket P/N 950-228. Installed 6 propeller locking nuts P/N NAS1291-7. Removed carburetor S/N 212940 and S/N 213013 and sent to Advanced Powerplant Solution for overhaul. Re-installed overhauled carburetors S/N 212940 and S/N 213013. synchronized carbs per Tecnam P2006T MML 12-20-00. **I certify that this engine has been inspected in accordance with a 100 Hr. inspection and was determined to be in airworthy condition.**

Josh Kennedy    A&P #4653415    Date: Thu, 09/05/24    Signature: 

*Signature &  
Licence no.:*



**Advanced Powerplant**

SOLUTIONS

[www.BuyRotaxParts.com](http://www.BuyRotaxParts.com)

**ROTAX.**

INDEPENDENT SERVICE CENTRE  
AIRCRAFT ENGINES

Date: 08-20-2024    Engine: 912S    Eng S/N: 9139965    Gearbox S/N: 82280    Engine Time: 554.6 Hrs

Performed 600 hour inspection on gearbox: Disassembled and inspected gear box. Cleaned all gearbox internal components. Reset break-away torque on slipper clutch to new specifications. Reassembled using new spring washers, phenolic washer, and retaining ring halves. All work done in accordance with latest Rotax maintenance information. Gearbox returned to customer for re-installation on aircraft.

  
Russell Horton    A&P 3347668    Rotax Heavy Rating 30001211017-4436



Advanced Powerplant

SOLUTIONS

www.BuyRotaxParts.com

**ROTAX.**

INDEPENDENT SERVICE CENTRE  
AIRCRAFT ENGINES

IRE  
3 R

Date: 08-20-24 Eng. Model: Rotax 912S Eng. S/N: 9139965 Total Time: 554.6 hrs

Performed Carburetor Over-Haul: Disassembled carburetors and inspected. Cleaned carburetors and parts via chemical bath and hot water wash. Installed new "R" style floats. Set float levels and performed inverted pressure test. Reassembled carburetors with all new, rubber and sealing components including o-rings, diaphragms, gaskets, fuel inlet needles, needle jets and jet needles. Applied epoxy to all drill plugs. All applicable service bulletins are up to date. All work done IAW latest Rotax maintenance information. See invoice for full list of replaced parts. Carburetors returned to customer for re-installation on aircraft.

Carburetor 1/3 S/N 212940

Carburetor 2/4 S/N 213013

Russell Horton

A&P 3347668, Rotax Heavy Rating 30001211017-4436



Created: Fri, 10/04/24 Model: 912 S2-01 S/N: 9.139.965

TACH: 568.9 TTIS: 568.8 TSOH: 568.8



Replaced oil pressure plug P/N 841-983, oil pressure relief spring P/N 838-122, oil pressure ball with newer style piston P/N 857-230, and added pressure shim P/N 227-055 using Rotax MMH as guide. Performed ops check, no defects noted.

Landon Reeder A&P #4369883 Date: Fri, 10/04/24 Signature:

**Maintenance record:**

Date:	Engine hours:		Work performed:	Signature & Licence no.:
	TSN:	TSO:		
<p><b>Created: 02/26/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: 9.139.965 Tach: 651.10 TTIS: 651.10</b></p> <p>Completed a engine 100 Hr. inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20 and Rotax MML/MMH. Researched AD's through current bi-weekly 2025-04, no applicable AD's due at this time. Performed differential compression check compressions as follows #1 79/80 #2 76/80 #3 79/80 #4 79/80. Drained engine oil sump, disassembled and cleaned oil tank due to use of over 30% 100LL fuel. Serviced oil sump with 3 liters of Aeroshell Sport Plus 4. Removed and cut open oil filter. Performed particulate inspection on filter. No metal found, no discrepancies noted. Replaced oil filter P/N: 825016. Removed and replaced #4 cylinder coolant flange P/N 922236 and o-ring P/N 950180. Replaced #2-4 intake o-ring P/N 230910. Replaced all spark plugs P/N 297656. Completed engine run up and ops check. No defects noted, test run satisfactory. I certify that this engine has been inspected in accordance with a 100 Hr inspection and has been determined to be in airworthy condition.</p> <p><b>Josh Kennedy A&amp;P 4653415 Date: 2/26/25 Signature:</b> </p>				
<p><b>Created: 03/06/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: 9.139.965 Tach: 655.20 TTIS: 655.20</b></p> <p>Pilot reported oil leaking in LH engine nacelle. After inspection found LH oil tank was over serviced causing excess oil to be discharged out of the breather/ vent line on oil tank. Cleaned oil off of airframe and removed excess oil to put oil level inside operational limits. performed ground operational check satisfactory.</p> <p><b>Logan Baker A&amp;P 4638550 Date: 3/6/25 Signature:</b> </p>				

**Maintenance record:**

Date:	Engine hours:		Work performed:	Signature & Licence no.:
	TSN:	TSO:		
<p>Created: 04/29/2025 Aircraft Registration Number: N330VA Make: Rotax                      Model: 912ULS S/N: 9.139.965 Tach: 737.50 TTIS: 737.50</p>				
<p>Completed a engine 100 Hr. inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20 and Rotax MML/MMH. Researched AD's through current bi-weekly 2025-08, no applicable AD's due at this time. Performed differential compression check compressions as follows #1 79/80 #2 79/80 #3 79/80 #4 78/80. Drained engine oil sump, disassembled and cleaned oil tank due to use of over 30% 100LL fuel. Serviced oil sump with 3 liters of Aeroshell Sport Plus 4. Removed and cut open oil filter. Performed particulate inspection on filter. No metal found, no discrepancies noted. Replaced oil filter P/N: 825016. Carburetors replaced with overhauled carburetors for 200 hour inspection. Removed LH carburetor P/N 892537 S/N 21.2941 and replaced with overhauled carburetor P/N 892537 S/N 24.3295. Removed RH carburetor P/N 892532 S/N 21.3013 and replaced with overhauled carburetor P/N 892532 S/N 24.3166. Work completed with reference to BRP Rotax 912 Maintenance Manual Heavy 73-10-00. Completed carburetor synchronization with reference to BRP Rotax 912 Maintenance Manual Line 12-20-00. Replaced cyl #1 top spark plug connector P/N 265249. Completed engine run up and ops check. No defects noted, test run satisfactory.</p>				
<p>I certify that this Engine has been inspected in accordance with a 100 hour inspection and has been determined to be in an airworthy condition.</p>				
<p>Logan Baker A&amp;P 4638550 Date: 4/29/25 Signature: </p>				
<p>Essential Aviation                      N330VA S/N0348/US                      Rotax S/N: 9.139.965                      Tach time:737.5 TSMOH: 737.5 Date:04/21/2025</p>				
<p>Completed annual inspection per FAR part43 appendix D and P2006T M.M. Performed compression check #1 79/80 #2 79/80 #3 79/80 #4 79/80. Researched AD's through ad bi-weekly report 2025-07.</p>				
<p>I certify that this engine has been inspected in accordance with Annual per FAR part 43 appendix D and was determined to be in airworthy condition.</p>				
<p>Gregory Warton A&amp;P 3807766 IA </p>				

9/26/25, 2:41 PM

Flight Schedule Pro



4850 Spartan Dr, Denton, TX 76207

Aviation

Office: (866) 383-2400 - Fax: (940) 3381-3555

WO18610 - N330VA - Tecnam - P-2006T - S/N: 348

LH ENG: - S/N: 9.139.965 - LH PROP: - S/N: 211167.0

RH ENG: - S/N: 10.005.059 - RH PROP: - S/N: 211165.0

ACTT: 816.50 - TACH: 816.50 - HOBBS: 831.40

LH ETT: 816.50 - LH TSMO: 816.50 - LH PTT: 816.50

RH ETT: 824.60 - RH TSMO: 824.60 - RH PTT: 824.60

Completed a engine 100 Hr. inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20 and Rotax MML/MMH. Researched AD's through current bi-weekly 2025-19, no applicable AD's due at this time. Performed differential compression check compressions as follows #1 77/80 #2 78/80 #3 78/80 #4 77/80. Drained engine oil sump, disassembled and cleaned oil tank due to use of over 30% 100LL fuel. Serviced oil sump with 3 liters of Rotax XPS 5-50 engine oil. Removed and cut open oil filter. Performed particulate inspection on filter. No metal found, no discrepancies noted. Replaced oil filter P/N: 825016. Pilot reported oil pressure fluctuation in flight prior to 100 hour inspection. Per Rotax engineering, the following parts were replaced. Installed new oil pump assembly P/N 911815. Oil pump gears P/N 956278, Oil pump cover P/N 911711. Oring P/N 430175, Oring x4 P/N 250460 Per Rotax HMM 79-00-00. Installed new oil system suction hoses P/N 26-7-1591-001, P/N 26-7-1591-002, P/N 26-7-1591-003, P/N 26-7-1591-004 Per Tecnam P2006T AMM 79-10. Replaced oil thermostatic valve with new valve P/N PIC-003 Per Tecnam P2006T AMM 79-10. Performed engine oil system purge. Completed engine run up, ops check, and test flight. No defects noted, test run satisfactory. I certify that this Engine has been inspected in accordance with a 100 hour inspection and has been determined to be in an airworthy condition.

Landon Reeder #4369883

Date: 9/26/25

Signature:

A TP

10/9/25, 10:04 AM

Flight Schedule Pro



4850 Spartan Dr, Denton, TX 76207

Aviation

Office: (866) 383-2400 - Fax: (940) 3381-3555

WO19075 - N330VA - Tecnam - P-2006T - S/N: 348

LH ENG: - S/N: 9.139.965 - LH PROP: - S/N: 211167.0

RH ENG: - S/N: 10.005.059 - RH PROP: - S/N: 211165.0

ACTT: 826.70 - TACH: 826.70 - HOBBS: 841.90

LH ETT: 826.70 - LH TSMO: 826.70 - LH PTT: 826.70

RH ETT: 835.00 - RH TSMO: 835.00 - RH PTT: 835.00

Pilot reported low coolant CAS message after initial startup before flight. Aircraft was grounded. Upper cowling was removed and low coolant level in reservoir was noted. Added Aeroshell/Dexcool until full line per P2006TAMM. No further discrepancies noted.

Landon Reeder #4369883

Date: 10/9/25

Signature:

A TP



**ROTAX®**

R/H #2  
ENGINE

**ENGINE  
LOG BOOK**

FOR ROTAX 2-STROKE AND 4-STROKE AIRCRAFT ENGINES

EDITION: 2023 05 01 | PART NO.: 898023

NO.:

M-424

Motor-Logbuch Nr.: **111-424** für Kolbenmotor  
 Engine Log Book: \_\_\_\_\_ for piston engine

Baumuster: Type of engine:	<b>912</b>	Baureihe: Model:	<b>S3-01</b>	Motor Nr.: Engine serial no.:	<b>10.005.059</b>
Hersteller: Manufacturer:	<b>BRP-Rotax GmbH &amp; Co KG A-4623 Gunskirchen, Austria</b>			Baujahr: Year of manufacture:	<b>Feb 2024</b>

Kennblatt:  
Data sheet: **EASA.E.121**

Startleistung: Take off power:	<b>73,5</b>	PS/kW hp/kW	zul. Dauer: perm. duration:	<b>5</b>	min. min.	bei: at:	<b>5800</b>	min 1 r.p.m.
-----------------------------------	-------------	----------------	--------------------------------	----------	--------------	-------------	-------------	-----------------

Max. zul. Dauerleistung: Max. cont. power:	<b>69</b>	PS/kW hp/kW	bei: at:	<b>5500</b>	min 1 r.p.m.
---	-----------	----------------	-------------	-------------	-----------------

Der oben bezeichnete Motor ist als betriebstüchtig anzusehen, wenn er gemäß der Zivilluftfahrzeug- und Luftfahrtgerät-Verordnung, letztgültige Ausgabe, und den Betriebs- und Wartungsanweisungen entsprechend betrieben und gewartet wird.

*The above mentioned engine is considered to be operationally reliable if operated and maintained in accordance with the Zivilluftfahrzeug- und Luftfahrtgerät-Verordnung, latest legal issue and the pertinent operational and maintenance instructions.*

Bemerkungen: **The engine was tested and delivered without governor.**  
 Remarks:

Datum:  
Date: **16. Februar.2024**

Unterschrift:  
Signature:

<b>BRP-Rotax GmbH &amp; Co KG</b>
<b>AT.21 G.0009</b>
<b>H. Steiner</b> <b>30137</b>

## SB-Stand / SB-Status

Status der durchgeführten SB (Service Bulletin's) bei 0-Stunden  
 Status of Airworthiness Directives or modifications effective at 0 hours.

Datum:  
Date:

Unterschrift & Pers. Nr.:  
Signature & Licence no.:

effective SB: 912-033, 912-042r1, 912-057r1.

optional SB: 912-037r1.

not applicable SB: 912-022, 912-028r1, 912-029r3, 912-030r1, 912-031, 912-039, 912-040r1, 912-041r2, 912-043r2, 912-045, 912-046, 912-047, 912-048, 912-049, 912-051, 912-052r4, 912-053, 912-054, 912-055, 912-056r1, 912-058, 912-059, 912-060, 912-061r1, 912-062r2, 912-063r1, 912-064r1, 912-066r1, 912-068r1, 912-070r1, 912-071, 912-073, 912-074, 912-075, 912-078

16. 02.  
2024

BRP-Rotax GmbH & Co KG  
 AT.21.G.0006  
 H. Staininger 30137

### Maintenance record

Date:	Engine hours:		Work performed:	Signature & Licence no.:
	Total: TSN:	since last overhaul: TSO:		
16.02.2024	0	-	Individual examination performed	<div style="border: 1px solid black; padding: 5px;">                     BRP-Rotax GmbH &amp; Co. KG                      AT.21.G.0006                      H. Steinhilber 30137                 </div>

**Created: 02/27/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: 10.005.059 Tach: 655.60 TTIS: 0.0**


Installed This engine Rotax 912 S3-01 S/N 10-005-059 on N330VA Tecnam P2006T S/N 348 with reference to Tecnam P2006T AMM 72-10 and Rotax 912 maintenance manual line and maintenance manual heavy and AC 43-13.1B. Installed new engine shock mounts P/N CON021-BS. Performed test ground run to check for leaks. No discrepancies noted. Performed test flight satisfactory.

**Logan Baker A&P 4638550 Date: 2/27/25 Signature:** 



**Created: 04/11/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: ~~9-130-065~~ Tach: 730.80 TTIS: ~~730.00~~**

*10,005,059 01<sup>2</sup> 75.20F*

CT Red Lined on taxi into shutdown on the ramp. No more than 30 seconds at redline prior to initiating shutdown of the affected engine.

**John Stefansen Cert: 4551923CFI Date: 4/11/25 Signature:** 

**Maintenance record:**

Date:	Engine hours:		Work performed:	Signature & Licence no.:
	TSN:	TSO:		
Created: 04/11/2025	Aircraft Registration Number: N330VA Make: Rotax		<p>Pilot reported engine coolant over temp occurrence. Temperature and time span as listed in entry above from PIC. After visual inspection found that the expansion tank cap was removed. Installed expansion tank cap, cleaned engine, performed Rotax 912 unscheduled maintenance check with reference to Rotax maintenance manual line 5-50-00 EXCEEDING OF MAX. COOLING SYSTEM TEMPERATURE inspection. Replenished/ serviced system with coolant. Performed ground operational run, no defects noted.</p>	
Model: 912ULS S/N: <del>9-139-905</del> 10.005.057LB	Tach: 730.80 TTIS: <del>730.00</del> 75.2LB			
Logan Baker	A&P 4638550	Date: 4/11/25	Signature: 	
Created: 04/29/2025	Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: <del>9-139-905</del> 10.005.0590P		<p>Completed a engine 100 Hr. inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20 and Rotax MML/MMH. Researched AD's through current bi-weekly 2025-08, no applicable AD's due at this time. Performed differential compression check compressions as follows #1 79/80 #2 78/80 #3 79/80 #4 79/80. Drained engine oil sump, disassembled and cleaned oil tank due to use of over 30% 100LL fuel. Serviced oil sump with 3 liters of Aeroshell Sport Plus 4. Removed and cut open oil filter. Performed particulate inspection on filter. No metal found, no discrepancies noted. Replaced oil filter P/N: 825016. Removed L/H carburetor and replaced with overhauled carburetor P/N 892-537 S/N 24.3298. Removed R/H carburetor and replaced with overhauled carburetor P/N 892-532 S/N 24.3150 work completed per BRP Rotax 912 ULS MMH 73-10. Performed carburetor synchronization per Rotax MML 12-20. Removed and replaced all spark plugs P/N 297656. Completed engine run up and ops check. No defects noted, test run satisfactory. I certify that this Engine has been inspected in accordance with a 100 hour inspection and has been determined to be in an airworthy condition.</p>	
	743.50 TTIS: 89.00			
Josh Kennedy	A&P 4653415	Date: 4/29/25	Signature: 	


Ma

Essential Aviation  
N330VA S/N0348/US  
Rotax S/N: 10.005.059

Tach time:743.5 TSMOH: 88.0 Date:04/21/2025

Completed annual inspection per FAR part43 appendix D and P2006T M.M. Performed compression check #1 79/80 #2 79/80 #3 79/80 #4 79/80. Researched AD's through ad bi-weekly report 2025-07.

**I certify that this engine has been inspected in accordance with Annual per FAR part 43 appendix D and was determined to be in airworthy condition.**

Gregory Warton A&P 3807766 IA 

Created: 06/19/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: ~~9.439.985~~ 10.005.059  
Tach: 786.20 TTIS: 131.70

Found carburetor chamber top was stripping at the bent tube assembly connector. Removed and replace chamber top with a serviceable used chamber top P/N 961250

Josh Kennedy A&P 4653415 Date: 6/19/25 Signature: 


9/25/25, 8:07 AM

Flight Schedule Pro

Created: 08/11/2025 Aircraft Registration Number: N330VA Make: Rotax Model: 912ULS S/N: 10.005.059 Tach: 821.70 TTIS: 167.20

Completed a engine 100 Hr. inspection IAW FAR 43 app. D with reference to Tecnam P2006T AMM 5-20 and Rotax MML/MMH. Researched AD's through current bi-weekly 2025-16, no applicable AD's due at this time. Performed differential compression check compressions as follows #1 78/80 #2 78/80 #3 78/80 #4 78/80. Drained engine oil sump, disassembled and cleaned oil tank due to use of over 30% 100LL fuel. Serviced oil sump with 3 liters of XPS 5W-50. Removed and cut open oil filter. Performed particulate inspection on filter. No metal found, no discrepancies noted. Replaced oil filter P/N: 825016. Removed and replaced alternator belt P/N: 6261MC. Completed engine run up and ops check. No defects noted, test run satisfactory.

**I certify that this Engine has been inspected in accordance with a 100 hour inspection and has been determined to be in an airworthy condition.**

Owen Fortney A&P #4429061 Date: 8/11/25 Signature: 


# COMPLIANCE STATEMENT - DECLARATION OF COMPLIANCE

to ASTM F2339-19a

Engine Type: 912 S2-01

Engine s/n: 9139965

## References:

1. ASTM F2339-19a
2. Serial Numbers (since ASTM has been established for ROTAX Aircraft Engines)
  - 912 A ..... from S/N 4410660 on
  - 912 F ..... from S/N 4412888 on
  - 912 S ..... from S/N 4923163 on
  - 912 UL ..... from S/N 4407160 on
  - 912 ULS ..... from S/N 5644817 on
  - 912 ULSFR ..... from S/N 4430116 on
  - 912 iS / iS Sport..... from S/N 4417078 on
  - 912 iSc Sport..... from S/N 4417412 on
  - 914 F ..... from S/N 4420471 on
  - 914 UL ..... from S/N 4419024 on
  - 915 iS A ..... from S/N 9132042 on
  - 915 iSc A ..... from S/N 9127006 on
  - 915 iSc B ..... from S/N 9122510 on
  - 916 iSc B ..... from S/N 9147013 on


BRP-Rotax GmbH & Co KG hereby declares that the aircraft engine or part of thereof as described in the statement of compliance confirms to the applicable ASTM F2339-19a standard.

No features or characteristics are found which would make the engine unsafe provided it is installed, operated and maintained in accordance with instructions and limitations as defined by BRP-Rotax approved documentation.

The product complies with the ASTM F2339-19a standard based on BRP's quality system for record keeping and instructions for continued airworthiness.



Ing. Michael Dopona  
Head of Design Organisation



Maximilian Feischl  
Accountable Manager

Gunskirchen, 20.10.2021

BRP-Rotax GmbH & Co KG | Rotaxstraße 1 | 4623 Gunskirchen | Austria

02. 12.2021 AO/Frb/Obe

BRP-Rotax GmbH & Co. KG  
Rotaxstraße 1  
A-4623 Gunsirichen, Austria  
T: +43 7246 601 0 F: +43 7246 6370  
www.rotax.com

LUCIANO SORLINI SPA CON SOCIO UNICO  
Piazza Roma 1  
I-25080 Carzago di Calvagese Riviera (Bs)

Firmenbuch-Nr.: FN217491s  
Landesgericht Wels  
UID-Nr. ATU 53018309  
BRP-ROTAX GmbH & Co KG  
DVR: 0381080  
  
OBERBANK, BLZ 15130  
Konto 283-0701/00  
IBAN AT70 1513 0002 8307 0100

**ROTAX AIRCRAFT ENGINE TYPE 912 S2-01**


Enclosed you will find for Rotax engine with S/N:

**9.139.965**

- test run protocol no. AC025017 of 29.
- authorised release certificate EASA FORM 1 no. B21/0614 of 02. 12. 2021
- engine log book no. 109-244

Best regards

BRP-Rotax GmbH & Co KG

iA   
Freinberger Roman

iA   
Elke Obermair

Enclosure

Partner with unlimited liability:  
BRP-Powertrain Management GmbH | Rotaxstraße 1 | 4623 Gunsirichen, Austria  
Firmenbuch-Nr.: FN 200454 k | Landesgericht Wels

# Aircraft - Testrun Protocol



personal_number	89174
projekt	AC_912_S
engine_no	9139965
test_cell	602
start_date	2021-10-29 08:49:34
operator	Dakovic Sasa
stroke_family	4
power_transm	Direkt
power_load	Dyno
g_i_internal	2.430000
g_e_internal	1.000000
fuel	Super
d_fuel	0
fuel_system	Carburetor
uut	912
test_type	automatic n=K
t_measure	10
test_owner	HET
test_name	EINLAUF_912_S
test_version	1.00
test_comment	912 S
l	l
displacement	1352.0
exhaust_system	Rotax Teile Nr.973676
intake_system	Ansaugluftverteiler kpl.: 667355
carburetor	2 x Bing 64
carb_calib	HD 155; LD 35; NP:3; Nadeldüse 2.70
idle_adj_screw	Zyl.1/3 Lr.1 1/2 Dk.1 Zyl.2/4 Lr.1 1/2 Dk.1
spark_plug	BOSCH 297656
ign_system	ROTAX
fuel_pump	Corona
compression_r	10.80
ignition_timing	26°
full_load_measurement	Messpunkt 1-6
takeoff_power	Messpunkt 7
flying_test_measurement	Messpunkt 8-9
part_load_measurement	Messpunkt 10-13
magnet_test	Messpunkt 14-16
intake_manifold_pressure_test	Messpunkt 17-19
idle	Messpunkt 20
result_name	AC025017

Operator Dakovic Sasa  
 Testcell 602  
 Engine Number 9139965  
 Project AC\_912\_S  
 Result Name AC025017  
 Start Date 2021-10-29 08:49:34  
 Testname EINLAUF\_912\_S

Checked by Sasa Dakovic  
 Test-Date 29.10.2021



**Aircraft - Testrun Protocol**

Special Note:

		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
engine_speed_calculated	rpm	5830	5516	5022	4517	4024	3517	5816	5491	4997	5498	4997	4521	4011	4005	3865	3870	5535
power_corrected_912	kW	74.2	68.5	65.4	58.7	51.4	43.4	74.2	70.8	55.3	70.7	55.3	41.8	29.0	28.9	25.8	25.8	70.6
correction_912	-	1.101	1.094	1.093	1.092	1.089	1.089	1.093	1.087	1.088	1.089	1.090	1.091	1.089	1.088	1.088	1.087	1.088
torque_corrected_912	Nm	121.5	118.7	124.3	124.1	122.0	117.8	121.8	123.0	105.7	122.7	105.7	88.3	69.0	68.8	63.7	63.8	121.8
fuel_consumption_spec_912_733	g/kWh	288	280	284	270	271	278	295	292	264	272	265	293	307	303	331	330	292
fuel_cons_733	cm³/h	27136.81	24510.26	23673.64	20230.09	17793.12	15420.67	27955.31	26443.27	18655.28	24561.16	18771.87	15641.64	11364.91	11187.46	10909.66	10918.67	26423.46
p_fuel_rail	bar	0.24	0.25	0.25	0.26	0.24	0.29	0.21	0.23	0.28	0.21	0.28	0.28	0.29	0.30	0.29	0.29	0.22
t_ambient	°C	32.9	30.9	30.6	30.6	29.7	29.6	30.8	29.1	29.4	29.6	29.8	30.0	29.7	29.5	29.3	29.2	29.3
p_oilpump_out	bar	3.7	3.7	3.6	3.7	3.9	3.9	3.7	3.7	3.6	3.7	3.6	3.7	3.9	3.9	3.9	3.9	3.7
t_oilfilter_out	°C	84.4	79.8	78.4	78.0	77.8	78.2	82.8	78.0	79.0	79.8	80.1	79.5	79.1	78.5	77.8	77.4	81.7
t_water_engine_out	°C	90	90	89	90	91	89	89	91	88	89	89	89	92	90	88	88	90
t_cyl_head_cyl_2	°C	92.7	92.4	91.8	92.5	93.2	92.2	92.3	93.2	90.1	91.2	91.0	91.3	93.8	92.1	90.2	90.9	91.8
t_cyl_head_cyl_3	°C	92.7	91.6	91.1	92.0	93.4	92.5	91.6	92.6	90.1	91.1	90.9	91.9	94.9	93.3	91.4	92.0	91.4
t_exhaust_cyl_1	°C	801	799	759	749	728	696	791	768	763	772	759	696	694	692	703	721	777
t_exhaust_cyl_2	°C	777	771	710	723	699	655	779	739	710	729	712	669	671	670	682	701	728
t_exhaust_cyl_3	°C	729	720	699	690	702	689	732	721	778	737	781	779	763	758	785	787	719
t_exhaust_cyl_4	°C	805	774	752	736	713	690	801	772	813	784	814	791	756	749	776	781	788
p_plenum_intake	mbar	937	928	946	954	961	962	937	940	888	940	888	848	769	775	780	779	938
p_ambient	mbar	977.6	977.3	977.3	977.4	977.6	977.7	977.6	977.4	977.3	977.4	977.4	977.5	977.5	977.5	977.4	977.4	977.4

**Testrun Information**

Magnetprobe Drehzahlabfall: Kreis A = 140 rpm, Kreis B = 135 rpm Differenzdruck : Ausgangsdruck 6 bar. Alle 4 Zylinder 5,95 bar  
 CO 5800 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 CO 5500 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 Dichtheitskontrolle: ja; Ölfilterkontrolle: ja;  
 Kraftstoffpumpentest: OK  
 Prüfer: Sasa Dakovic



Operator Dakovic Sasa  
 Testcell 602  
 Engine Number 9139965  
 Project AC\_912\_S  
 Result Name AC025017  
 Start Date 2021-10-29 08:49:34  
 Testname EINLAUF\_912\_S

Checked by Sasa Dakovic  
 Test-Date 29.10.2021



Aircraft - Testrun Protocol

Special Note:

		18	19	20														
engine_speed_calculated	rpm	5006	4517	1695														
power_corrected_912	kW	43.4	31.6	1.9														
correction_912	-	1.088	1.087	1.086														
torque_corrected_912	Nm	82.8	66.9	10.9														
fuel_consumption_spec_912_733	g/kWh	289	33	669														
fuel_cons_733	cm³/h	16066.86	-1335.11	1651.45														
p_fuel_rail	bar	0.29	0.30	0.34														
t_ambient	°C	29.5	29.0	28.9														
p_oilpump_out	bar	3.7	3.6	3.4														
t_oilfilter_out	°C	82.0	79.1	74.7														
t_water_engine_out	°C	89	88	89														
t_cyl_head_cyl_2	°C	91.3	90.5	91.1														
t_cyl_head_cyl_3	°C	91.4	91.0	91.6														
t_exhaust_cyl_1	°C	716	705	541														
t_exhaust_cyl_2	°C	686	689	490														
t_exhaust_cyl_3	°C	792	794	534														
t_exhaust_cyl_4	°C	816	785	542														
p_plenum_intake	mbar	834	752	403														
p_ambient	mbar	977.4	977.4	977.4														

Testrun Information

Magnetprobe Drehzahlabfall: Kreis A = 140 rpm, Kreis B = 135 rpm Differenzdruck : Ausgangsdruck 6 bar. Alle 4 Zylinder 5,95 bar  
 CO 5800 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 CO 5500 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 Dichtheitskontrolle: ja; Ölfilterkontrolle: ja;  
 Kraftstoffpumpentest: OK  
 Prüfer: Sasa Dakovic

BRP-Rotax GmbH & Co KG  
 07013 0006  
 Dr. Freinberger 31420

# COMPLIANCE STATEMENT - DECLARATION OF COMPLIANCE

to ASTM F2339-19a

Engine Type: 912 S2-01

Engine s/n: 9139966

## References:

1. ASTM F2339-19a

2. Serial Numbers (since ASTM has been established for ROTAX Aircraft Engines)

912 A .....	from S/N 4410660 on
912 F .....	from S/N 4412888 on
912 S .....	from S/N 4923163 on
912 UL .....	from S/N 4407160 on
912 ULS .....	from S/N 5644817 on
912 ULSFR .....	from S/N 4430116 on
912 iS / iS Sport.....	from S/N 4417078 on
912 iSc Sport.....	from S/N 4417412 on
914 F .....	from S/N 4420471 on
914 UL .....	from S/N 4419024 on
915 iS A .....	from S/N 9132042 on
915 iSc A .....	from S/N 9127006 on
915 iSc B .....	from S/N 9122510 on
916 iSc B .....	from S/N 9147013 on


BRP-Rotax GmbH & Co KG hereby declares that the aircraft engine or part of thereof as described in the statement of compliance confirms to the applicable ASTM F2339-19a standard.

No features or characteristics are found which would make the engine unsafe provided it is installed, operated and maintained in accordance with instructions and limitations as defined by BRP-Rotax approved documentation.

The product complies with the ASTM F2339-19a standard based on BRP's quality system for record keeping and instructions for continued airworthiness.



Ing. Michael Dopona  
Head of Design Organisation



Maximilian Feischl  
Accountable Manager

Gunskirchen, 20.10.2021

BRP-Rotax GmbH & Co KG | Rotaxstraße 1 | 4623 Gunskirchen | Austria

02. 12.2021 AO/Frb/Obe

**BRP-Rotax GmbH & Co. KG**  
Rotaxstraße 1  
A-4623 Gunskirchen, Austria  
T: +43 7246 601 0 F: +43 7246 6370  
www.rotax.com

LUCIANO SORLINI SPA CON SOCIO UNICO  
Piazza Roma 1  
I-25080 Carzago di Calvagese Riviera (Bs)

Firmenbuch-Nr.: FN217491s  
Landesgericht Wels  
UID-Nr. ATU 53018309  
BRP-ROTAX GmbH & Co KG  
DVR: 0381080

OBERBANK, BLZ 15130  
Konto 283-0701/00  
IBAN AT70 1513 0002 8307 0100

**ROTAX AIRCRAFT ENGINE TYPE 912 S2-01**


Enclosed you will find for Rotax engine with S/N:


**9.139.966**

- test run protocol no. AC024988 of 28.
- authorised release certificate EASA FORM 1 no. B21/0615 of 02. 12. 2021
- engine log book no. 109-245

Best regards

BRP-Rotax GmbH & Co KG

iA   
BRP-Rotax GmbH & Co KG  
AT 21 74 91 s  
R. Freinberger 31420  
Freinberger Roman

iA   
Elke Obermair

Enclosure

Partner with unlimited liability:  
BRP-Powertrain Management GmbH | Rotaxstraße 1 | 4623 Gunskirchen, Austria  
Firmenbuch-Nr.: FN 200454 k | Landesgericht Wels



# Aircraft - Testrun Protocol

personal_number	89174
projekt	AC_912_S
engine_no	9139966
test_cell	602
start_date	2021-10-28 08:50:18
operator	Dakovic Sasa
stroke_family	4
power_transm	Direkt
power_load	Dyno
g_i_internal	2.430000
g_e_internal	1.000000
fuel	Super
d_fuel	0
fuel_system	Carburetor
uut	912
test_type	automatic n=K
t_measure	10
test_owner	HET
test_name	EINLAUF_912_S
test_version	1.00
test_comment	912 S
l	l
displacement	1352.0
exhaust_system	Rotax Teile Nr.973676
intake_system	Ansaugluftverteiler kpl.: 667355
carburetor	2 x Bing 64
carb_calib	HD 155; LD 35; NP:3; Nadeldüse 2.70
idle_adj_screw	Zyl.1/3 Lr.1 1/2 Dk.1 Zyl.2/4 Lr.1 1/2 Dk.1
spark_plug	BOSCH 297656
ign_system	ROTAX
fuel_pump	Corona
compression_r	10.80
ignition_timing	26°
full_load_measurement	Messpunkt 1-6
takeoff_power	Messpunkt 7
flying_test_measurement	Messpunkt 8-9
part_load_measurement	Messpunkt 10-13
magnet_test	Messpunkt 14-16
intake_manifold_pressure_test	Messpunkt 17-19
idle	Messpunkt 20
result_name	AC024988

Operator Dakovic Sasa  
 Testcell 602  
 Engine Number 9139966  
 Project AC\_912\_S  
 Result Name AC024988  
 Start Date 2021-10-28 08:50:18  
 Testname EINLAUF\_912\_S

Checked by Sasa Dakovic  
 Test-Date 28.10.2021



**Aircraft - Testrun Protocol**

Special Note:

		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
engine_speed_calculated	rpm	5843	5515	5012	4502	4015	3501	5848	5540	4995	5533	4976	4515	4013	4014	3866	3882	5509
power_corrected_912	kW	73.5	71.1	66.1	58.6	50.7	42.3	73.7	71.8	55.0	72.0	55.5	42.0	29.4	29.4	26.2	26.5	72.0
correction_912	-	1.074	1.076	1.079	1.079	1.079	1.079	1.079	1.081	1.082	1.082	1.083	1.084	1.083	1.083	1.083	1.083	1.082
torque_corrected_912	Nm	120.2	123.1	125.9	124.4	120.5	115.3	120.3	123.8	105.1	124.3	106.4	88.9	69.9	70.0	64.7	65.1	124.8
fuel_consumption_spec_912_733	g/kWh	277	277	269	260	252	274	283	280	259	282	260	297	300	292	332	319	278
fuel_cons_733	cm³/h	26212.87	25374.32	22845.79	19581.47	16440.75	14892.98	26825.77	25848.21	18304.58	26095.80	18508.25	15989.99	11317.47	11028.27	11147.63	10842.95	25718.30
p_fuel_rail	bar	0.25	0.26	0.26	0.27	0.25	0.26	0.22	0.22	0.27	0.23	0.27	0.26	0.30	0.30	0.30	0.29	0.20
t_ambient	°C	27.5	28.1	29.1	28.9	28.9	28.8	28.8	29.6	29.8	29.9	30.1	30.3	30.1	30.0	30.1	30.0	29.7
p_oilpump_out	bar	3.8	3.6	3.7	3.6	4.0	4.2	3.7	3.6	3.7	3.6	3.7	3.6	3.9	3.8	3.9	3.9	3.7
t_oilfilter_out	°C	81.2	81.8	80.8	79.8	80.0	79.8	80.3	79.4	80.4	80.1	79.1	78.5	78.7	78.2	77.6	77.2	80.7
t_water_engine_out	°C	90	89	90	90	90	89	91	92	88	93	91	88	89	91	92	90	92
t_cyl_head_cyl_2	°C	93.3	92.3	92.5	93.0	92.5	91.8	94.3	95.1	90.3	95.4	94.0	90.8	91.5	93.3	94.5	92.5	94.3
t_cyl_head_cyl_3	°C	91.7	90.5	90.7	91.1	90.6	90.1	92.8	93.4	89.0	93.7	92.7	89.6	90.6	92.4	93.8	91.9	92.7
t_exhaust_cyl_1	°C	789	778	752	748	741	709	791	776	751	779	749	694	682	680	690	708	759
t_exhaust_cyl_2	°C	790	782	760	741	731	682	794	780	746	784	743	694	706	707	716	734	768
t_exhaust_cyl_3	°C	782	770	742	721	718	688	783	769	793	774	793	761	762	760	784	791	759
t_exhaust_cyl_4	°C	787	771	743	726	703	678	788	766	804	773	807	786	733	725	739	743	754
p_plenum_intake	mbar	944	947	954	963	967	968	943	947	892	947	896	855	778	777	788	786	947
p_ambient	mbar	984.7	984.6	984.5	984.4	984.4	984.3	984.3	984.4	984.4	984.3	984.4	984.5	984.5	984.5	984.5	984.5	984.4

**Testrun Information**

Magnetprobe Drehzahlabfall: Kreis A = 148 rpm, Kreis B = 132 rpm Differenzdruck : Ausgangsdruck 6 bar. Alle 4 Zylinder 5,95 bar  
 CO 5800 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 CO 5500 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 Dichtheitskontrolle: ja; Ölfilterkontrolle: ja;  
 Kraftstoffpumpentest: OK  
 Prüfer: Sasa Dakovic

BRP-Rotax GmbH & Co KG  
 21.0006  
 R. Franberger 31420



Operator Dakovic Sasa  
 Testcell 602  
 Engine Number 9139966  
 Project AC\_912\_S  
 Result Name AC024988  
 Start Date 2021-10-28 08:50:18  
 Testname EINLAUF\_912\_S

Checked by Sasa Dakovic

Test-Date 28.10.2021



Aircraft - Testrun Protocol

Special Note:


		18	19	20														
engine_speed_calculated	rpm	5009	4516	1747														
power_corrected_912	kW	43.2	31.8	1.8														
correction_912	-	1.081	1.081	1.080														
torque_corrected_912	Nm	82.4	67.2	9.7														
fuel_consumption_spec_912_733	g/kWh	302	298	791														
fuel_cons_733	cm³/h	16748.95	12139.81	1790.33														
p_fuel_rail	bar	0.26	0.28	0.33														
t_ambient	°C	29.7	29.7	29.3														
p_oilpump_out	bar	3.6	3.7	3.2														
t_oilfilter_out	°C	79.7	79.5	77.4														
t_water_engine_out	°C	92	89	91														
t_cyl_head_cyl_2	°C	94.9	92.1	93.5														
t_cyl_head_cyl_3	°C	93.4	90.8	92.8														
t_exhaust_cyl_1	°C	698	705	570														
t_exhaust_cyl_2	°C	703	734	600														
t_exhaust_cyl_3	°C	782	787	595														
t_exhaust_cyl_4	°C	806	751	616														
p_plenum_intake	mbar	839	757	395														
p_ambient	mbar	984.6	984.6	984.5														

Testrun Information

Magnetprobe Drehzahlabfall: Kreis A = 148 rpm, Kreis B = 132 rpm Differenzdruck : Ausgangsdruck 6 bar. Alle 4 Zylinder 5,95 bar  
 CO 5800 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 CO 5500 rpm: Z1 = %; Z2 = %; Z3 = %; Z4 = %  
 Dichtheitskontrolle: ja; Ölfilterkontrolle: ja;  
 Kraftstoffpumpentest: OK  
 Prüfer: Sasa Dakovic

BRP-Rotax GmbH & Co KG  
 31420  
 [Signature]



1. Approving Competent Authority/Country <b>Austro Control GmbH / Austria</b>		2. <b>AUTHORISED RELEASE CERTIFICATE EASA FORM 1</b>			3. Form Tracking Number <b>B24/0206</b>	
4. Approved Organisation Name and Address: <b>ROTAX</b> AIRCRAFT ENGINES				BRP-Rotax GmbH & Co KG A-4623 Gunskirchen, Austria Rotaxstraße 1		5. Work Order/Contract/Invoice Delivery Note <b>80749637</b> Date <b>09.02.2024</b>
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial-No.	11. Status/Work	
1	Rotax engine 912 S3-01	309120133	1	10005059	new	
12. Remarks <i>For information about storage and storage conditions of spare parts please follow the instructions at the relevant Service Letter (SL-912-I-011,SL-915-I-003,SL-912-022,SL-914-020,SL-916-I-003)</i>  <i>The engine was tested and delivered without governor.</i>  <i>Next overhaul after 2.000 h or 15 years of first operation</i> Service Bulletin 912-037r1. optional: Service Bulletin 912-033, 912-042r1, 912-057r1. effect:  Service Bulletin 912-022, 912-028r1, 912-029r3, 912-030r1, 912-031, 912-039, 912-040r1, 912-041r2, 912-043r2, 912-045, 912-046, 912-047, 912-048, 912-049, not applic.: 912-051, 912-052r4, 912-053, 912-054, 912-055, 912-056r1, 912-058, 912-059, 912-060, 912-061r1, 912-062r2, 912-063r1, 912-064r1, 912-066r1, 912-068r1, 912-070r1, 912-071, 912-073, 912-074, 912-075, 912-078  Displayed for : <b>ROTECH MOTOR LTD.</b> Limited life parts will normally be accompanied by maintenance history including life used						
13a. Certifies that the items identified above were manufactured in conformity to:  <input checked="" type="checkbox"/> approved design data and are in condition for safe operation  <input type="checkbox"/> non-approved design data specified in block 12				14a. <input type="checkbox"/> Part-145.A.50 Release to Service <input type="checkbox"/> Other Regulation specified in block 12  Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service		
13b. Authorised Signature  Electronic Signature on File BRP-Rotax GmbH & Co KG AT.21.G.0006 H. Steininger 30137		13c. Approval/Authorisation Number <b>AT.21G.0006</b>		14b. Authorised Signature		14c. Certificate/Approval Ref. No.
13d. Name <b>Steininger Helmut</b>		13e. Date (dd mmm yyyy) <b>16.Feb.2024</b>		14d. Name		



Start Date	07.02.2024 19:02:35
Engine Number	10005059
Result Number	AC0220468

		1	2	3	4	5	6	7	8	9	10	11	12					
engine_speed_calculated	rpm	0	5810	5514	5014	4513	5811	5006	4513	4007	3752	3787	1708					
power_corrected_912	kW	0.0	74.8	72.7	67.5	60.0	74.3	53.5	38.6	27.9	23.3	23.8	3.6					
correction_912	-	1.082	1.081	1.081	1.081	1.081	1.081	1.085	1.085	1.084	1.084	1.084	1.083					
torque_corrected_912	Nm	0.1	122.9	125.9	128.5	127.0	122.1	102.0	81.7	66.4	59.2	60.0	20.3					
fuel_consumption_spec_912_733	g/kWh	0	288	272	267	266	278	272	293	305	359	342	307					
fuel_cons_733	cm³/h	0.00	27628.68	25398.39	23155.64	20529.48	26543.05	18642.86	14467.92	10913.68	10729.50	10451.62	1429.02					
p_fuel_rail	bar	0.00	0.26	0.27	0.27	0.26	0.28	0.29	0.29	0.33	0.33	0.32	0.32					
t_ambient	°C	24.9	24.8	24.8	24.7	24.8	24.9	25.7	25.7	25.6	25.5	25.4	25.2					
p_oilpump_out	bar	-0.0	3.9	4.3	4.1	3.8	4.0	4.2	4.1	4.0	4.1	4.0	3.6					
t_fuelpump_in	°C	19.5	17.1	17.0	16.9	16.9	16.9	16.8	16.8	16.8	16.8	16.8	16.9					
t_oilfilter_out	°C	21.7	91.1	85.7	92.6	88.2	90.9	87.9	88.5	84.7	79.5	79.3	76.8					
t_water_engine_out	°C	46	91	94	93	91	90	88	87	85	85	86	90					
t_cyl_head_cyl_2	°C	22.5	96.1	96.6	99.0	96.5	95.9	91.9	92.8	91.1	88.8	90.8	98.1					
t_cyl_head_cyl_3	°C	21.8	94.9	95.4	97.8	95.1	94.3	91.1	92.4	90.9	88.6	90.9	96.7					
t_exhaust_cyl_1	°C	37	770	776	754	751	795	746	694	678	681	691	571					
t_exhaust_cyl_2	°C	31	747	749	736	730	770	731	690	670	675	685	565					
t_exhaust_cyl_3	°C	29	757	765	749	710	783	785	745	742	774	786	588					
t_exhaust_cyl_4	°C	30	778	789	768	721	805	805	770	759	791	796	591					
p_plenum_intake	mbar	970	931	935	941	945	931	873	828	768	779	777	457					
p_ambient	mbar	968.6	969.2	969.1	969.2	969.1	969.1	968.7	968.6	968.7	968.7	968.6	968.7					
lambda_1	-	4.81	0.91	0.91	0.90	0.93	0.91	0.86	0.78	0.76	0.76	0.76	0.79					
lambda_2	-	4.81	0.85	0.84	0.84	0.88	0.85	0.82	0.77	0.75	0.75	0.75	0.81					
lambda_3	-	4.81	0.92	0.92	0.92	0.88	0.92	1.03	1.13	1.06	1.06	1.06	0.90					
lambda_4	-	4.81	0.92	0.93	0.92	0.86	0.93	1.02	1.07	1.04	1.04	1.04	0.88					

**Meta Information**

Magnet Test Lane AB-A=255rpm | Lane AB-B=220rpm | Lane A-B=35rpm  
 Short Circuit Check: OK  
 Fuel Conservation: Completed

BRP Rotax GmbH & Co KG  
 H. Steininger 30137  
 07.02.2024





## Aircraft - Testrun Protocol

### Engine

Engine Number	10005059
Engine Type	AC_912_S

### Audit Information

EOL Date	07.02.2024 19:02:35
Operator ID	30080
Testbench ID	602
Test Procedure	P_EL_Carburetor
Result Number	AC0220468

### Measure Points

Engine Stopped Measurement	Measure Point 1
Full Load Measurement	Measure Point 2-5
TakeOff Power Measurement	Measure Point 6
Part Load Measurement	Measure Point 7-9
Magnet Test Measurement	Measure Point 10-11
Idle Point Measurement	Measure Point 12

16. 02.2024 ME/Steih/Obe

BRP-Rotax GmbH & Co. KG  
Rotaxstraße 1  
A-4623 Gunkskirchen, Austria  
T: +43 7246 601 0 F: +43 7246 6370  
www.rotax.com

ROTECH MOTOR LTD.  
6235 OKANAGAN LANDING ROAD,  
VERNON BC V1H 1M5,  
CANADA

Firmenbuch-Nr.: FN217491s  
Landesgericht Wels  
UID-Nr. ATU 53018309  
BRP-ROTAX GmbH & Co KG  
DVR: 0381080

OBERBANK, BLZ 15130  
Konto 283-0701/00  
IBAN AT70 1513 0002 8307 0100

## ROTAX AIRCRAFT ENGINE TYPE 912 S3-01

Enclosed you will find for Rotax engine with S/N:

**10.005.059**

- test run protocol no. AC0220468 of 07. 02.2024
- authorised release certificate EASA FORM 1 no. B24/0206 of 16. 02. 2024
- engine log book no. 111-424

Best regards

BRP-Rotax GmbH & Co KG

iA   
Steininger Helmut

iA   
Elke Obermair

**Enclosure**

Partner with unlimited liability:  
BRP-Powertrain Management GmbH | Rotaxstraße 1 | 4623 Gunkskirchen, Austria  
Firmenbuch-Nr.: FN 200454 k | Landesgericht Wels