Base record:

| | Engine log book number: | LS-191-0719 | for piston engine |
|---------|------------------------------------|-----------------------------------|--|
| | Type of engine: | Model: UCS2-01 | Engine serial no.: 9573 013 |
| | Manufacturer: BRP-Rotax GmbH | & Co KG, 4623 Gunskirchen, Austri | a Year of manufacture: NAY2019 |
| | Data sheet: | F2339 - 06 | |
| | | Hp. perm. duration: | min at <u>S&Co</u> r.p.m. |
| | Max. cont. power: 69,00 kW/l | Hp. atS \$Co | r.p.m. |
| | _ | · | operated and maintained in accordance with he pertinent operational and maintenance |
| | Remarks: CONTO GURDZO CON CASTULLO | NO STANDARD INSTALLATO | |
| Z3.IIII | Date: | | LUCIANO SORLINI S. D. G. CON SOCIO UNICO Via Marconi, 33 25080 CARZAGO DI CALVAGESE RIV DS; Codice Figale: 005848601/4 Signature artisti. N. J.: 00729280980 |

Engine installation record:

| Aircraft: | | Dat | e: | Engine | hours: | Signature & Licence no.: |
|-----------|--|---|---------------------------------------|--|---|--------------------------------------|
| Registr.: | type: | in: | out: | TSN | TSO | Licenso iis. |
| 175 | P2008 | 1/08/19 | | 8 | | COSTRUZIONI AERONAUTICH |
| | , , , | | | | | TECNAN |
| | | | | | | Via Maiorise 81043 CAPUA (Caserta |
| | | | · · · · · · · · · · · · · · · · · · · | | , | |
| | | | | | | |
| | Tach Hours: 99 Engine Total H | Hours: 99.6 | 0 4 OF A | , u coope m Lie | September 1 | |
| | Engine Total F Install new 825016 oi Completed Tecnam In BRP maintenance ma I certify that this engi and inspection proceed | Hours: 99.6 I filter and service with aspection Document Normula document Normula document Normula document as been inspected in dures, and was found to | all torque limits | hell SPORT PLUS ordance with Tecnan s and found ok. | 4 oil. n P2008 Maintenand ion per the manufac | ce Manual and Rotax- |
| | Engine Total F Install new 825016 oi Completed Tecnam In BRP maintenance ma | Hours: 99.6 I filter and service with aspection Document Normula document Normula document Normula document as been inspected in dures, and was found to | all torque limits | hell SPORT PLUS of ordance with Tecnary and found ok. ith an annual inspect on for safe operation. | 4 oil. n P2008 Maintenand ion per the manufac | ce Manual and Rotax- |
| | Engine Total F Install new 825016 oi Completed Tecnam In BRP maintenance ma I certify that this engi and inspection proceed | Hours: 99.6 I filter and service with aspection Document Normula document Normula document Normula document as been inspected in dures, and was found to | all torque limits | hell SPORT PLUS of ordance with Tecnary and found ok. ith an annual inspect on for safe operation. | 4 oil. n P2008 Maintenand ion per the manufac | ce Manual and Rotax- |

Engine installation record:

| F | ENGINE LOG BOOK ENTRY ROTAX 912ULS2-01 S/N 9573013 | Signature & Licence no.: |
|---|---|-----------------------------|
| | Tach Hours: 195.4 Engine Total Hours: 195.4 Date: November 30, 2021 | |
| | Install new 825016 oil filter and service with 3 qts. Of Aeroshell SPORT PLUS 4 oil. Install 8 new spark plugs p/n DCPR8E Complied with 200 hours carb inspection Completed Tecnam Inspection Document N2008/008 in accordance with Tecnam P2008 Maintenance Manual and Rotax-BRP maintenance manual d06117.fm, check all torque limits and found ok. | |
| | I certify that this engine has been inspected in accordance with a 100 hour inspection per the manufacturer's maintenance and inspection procedures, and was found to be in a condition for safe operation. DATE: NOV 30 2001 | |
| | SIGNED: ROTAX OF EAST-108:10-3996 A 1 4 3 6704 | |
| | ROTAX 912ULS2-01 S/N 9573013 | |
| | Tach Hours: 209.5 Engine Total Hours: 209.5 | |
| | Install new 825016 oil filter and service with 3 qts. Of Aeroshell SPORT PLUS 4 oil. Completed Tecnam Inspection Document N2008/008 in accordance with Tecnam P2008 Maintenance Manual and Rotax-BRP maintenance manual d06117.fm, check all torque limits and found ok. I certify that this engine has been inspected in accordance with an annual inspection per the manufacturer's maintenance and inspection procedures, and was found to be in a condition for safe operation. | |

4

| B-status and modification record: | | Sia | nature & Licence no | 135 |
|--|--------|------------|------------------------------------|----------------|
| Airworthiness directive or modification: | Date: | | COSTRUZIONI AERONAUTICH | E |
| S1-812-018 RL | OT/08/ | 13 | KITECNAN | Sp.A. |
| | 23/07 | 2/19 / 1/1 | Via Maiorise 81043 CAPUA (Caser | ta) |
| 56-312-073 UL | 2 3/01 | 113 | | Œ |
| 30 | | | CONTRUZION AERONAUTICA TECNA | , -T |
| | | | Via Majorise | de' |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | - |
| | | | | |
| | , | | | |
| | | | - | |

| Engine hours: | | | norformed: | Signature & Licence no.: | |
|---------------|--------------------|-------------------------|--|--|--|
| Date: | | TSO: | Work | performed: | |
| ł | TSN: | | | | |
| | ours: 274.4 | | FAX 912ULS2-0 S/N 9573013 N893G | <u>01</u> Date: January | 24, 2023 |
| Engine | Total Hours: | 2/4.4 | | ninants. None found, Installed new | Dates |
| DATE: // | m 27,202 | | ENGINE LOG F ROTAX 912 1 S/N 957301 | <u>ULS2-01</u> | |
| | Tach Hou Engine To | otal Hours: 30 |)7.2 | Date: F | February 17, 2023 |
| | Install new 82: | 25016 oil filter and se | ervice with 3 qts. Of Aero | osheli SPORT PLUS 4 oil. coordance with Tecnam P2008 Ma its and found ok. with a 100 hour inspection per th tion for safe operation. | aintenance Manual and Rotax- ne manufacturer's maintenance |

| | | ROTAX 912ULS2-01 S/N 9573013 | | e & |
|-------|---|---|--|------|
| Date: | DATE: March 10, 20 | Date: March Ter. Cut and inspected filter. No abnormal contaminar roshell SPORT PLUS 4 oil. Run engine and checked 1.7.2.3 SIGNED: | nts found. Installed new rotar | no.: |
| | ENGINE <u>RO</u> J | LOG BOOK ENTRY <u>FAX 912ULS2-01</u> S/N 9573013 | | |
| | Tach Hours: 404.4 Engine Total Hours: 404.4 | Date: Apr | ril 05, 2023 | |
| | Install new 825016 oil filter and service with Install 8 new spark plugs p/n DCPR8E Complied with 200 hours carb inspection Completed Tecnam Inspection Document N2 BRP maintenance manual d06117.fm, check I certify that this engine has been inspected i and inspection procedures, and was found to DATE: | 2008/008 in accordance with Tecnam P2008 Mainte all torque limits and found ok. | enance Manual and Rotax- nanufacturer's maintenance | |

| Date: Tach Hou | RO1 | FAX 912ULS2-01 S/N 9573013 | The state of the s | |
|------------------------------|--|--|--|---|
| 9 out 10 | tal Ho | N893G | | |
| Drained engine | il and | Date: Apr d checked for contaminants. None four FPLUS 4 oil. Run engine and checked | il 20, 20- | |
| 625016 filter and | serviced with 3 ate. A | Date: Apr d checked for contaminants. None four FPLUS 4 oil. Run engine and checked | 4 20, 2023 | |
| DATE: Apr | Aeroshell SPOR | PLUS 4 oil, Rup on in None four | nd t | 1 |
| | 2023 | checked | for leaks. None for | - |
| | | SIGNED FORME | A sund. | - |
| | 11.44 | 7 | DH=P3578747 | |
| | The second secon | | | |
| | ROTAY 012 | TIT Co | | |
| Tach Hours: 453.5 | ROTAX 912 S/N 9573 | <u>ULS2-01</u> | | - |
| Engine Total II | | Dod. Br. | | - |
| 825016 filter and serviced a | oved oil filter. Cut and inspected filter | No abnormal contaminants found In I. Run engine and ehecked for leaks N | | - |
| DATE: My 03, 70 | acroshell SPORT PLUS 4 oi | . No abnormal contaminants found In I. Run engine and ehecked for leaks N | stalled new rotax | |
| 93,70 | <u> </u> | SIGNED. | one round. | |
| | The second secon | | 1090g | |
| | | The state of the s | | - |
| | | | | |
| | | | | |

ENGINE LOG BOOK ENTRY Main ROTAX 912ULS2-01 Da: Tach Hours: 501.4 'e & Engine Total Hours: 501.4 Date: May 25, 2023 no.: Install new 825016 oil filter and service with 3 qts. Of Aeroshell SPORT PLUS 4 oil. Install 8 new spark plugs p/n DCPR8E Complied with 200 hours carb inspection Completed Tecnam Inspection Document N2008/608 in accordance with Tecnam P2008 Maintenance Manual and Rotax-BRP maintenance manual d96117.fm, check all torque limits and found ok. I certify that this engine has been inspected in accordance with a 100 hour inspection per the manufacturer's maintenance and inspection procedures, and was found to be in a condition for safe operation. **ROTAX 912ULS2-01** S/N 9573013 Tach Hours: 507.3 Date: June 22, 2023 Engine Total Hours: 507.3 Installed double ignition coil set that runs top Cyl#3 and top Cyl#4. Installed using Rotax Maintenance Manual Heavy Following Chapter 74-20-00 page 9-24. Test ran aircraft OK.

DATE: 100 22, 2023

| Dai | | ROTAX 912ULS2-01 | | - a |
|-----|--|--|---|-----|
| | Tach Hours: 537.3 Engine Total Hours: 537.3 Drained engine oil and removed in a | N893G | Date: July 3, 2023 | |
| | Drained engine oil and removed oil filter. (825016 filter and serviced with 3 qts Aerosl DATE: July 3, 2023 | Cut filter and checked for contaminants the sport of PLUS 4 oil. Run engine at SIGNER. | None found. Installed new Rotax and checked for leaks. None found. | |
| | | | 773436900 | |
| | | DOTAY 0402 | | |
| | Engine Total Hours: 578.6 | ROTAX 912ULS2-01 S/N 9573013 N893G | Date: July 19, 2023 | |
| | Drained engine oil and removed oil filter. Cu 825016 filter and serviced with 3 qts Aeroshe DATE: fy/9, 2023 | | None found. Installed new Rotax I checked for leaks: None found. | - |
| | | SIGNED: | 107738909 | - |

| | ENGINE L | OG BOOK ENTRY | i | |
|------|---|--|----------|--|
| Date | ROTA | DTAX 912ULS2-01 S/N 9573013 | | |
| | Tach Hours: 598.8 | | İ | |
| | Engine Total Hours: 598.8 | Date: August 8, 2023 | | |
| | Install new 825016 oil filter and service with 3 qualitated 8 new spark plugs p/n DCPR8E Complied with 200 hours carb inspection Completed Tecnam Inspection Document N2008/BRP maintenance manual 400147 | 008 in accordance with Tecnam P2008 Maintenance Manual and Rotax- | | |
| | DATE: Ay 8, 2023 | SIGNED: ROTAX CERT##0811200830.39% | | |
| | | | ; | |
| | | ROTAVOIAN | <u> </u> | |
| | 1 acii 1100fg. 638 1 | ROTAX 912ULS2-01 S/N 9573013 | | |
| | Engine Total Hours: 638.1 | Date: August 22, 2023 and inspected filter. No abnormal contaminants found. Installed new rotax SPORT PLUS 4 oil. Run engine and checked for leaks. None found. | | |
| | BAIE: Ay 24 2623 | SIGNED: 33 43690 9 | | |
| | | | - | |

| Engine Total Hours: 648.1 | ROTAX 912ULS2-01 S/N 9573013 N893G | Date: August 25, 2023 | ture & |
|--|--|---|--------|
| Drained engine oil and removed oil filter. Cut f 825016 filter and serviced with 3 qts Acroshell DATE: 425. 2023 | filter and checked for contaminants SPORT PLUS 4 oil. Run engine a SIGNED: | s. None found. Installed new Rotax and checked for leaks. None found. | |
| Tach Hours: 690.2 Engine Total Hours: 690.2 | ROTAX 912ULS2-0 S/N 9573013 N893G | Date: September 05, 2023 | |
| Drained engine oil and serviced with 3 qts DATE: 9/5/2023 | Aeroshell SPORT PLUS 4 oil. Ru <u>SIGNE</u> | n engine and checked for leaks. None found D: Una Africa ASP 38838 | 389 |
| | | | |

| <u>Ma</u> | <u>RO1</u> | ΓAX 912ULS2-01 |
|-----------|---|---|
| L | Tach Hours: 698.3 Engine Total Hours: 698.3 | S/N 9573013 Date: October 25, 2023 |
| | I certify that this engine has been inspected in according procedures, and was found to be in a condition for | 008 in accordance with Tecnam P2008 Maintenance Manual and Rotax-BRP maintenance and ok. |
| | DATE: 10-25-2023 | SIGNED: SESSIFE AFD IA 3578747 |
| | | |
| | Tach Hours: 742.2 Engine Total Hours: 742.2 | OTAX 912ULS2-01 S/N 9573013 Date: November 30, 2023 xhaust system and found weak spring at cyl #4 exhaust ball joint and aust spring |
| | DATE: 11/30/2023 | SIGNED: Page 3578747 |
| | | |
| | | |
| | | |

| Maintenance | | | | |
|-------------|---|-------------------------------------|--------------------------|---|
| | | | | |
| Date: | | ENGINE LOC | BOOK ENTRY 912ULS2-01 | Y |
| | Tach Hours: 772.6 | S/N <u>9</u> | 573013 | Date: December 26, 2023 |
| | Drained engine oil and servi Replaced RH MLG tire. Replaced battery. Replaced RH MLG brake ro | | SPORT PLUS 4. Run en | igine and checked for leaks. None found. $A+04339978$ |
| | DATE: 12/26/23 | or. | SIGNED: (| Shorter Hughes |
| | | | | |
| | | ENGINE LOG B ROTAX 91 S/N 957 | 12ULS2-01 | |
| | Tach Hours: 777.1 Engine Total Hours: 7 | 777.1 | | Date: Jan 02, 2024 |
| | install 8 new spark plugs p/n DC | PR8E, engine test ran ol | | |
| | DATE: 1/2, 02, 2024 | | SIGNED: | \$132 000230.1936 AD3 75-9 |
| | | | | |
| 15 | | | | |

ENGINE LOG BOOK ENTRY ROTAX 912ULS2-01 S/N 9573013

Tach Hours: **796.6** re & Engine Total Hours: 796.6 no.: Date: February 14, 2024 Install new 825016 oil filter and service with 3 qts. Of Aeroshell SPORT PLUS 4 oil. Install 8 new spark plugs p/n DCPR8E Complied with 200 hours carb inspection installed gear box after 600hours inspection, see repair station log Completed Tecnam Inspection Document N2008/008 in accordance with Tecnam P2008 Maintenance Manual and Rotax-I certify that this engine has been inspected in accordance with a 100 hour inspection per the manufacturer's maintenance and inspection procedures, and was found to be in a condition for safe operation. 30-January-2024 N893G 912ULS ESN: 9573013 Hobbs: 796.6 C/W 600-Hour Gear Box Inspection on Gear Box S/N 76209. Installed 3 new spring discs, 2 ring halves, thrust washer and re-shimmed. All work completed I/A/W Rotax M/M. Pertinent details can be found on file @ Lockwood Aviation Repair Under WO14674.
Signature: Keith Hemsher IRMT#410813250202-5610

Maintenar --ROTAX 912ULS2-01 Date: Tach Hours: **820.8** N893G Engine Total Hours: 820.8 Date: March 19, 2024 ure & Drained engine oil and removed oil filter. Cut filter and checked for contaminants. None found. Installed new Rotax 825016 filter and serviced with 3 qts Aeroshell SPORT PLUS 4 oil. Run engine and checked for leaks. None found. e no.: Lark 19, 2024 ROTAX 912ULS2-01 S/N 9573013 Tach Hours: **846.5** Engine Total Hours: 846.5 Engine 10tal flours: **540.5**Drained engine oil and removed oil filter. Cut and inspected filter. No abnormal contaminants found. Installed new rotax 825016 filter and serviced with 3qts aeroshell SPORT PLUS 4 oil. Run engine and checked for leaks. None found. 17

Maintenance rooms

| Date: | Tach Hours: 869.9 Engine Total Hours: 869.9 Drained engine oil and removed oil filter. Cut and inspected filter. No abnormal contaminants found. Installed new rotax 825016 filter and serviced with 3qts aeroshell SPORT PLUS 4 oil. Run engine and checked for leaks. None found. DATE: OX/02/2024 SIGNED: ATP 5578747 |
|--|--|
| Install new 825016 oil filter and sei Completed Tecnam Inspection Doc manual d06117.fm, check all torque Cleaned and treated corresion on re | Engine Total Hours: 887.6 Install new 825016 oil filter and service with 3 qts. Of Aeroshell SPORT PLUS 4 oil. Completed Tecnam Inspection Document N2008/008 in accordance with Tecnam P2008 Maintenance Manual and Rotax-BRP maintenance Cleaned and treated corrosion on redictor and found ok. |
| | I certify that this engine has been inspected in accordance with an annual inspection per the manufacturer's maintenance and inspection procedures, and was found to be in a condition for safe operation. DATE: 07-06-2025 SIGNED: 11-3578747 |
| | |

| ntenan | ce record: | | Signature & Licence no.: |
|--------|---|---|--------------------------|
| | Engine hours: | Work performed: | |
| Date: | TSN' TOO | ENGINE LOG BOOK ENTRY ROTAX 912ULS2-01 | |
| | Tach Hours: 940 . Engine Total Ho | 5/N <u>9313019</u> .5 urs: 940. 5 | Date: May 2, 2025 |
| | Englie Total 22 | all Spark Plugs P/N DCPR8E 4339 | · · · |
| | - Torqued to 15 It. less | rime. | radidan Badge |
| | DATE: OS/2/2 | 5 A/P: 5 | 012653 |
| | | | |
| | | ENGINE LOG BOOK ENTRY ROTAX 912ULS2-01 S/N 9573013 | Date: May 16, 2025 |
| | Tach Hours: 950 Engine Total Hours | 6.9 urs: 956.9 d serviced with 3 qts Aeroshell SPORT PLUS 4. Run en | Tim McAnim AR 4845573 |
| | DATE: 5-16-3 | .5 | AF 98477. |