

# **AIRCRAFT TECHNICAL LOGS**

## **Section 2. RECORD OF INSTALLATIONS & MODIFICATIONS TO AIRCRAFT**

RECORD OF ENGINE WORK

AIRFRAME LOG

- 1. Nationality and Registration N500NA
- 2. Manufacturer's Designation DA40
- 3. Record of
  - (a) Engine Installations
  - (b) Propeller Installations
  - (c) Airworthiness Directives (A/D)
  - (d) Service Bulletins (S/B)
  - (e) Special Inspections (S/I)
  - (f) Modifications (MODS)







SPECIAL INSPECTION

WORK OR INSPECTION

Hartzell Propeller Inc.  
One Propeller Place  
Piqua, OH 45356

Page 1 of 4  
2/9/05

DA40-NST-EASA

INSTRUCTIONS FOR INSTALLATION  
OF A HARTZELL HC-C2YR-1BF/F7495S PROPELLER  
AND A-2295(P) SPINNER ON DIAMOND DA 40 AIRCRAFT

STC SA01850CH

LOG OF REVISIONS

Revision	Revised Pages	Description of Revision	Approved	Date

EASA STC EASA, I.M.A.S. 01644  
dated 30/08/2005



NOTE: All changes are indicated by a black vertical line along the left margin.

Approval / Authority



Date 07. OCT. 2005



# RECORD OF AIRFRAME DIRECTIVES (A/D), SERVICE BULLETINS (S/B),

DETAILS OF




Date: July 07, 2004 S/N: 40.367 REG: N500NA  
HOBBS: 12.6 W/O RO-04-079

*The following SB's and AWD's complied with*  
Garmin SB 0408 – GIA63 Main and Nav. Covers replacement – CW

The maintenance described above has been performed in accordance with the  
applicable standards of airworthiness.

DIAMOND AIRCRAFT INDUSTRIES D.O.T. APPROVAL # 161-93

Signature 

Lic. Or Stamp 