

mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198
Juni 2005

Owner Name MONTECELLO AIR LLC

Address 3450 AIRPORT ROAD
NAPA, CA 94558

Propeller Model MTV-12-B

Blade Model 183-596

Hub Serial No. 170959

Blade Serial No. 1 AIG-66893 Propeller Diameter: 183 cm \pm 0.5 cm

2 AIG-66894 Low Pitch: 11 $^{\circ}$ \pm 0.2 $^{\circ}$ TCI: 72 Month

3 AIG-66895 High Pitch: 30 $^{\circ}$ \pm 1 $^{\circ}$ TBO: 1800 Hrs.

4 / Feathering: / $^{\circ}$ \pm / $^{\circ}$

5 / Reverse: / $^{\circ}$ \pm / $^{\circ}$

6 / at radius station: 68 cm

INSTALLATION HISTORY

Date	Aircraft Model, Registration & Serial No., Tacho or Hobbs-Time
03/03/2018	P2010 11768LT 5/11 064/05 0.0 REWAT 1F.21G.0032 REWAT 7

Propeller

02 April 2021 @ 17:00 Hrs

MT-PROPELLER MTV-12-B

HUB S/N:170959

Tach: 155.1

HOBBS: 155.1

SMOH: 155.1

Propeller was inspected on Lycoming IO-390 C3B6, S/N L-723-80E, installed to airframe N769LN this date. All worked done REFERENCE CFR Part 43 Appendix D; Lycoming IO-390-C Series Maintenance Manual, TECNAM Aircraft Maintenance Manual Doc. No. 2010/101 2nd Edition. Engine run performed; all operations normal.

I certify that this Propeller has been inspected and was determined to be in airworthy condition at this and date only. No warranty to future condition.



David McCallum A&P Mechanic 3222105

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time and date only. No warranty to future condition.



Damon Schmidt A & P Mechanic 3065649 IA

Propeller

31 Dec 2022 @ 17:00 Hrs

MT-PROPELLER MTV-12-B

HUB S/N:170959


Tach: 209.1

HOBBS: 209.1

SMOH: 209.1


Propeller was inspected on Lycoming IO-390 C3B6, S/N L-723-80E, installed to airframe N769LN this date. All worked done REFERENCE CFR Part 43 Appendix D; Lycoming IO-390-C Series Maintenance Manual, TECNAM Aircraft Maintenance Manual Doc. No. 2010/101 2nd Edition. Engine run performed; all operations normal.

I certify that this Propeller has been inspected and was determined to be in airworthy condition at this and date only. No warranty to future condition.



David McCallum A&P Mechanic 3222105

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time and date only. No warranty to future condition.



Damon Schmidt A & P Mechanic 3065649 IA


Propeller

31 December 2023 @ 17:00 Hrs **MT-PROPELLER** MTV-12-B HUB S/N:170959

Tach: 231.1 HOBBS: 231.1 SMOH: 231.1


Propeller was inspected on Lycoming IO-390 C3B6, S/N L-723-80E, installed to airframe N769LN this date. All worked done REFERENCE CFR Part 43Appendix D; Lycoming IO-390-C Series Maintenance Manuel, TECNAM Aircraft Maintenance Manual Doc. No. 2010/101 2nd Edition. Engine run performed; all operations normal.

I certify that this Propeller has been inspected and was determined to be in airworthy condition at this and date only. No warranty to future condition.



David McCallum A&P Mechanic 3222105

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time and date only. No warranty to future condition.



Damon Schmidt A & P Mechanic 3065649 IA

Propeller

15 August 2025 @ 17:00 Hrs

MT-PROPELLER MTV-12-B

HUB S/N:170959


Tach: 326.1

HOBBS: 326.1

SMOH: 326.1


Propeller was inspected on Lycoming IO-390 C3B6, S/N L-723-80E, installed to Airframe N769LN this date. All worked done REFERENCE CFR Part 43 Appendix D; Lycoming IO-390-C Series Maintenance Manual, TECNAM Aircraft Maintenance Manual Doc. No. 2010/101 2nd Edition. . Engine run and test flight performed; all operations normal.

I certify that this Propeller has been inspected and was determined to be in airworthy condition at this and date only. No warranty to future condition.



David McCallum A&P Mechanic 3222105

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time and date only. No warranty to future condition.



Damon Schmidt A & P Mechanic 3065649 IA